



Trajectory Planning


N.SUKAVANAM

DEPARMENT OF MATHEMATICS



Path v/s Trajectory


- Path: A sequence of robot configurations in a particular order without regard to the timing of these configurations.
- Trajectory: It is concerned about when each part of the path must be attained, thus specifying timing.



movements in a path Sequential robot



Trajectory Planning




Cartesian and Joint Trajectory

Consider a two arm manipulator equation:

$$x = L_1 C\theta_1 + L_2 C(\theta_1 + \theta_2)$$

$$y = L_1 S\theta_1 + L_2 S(\theta_1 + \theta_2)$$







$$\theta_2 = \arccos\left(\frac{x^2 + y^2 - L_1^2 - L_2^2}{2L_1L_2}\right)$$

$$\theta_1 = \tan^{-1} \left(\frac{ay - bx}{ax + by} \right)$$

where

$$\frac{a}{b} = \frac{L_1 + L_2 C(\theta_2)}{L_2 S(\theta_2)}$$





x

Cartesian and Joint Trajectory

- If (x(t), y(t)) is given as a vector function of time t, then we can obtain $(\theta_1(t), \theta_2(t))$ as functions of t.
- Here (x(t), y(t)) is called Cartesian Trajectory and $(\theta_1(t), \theta_2(t))$ is called Joint Trajectory.
- For a n-arm manipulator, if the arm-matrix 0T_n is given as a function of t, then it is called the Cartesian Trajectory.
- The corresponding inverse kinematics solution $q(t)=(q_1(t),q_2(t)\ldots q_n(t))$ is called the Joint Trajectory.

Trajectory Planning

Point to point motion

- Teach initial and final points; intermediate path is not critical and is computed by the controller
- Applications: Moving of parts, spot welding, automated loading and unloading of machines; pick-and-place motion

Continuous path motion

- Used when there is a need to follow a complex path through 3-D space, possibly at high speeds (spray painting, welding, polishing)
- Points generally taught by manual lead through with high speed automatic sampling

- Single joint (1 DOF):
 - We Know $\theta(0)$, $\theta(t_f)$
 - We also Know $\dot{\theta}(0)$, $\dot{\theta}(t_f)$
 - Want to find $\theta(t), \dot{\theta}(t), \ddot{\theta}(t)$
 - So we have four Constraints: Lets try a Cubic polynomial

$$\theta(t) = a_0 + a_1 t + a_2 t^2 + a_3 t^3$$

- To determine the coefficients we need to look at our boundary conditions as follows:
 - ✓ Position at t=0
 - ✓ Velocity at t=0
 - ✓ Position at t=final
 - ✓ Velocity at t=final

$$\theta(t) = a_0 + a_1 t + a_2 t^2 + a_3 t^3$$

$$\theta(t) = a_1 + 2a_2t + 3a_3t^2$$

So we can evaluate the coefficients as follows:

$$\theta(0) = a_0$$

$$\dot{\theta}(0) = a_1$$

$$\theta(t_f) = \theta(0) + \dot{\theta}(0).t_f + a_2.t_f^2 + a_3.t_f^3$$

$$\dot{\theta}(t_f) = \dot{\theta}(0) + 2.a_2.t_f + 3.a_3.t_f^2$$

$$a_2 = \frac{3}{t_f^2} \cdot \left(\theta(t_f) - \theta(0)\right) - \frac{2}{t_f} \dot{\theta}(0) - \frac{1}{t_f} \dot{\theta}(t_f)$$

$$a_3 = -\frac{2}{t_f^3} \cdot \left(\theta(t_f) - \theta(0)\right) - \frac{1}{t_f^2} \cdot (\dot{\theta}(t_f) - \dot{\theta}(0))$$



If the initial and final velocity are zero then,

$$a_0 = \theta(0)$$

$$a_1 = 0$$

$$a_2 = \frac{3}{t_f^2} \cdot \left(\theta(t_f) - \theta(0)\right)$$

$$a_3 = -\frac{2}{t_f^3} \cdot \left(\theta(t_f) - \theta(0)\right)$$

So finally, the acceleration is given by:

$$\ddot{\theta}(t) = 2a_2 + 6a_3t$$

$$\ddot{\theta}(t) = \frac{6}{t_f^2} \cdot \left(\theta(t_f) - \theta(0)\right) - \frac{12}{t_f^3} \left(\theta(t_f) - \theta(0)\right).t$$



Quintic Polynomial Trajectory

- Cubic allow us to define the position and velocity at each location in the trajectory but not the acceleration.
- If we also want to specify the acceleration we would need a Quintic or order 5 polynomial.

 $\theta(t) = a_0 + a_1 t + a_2 t^2 + a_3 t^3 + a_4 t^4 + a_5 t^5$

 Use the initial and final positions, velocities and accelerations as our boundary conditions to solve for the coefficients.

Quintic Polynomial Trajectory

$$\begin{bmatrix} \theta_0 \\ \omega_0 \\ \theta_f \\ \omega_f \\ \alpha_f \end{bmatrix} = \begin{bmatrix} 1 & t_0 & t_0^2 & t_0^3 & t_0^4 & t_0^5 \\ 0 & 1 & 2t_0 & 3t_0^2 & 4t_0^3 & 5t_0^4 \\ 0 & 0 & 2 & 6t_0 & 12t_0^2 & 20t_0^3 \\ 1 & t_f & t_f^2 & t_f^3 & t_f^4 & t_f^5 \\ 0 & 1 & 2t_f & 3t_f^2 & 4t_f^3 & 5t_f^4 \\ 0 & 0 & 2 & 6t_f & 12t_f^2 & 20t_f^3 \end{bmatrix} \begin{bmatrix} a_0 \\ a_1 \\ a_2 \\ a_3 \\ a_4 \\ a_5 \end{bmatrix}$$

$$\begin{bmatrix} a_0 \\ a_1 \\ a_2 \\ a_3 \\ a_4 \\ a_5 \end{bmatrix} = \begin{bmatrix} 1 & t_0 & t_0^2 & t_0^3 & t_0^4 & t_0^5 \\ 0 & 1 & 2t_0 & 3t_0^2 & 4t_0^3 & 5t_0^4 \\ 0 & 0 & 2 & 6t_0 & 12t_0^2 & 20t_0^3 \\ 1 & t_f & t_f^2 & t_f^3 & t_f^4 & t_f^5 \\ 0 & 1 & 2t_f & 3t_f^2 & 4t_f^3 & 5t_f^4 \\ 0 & 0 & 2 & 6t_f & 12t_f^2 & 20t_f^3 \end{bmatrix}^{-1} \begin{bmatrix} \theta_0 \\ \omega_0 \\ \alpha_0 \\ \theta_f \\ \omega_f \\ \alpha_f \end{bmatrix}$$



Example

Consider a SCARA Robot manipulator:

The arm matrix

$${}^{0}T_{4} = \begin{bmatrix} C_{1-2-4} & S_{1-2-4} & 0 & a_{1}C_{1} + a_{2}C_{1-2} \\ S_{1-2-4} & -C_{1-2-4} & 0 & a_{1}S_{1} + a_{2}S_{1-2} \\ 0 & 0 & -1 & d_{1} - d_{3} - d_{4} \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$OA = d_{1} = 10$$

$$AB = a_{1} = 5$$

$$BC = d_{2} = 3$$

$$CE = d_{3}(variable)$$

$$EF = d_{4} = 4$$



Example

If

$$T(0) = \begin{bmatrix} \frac{1}{\sqrt{2}} & \frac{1}{\sqrt{2}} & 0 & 3\\ \frac{1}{\sqrt{2}} & -\frac{1}{\sqrt{2}} & 0 & 4\\ 0 & 0 & -1 & 2\\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$\frac{DT}{dt}(0) = 0_{4\times4}$$

$$T(0) = \begin{bmatrix} 0 & 1 & 0 & 0 \\ 1 & 0 & 0 & 5 \\ 0 & 0 & -1 & 1 \\ 0 & 0 & 0 & 1 \end{bmatrix}$$

$$\frac{DT}{dt}(10) = 0_{4\times4}$$

Example

Let

$$T(t) = A_0 + A_1 t + A_2 t^2 + A_3 t^3$$

$$\Rightarrow T(0) = A_0, \frac{dT}{dt}(0) = A_1 = 0$$

$$T(10) = A_0 + 10.A_1 + 100.A_2 + 1000.A_3$$

$$\dot{T}(10) = A_1 + 20.A_2 + 300.A_3$$

$$T(0) = T_0 = A_0 \frac{dT}{dt} = T_1 = A_1$$

Thanks!

