


Tinker board loT를 위한 최선의 엣지 단말기




Hangeoil Jeon <u>- hands9998@coit.co.kr</u> Seo heui Bae - suhidahi@naver.com Beomseok Park – baam.park.95@gmail.com

Andorid 한글화





















```
Microsoft Windows [Version 10.0.19044.1826]
(c) Microsoft Corporation. All rights reserved.

C:\Users\hands>adb devices


* daemon not running; starting now at tcp:5037

* daemon started successfully
List of devices attached
JY3TOZLXE7 device

C:\Users\hands>adb root
restarting adbd as root

C:\Users\hands>adb shell pm grant jp.co.c_lis.ccl.morelocale android.permission.CHANGE_CONFIGURATION
```

- 1. ADB 연결 확인
- 2. ADB root로 루트 권한
- 3. adb shell pm grant jp.co.c_lis.ccl.morelocale android.permission.CHANGE_CONFIGURATION



- 1. 한국어 세팅 후
- 2. ADB reboot으로 적용

Andorid 한글화 – 한글 키보드 설치

