



Fault Scenario: Magnetometer Bias



ESKF-Smoother Disagreement



Redundant Estimator Mode

