


1

2


3

4

## USB\_TYPE A





## 5V-3.3 LDO



J1 for current test

J1 default jumper on



A

A

B

B

C

C

D

D

