

LOCKOUT TAGOUT PROCEDURE

Document ID: LOTO-001

Purpose:

To ensure equipment is safely isolated before maintenance activities.

Procedure:

1. Notify affected personnel.
2. Shut down equipment.
3. Isolate energy sources.
4. Apply lock devices.
5. Apply warning tags.
6. Verify isolation.
7. Perform maintenance.
8. Remove locks and restore operation.

Responsibility:

Maintenance Department

Revision: 1.0

END OF DOCUMENT