

D_1 (Next State Q_1)

		Q_0
		0 1
Q_1	0	f_2 0
	1	f'_1 1

D_0 (Next State Q_0)

		Q_0
		0 1
Q_1	0	f_2 at'_1
	1	f_1 at'_2