```
<?xml version="1.0" encoding="UTF-8" standalone="ves" ?>
<UxAS EntityID="1000" FormatVersion="1.0" EntityType="Aircraft">
    <Bridge Type="Lmcp0bjectNetworkZeroMgZyreBridge" NetworkDevice="enx281878b9065a">
       <SubscribeToExternalMessage MessageType="uxas.messages.task.AssignmentCoordination"/>
    </Bridge>
    <Service Type="TaskManagerService"/>
    <Service Type="SendMessagesService" PathToMessageFiles="../MessagesToSend/">
       <Message MessageFileName="AirVehicleConfiguration V1000.xml" SendTime ms="50"/>
       <Message MessageFileName="AirVehicleConfiguration V2000.xml" SendTime ms="60"/>
   </Service>
    <Service Type="MessageLoggerDataService" FilesPerSubDirectory="10000" LogFileName="testfile">
       <LogMessage MessageType="uxas" NumberMessagesToSkip="0"/>
   </Service>
</UXAS>
```