Evaluate statistics of stresses

```
function [msig u,stdDev sig u,mu u,stdDev u u] = GetStresses(X)
% Input - X
                     - Design Variable;
% Output - mSig u - mean Normal stresses on nodal location
         stdDev_sig_u - standard deviation of normal stresses on nodes
         mu_u - mean displacement on nodal location
용
          stdDev u u - standard deviation of displacement on nodes
Mass = 500; % total operational mass of aircraft
Nnodes = length(X)/2; % Number of nodes
L = 7.5; %m - Semi Length of spar
x = (0:L/(Nnodes-1):L)'; % discretize the length
E = 70e9; % 70 GPa Young's modulus
% Calculate Iyy
Iyy = Calc_Iyy(X,Nnodes);
zmax = X(1:2:end);
force_nominal = Calc_force(x,Mass,L);
[msig_u,stdDev_sig_u,mu_u,stdDev_u_u] = uncertainity(zmax,force_nominal,Iyy,E,L,Nnodes-1);
end
```

Published with MATLAB® R2021a