

P.O. Box 2442 Midland, TX 79702 (432) 279-0403

Bill To

Texas Pacific Water Resources 15 Smith Rd, Suite 2012 Midland, TX 79705

Invoice #	Date	
24-0238	10/30/2024	

	PO Number	Contact Person	Project Name		
	99031W	Jacob	Horned Frog 23-13		
Des	crintion		Quantity	Rate	Amount

Description	Quantity	Rate	Amount
October 29, 2024 Customer called about water well not working properly. Drive to location and set up. Motor and wire down hole need to be replaced. Less than 2 months old. Customer requested camera be run down hole. Labor 3 man crew with truck, 25T pump hoist, tongs with support truck	9	295.00	2,655.00
October 30, 2024 Drive to location and set up. Run camera down hole. No signs of what caused equipment to fail. Provide and install new 60HP Motor and 500' #2 wire. Set new motor and existing pump end down hole. Leave well working properly. Run Well Camera Motor 60HP 6 inch (480V 3 phase)	1	500.00 13,257.22	500.00 13,257.22
#2 AWG flat wire Deep water splice kit 2 inch waterproof pipe wrap tape Check value, Break off plug, Knockout Labor 3 man crew with truck, 25T pump hoist, tongs with support truck	500 1 10 1 11.5	14.78 136.23 15.68 106.40 295.00	7,390.00 136.23 156.80 106.40 3,392.50
			·

Thank you for your business.	Sales Tax (6.25%)	\$1,724.63
Regulated by the Texas Department of Licensing and Regulation P.O.Box 12157 Austin, Texas 78711 1-800-803-9202, 512-463-7880 www.tdlr.texas.gov TDLR Water Well Driller/Master Pump Installer		
Matthew Davis License #59820	Total	\$29,318.78