1. Description


1.1. Project

Project Name	Nucleo-F446_DAC_Test5
Board Name	NUCLEO-F446RE
Generated with:	STM32CubeMX 5.1.0
Date	03/30/2019

1.2. MCU

MCU Series	STM32F4
MCU Line	STM32F446
MCU name	STM32F446RETx
MCU Package	LQFP64
MCU Pin number	64

2. Pinout Configuration




3. Pins Configuration

Pin Number LQFP64	Pin Name (function after	Pin Type	Alternate Function(s)	Label
4	reset)	Dawer		
2	VBAT	Power	CDIO EVIIIA	D4 [Dive Diveb Diviteral
	PC13	1/0	GPIO_EXTI13	B1 [Blue PushButton]
3	PC14-OSC32_IN	1/0	RCC_OSC32_IN	
4	PC15-OSC32_OUT	1/0	RCC_OSC32_OUT	
5	PH0-OSC_IN	I/O	RCC_OSC_IN	
6	PH1-OSC_OUT	I/O	RCC_OSC_OUT	
7	NRST	Reset		
12	VSSA	Power		
13	VDDA	Power		
16	PA2	I/O	USART2_TX	USART_TX
17	PA3	I/O	USART2_RX	USART_RX
18	VSS	Power		
19	VDD	Power		
20	PA4	I/O	DAC_OUT1	
21	PA5	I/O	DAC_OUT2	
30	VCAP_1	Power		
31	VSS	Power		
32	VDD	Power		
46	PA13	I/O	SYS_JTMS-SWDIO	TMS
47	VSS	Power		
48	VDD	Power		
49	PA14	I/O	SYS_JTCK-SWCLK	TCK
55	PB3 *	I/O	SYS_JTDO-SWO	SWO
60	BOOT0	Boot		
63	VSS	Power		
64	VDD	Power		

^{*} The pin is affected with a peripheral function but no peripheral mode is activated

4. Clock Tree Configuration



Page 4

5. Software Project

5.1. Project Settings

Name	Value		
Project Name	Nucleo-F446_DAC_Test5		
Project Folder	D:\Users\gizmo\Documents\workspace\Nucleo-F446_DAC_Test5		
Toolchain / IDE	SW4STM32		
Firmware Package Name and Version	STM32Cube FW_F4 V1.24.0		

5.2. Code Generation Settings

Name	Value		
STM32Cube Firmware Library Package	Copy only the necessary library files		
Generate peripheral initialization as a pair of '.c/.h' files	No		
Backup previously generated files when re-generating	No		
Delete previously generated files when not re-generated	Yes		
Set all free pins as analog (to optimize the power	No		
consumption)			

6. Power Consumption Calculator report

6.1. Microcontroller Selection

Series	STM32F4
Line	STM32F446
мси	STM32F446RETx
Datasheet	027107_Rev6

6.2. Parameter Selection

Temperature	25
Vdd	null

7. IPs and Middleware Configuration 7.1. DAC

mode: OUT1 Configuration mode: OUT2 Configuration 7.1.1. Parameter Settings:

DAC Out1 Settings:

Output Buffer Enable
Trigger None

DAC Out2 Settings:

Output Buffer Enable
Trigger None

7.2. RCC

High Speed Clock (HSE): Crystal/Ceramic Resonator Low Speed Clock (LSE): Crystal/Ceramic Resonator

7.2.1. Parameter Settings:

System Parameters:

VDD voltage (V) 3.3
Instruction Cache Enabled
Prefetch Buffer Enabled
Data Cache Enabled

Flash Latency(WS) 5 WS (6 CPU cycle)

RCC Parameters:

HSI Calibration Value 16

TIM Prescaler Selection Disabled

HSE Startup Timout Value (ms) 100

LSE Startup Timout Value (ms) 5000

Power Parameters:

Power Regulator Voltage Scale Power Regulator Voltage Scale 1

Power Over Drive Enabled

7.3. SYS

Debug: Serial Wire

Timebase Source: SysTick

7.4. USART2

Mode: Asynchronous

7.4.1. Parameter Settings:

Basic Parameters:

Baud Rate 115200

Word Length 8 Bits (including Parity)

Parity None Stop Bits 1

Advanced Parameters:

Data Direction Receive and Transmit

Over Sampling 16 Samples

^{*} User modified value

8. System Configuration

8.1. GPIO configuration

IP	Pin	Signal	GPIO mode	GPIO pull/up pull down	Max Speed	User Label
DAC	PA4	DAC_OUT1	Analog mode	No pull-up and no pull-down	n/a	
	PA5	DAC_OUT2	Analog mode	No pull-up and no pull-down	n/a	
RCC	PC14- OSC32_IN	RCC_OSC32_IN	n/a	n/a	n/a	
	PC15- OSC32_OU T	RCC_OSC32_O UT	n/a	n/a	n/a	
	PH0- OSC_IN	RCC_OSC_IN	n/a	n/a	n/a	
	PH1- OSC_OUT	RCC_OSC_OUT	n/a	n/a	n/a	
SYS	PA13	SYS_JTMS- SWDIO	n/a	n/a	n/a	TMS
	PA14	SYS_JTCK- SWCLK	n/a	n/a	n/a	TCK
USART2	PA2	USART2_TX	Alternate Function Push Pull	Pull-up	Very High	USART_TX
	PA3	USART2_RX	Alternate Function Push Pull	Pull-up	Very High	USART_RX
Single Mapped Signals	PB3	SYS_JTDO- SWO	n/a	n/a	n/a	SWO
GPIO	PC13	GPIO_EXTI13	External Interrupt Mode with Falling edge trigger detection	No pull-up and no pull-down	n/a	B1 [Blue PushButton]

8.2. DMA configuration

nothing configured in DMA service

8.3. NVIC configuration

Interrupt Table	Enable	Preenmption Priority	SubPriority	
Non maskable interrupt	true	0	0	
Hard fault interrupt	true	0	0	
Memory management fault	true	0	0	
Pre-fetch fault, memory access fault	true	0	0	
Undefined instruction or illegal state	true	0	0	
System service call via SWI instruction	true	0	0	
Debug monitor	true	0	0	
Pendable request for system service	true	0	0	
System tick timer	true	0	0	
PVD interrupt through EXTI line 16	unused			
Flash global interrupt	unused			
RCC global interrupt	unused			
USART2 global interrupt	unused			
EXTI line[15:10] interrupts	unused			
TIM6 global interrupt and DAC1, DAC2 underrun error interrupts	unused			
FPU global interrupt	unused			

^{*} User modified value

9. Software Pack Report