




Schematic is not equal to heltec-ht62-esp32c3-sx1262; Idea was to match the HT-CT62
However, MOSI and SCK are swapped and GPIO8 is also used by the blue LED
Choice of GPIO8 is not smart: Is used by the onboard blue LED

This can be corrected when building the firmware but stock image cannot be used

TITLE: ESP32-C3 Supermini to DX-LR-30		REV: 1.0
EasyEDA	Company: rzident	Sheet: 1/1
	Date: 2026-05-17 Drawn By: rzident	