




Copper Alloy Above 40 C Hysteresis Loop (20 Ms Segment)



Copper Alloy At 10 C Hysteresis Loop (20 Ms Segment)



Mild Steel Hysteresis Loop (20 Ms Segment)



Transformer Iron Hysteresis Loop (20 Ms Segment)

