

One joint resistance does not explain all coils

