

BridgeAI Inspection Report

Generated: 2026-05-31 00:24:55 UTC

1. Inspection Summary

Bridge Name:	New Bridge Inspection
Inspection ID:	INS-27
AI Severity:	Critical
Risk Level:	99/100
Urgency:	Immediate
Inspection Priority:	Critical
Total Crack Length:	460.28 px
Max Crack Width:	3.74 px
Crack Density:	0.09 clusters
Area Percentage:	0.1195%

2. Executive Summary

The detected crack exceeds safety thresholds for primary support nodes.

3. AI Engineering Recommendations

Maintenance Strategy:

Immediate Structural Reinforcement & Epoxy Injection

Predictive Analysis:

High probability of crack propagation within 3-6 months due to thermal cycling.

Safety Warning:

CRITICAL: Significant structural compromise detected. Immediate load reduction recommended.

Disclaimer: This report is AI-generated for engineering assistance and should be verified by a licensed professional.