

# BridgeAI Inspection Report

Generated: 2026-05-26 08:04:42 UTC

## 1. Inspection Summary

|                     |                       |
|---------------------|-----------------------|
| Bridge Name:        | New Bridge Inspection |
| Inspection ID:      | INS-19                |
| AI Severity:        | Critical              |
| Confidence Score:   | 30.42%                |
| Risk Level:         | 46/100                |
| Total Crack Length: | 2119.72 px            |
| Max Crack Width:    | 258.37 px             |
| Crack Density:      | 0.04 clusters         |
| Area Percentage:    | 98.9736%              |

## 2. AI Engineering Recommendations

**Maintenance Strategy:**

Immediate Structural Reinforcement & Epoxy Injection

**Predictive Analysis:**

High probability of crack propagation within 3-6 months due to thermal cycling.

**Safety Warning:**

CRITICAL: Significant structural compromise detected. Immediate load reduction recommended.

*Disclaimer: This report is AI-generated for engineering assistance and should be verified by a licensed professional.*