SET PINZ AS INPUT SET PINZ AS OUTPUT LOOP &

IF (PINZ IS ON) &
TURN PINS ON "1"

3 ELSE \$

TURN PIN 3 OFF "O"

3

LPC_GP101 -> FIDDR 8= (1 << 2) LPC_GP101 -> FIDDR 1= (1 << 3)

WHICE (TRUE/1) {

IF (LPL-GPIOX -> FIDDIR & (1<<2)) {

LPC-GPIOX-> FIDSET = (1<<3);

3 ELSE &

LPC_GP10X->FOCUR = (1<< 3);