
When an Error Message pops up

During the BWA Measurement



01 In case of dry skin

The BWA is designed to stop the measurement if the contact resistance is high to ensure the precision and accuracy of the measurement. Subjects with excessively dry skin have high contact resistance. Therefore, if the skin is not moisturized enough, high contact resistance may affect the result.

02 In case of wrong attachment position

If the BWA logo on the clamp is attached in the wrong position or direction, the measurement may cease. Check the attachment position again.

03 In case the electrodes are not fully attached to the skin

If the measurement ceases again after the above options, the electrodes might be unattached from the skin. Especially for the ankle, the bone structure is large and complicated, so at least the upper part of the electrode must be in touch with the skin.

CHECK LIST

The solution to Prevent BWA Measurement from Stopping


01 If the subject lies down for measurement, attach the clamp electrodes before input of the personal information.

02 Press down on the InBody tissue to make sure that the moisture is fully absorbed in the skin, especially above and below the palm, and the inside and outside of the ankle.





03 Apply ECG gel or moisturizing cream before attachment if there is excessive exfoliate due to dryness or if there is a lot of hair.
※Apply the gel only on the area within the red dotted line, and do not apply on skin where the top and bottom electrodes meet.



<Back of the hand & Wrist > <Inner & Outer side of the Ankle>

04 When attaching the foot electrodes, they must be fully attached to the skin, or at least the upper part of the electrode must be in touch with the skin.

