1900348307/13/BR/5000

MOTOR VEHICLE VALUATION & INSPECTION

CERTIFICATE

TECHNICAL INSPECTION

This is to certify that the vehicle

Registration Number	:	90UN198K
Vehicle Make	:	TOYOTA L/CRUISER
Vehicle Model	:	HZJ76
Chassis Number	:	JTEEB71J707026906
Year of Manufacture	:	2014

Has been inspected and assessed by AA of Kenya and valued at

KES. 2,550,000 (Kenya Shillings TWO MILLION FIVE HUNDRED FIFTY THOUSAND ONLY)

A detailed report is attached.

Valuation & Inspection Manager

Valuation & Inspection Officer

Date : 25/08/2025

FEDERATION INTERNATIONALE DE L'AUTOMOBILE

INSPIRING MOBILITY

1900348307/13/BR/5000

MOTOR VEHICLE VALUATION & INSPECTION

TECHNICAL INSPECTION

CLIENT DETAILS

Client Name	: UNICEF KCO
Email	: unicef@gmail.com
Insured Tel	: 0700609050

VEHICLE DETAILS

Reg. No	: 90UN198K
Vehicle Make	: TOYOTA L/CRUISER
Vehicle Model Number	: HZJ76 (4164 CC)
Type	: HARD TOP
Odometer	: 210824 KM
Colour	: WHITE
YOM	: 2014
Date Of 1st Reg	: 16-SEP-2015
Chassis No	: JTEEB71J707026906
Engine No	: 1HZ-0807722

Issuing Office	: Kasarani
Receipt No	: PSINV343932

Date : 25/08/2025

Valuation & Inspection Manager

Valuation & Inspection Officer

Body Condition	: Good
Electricals	: Good
Engine Area	: Good
Transmission System	: Good
Steering System	: Good
Braking System	: Good
General Condition	: SERVICEABLE PAINT FADES AND SCRATCHES NOTED ON VARIOUS BODY WINDSCREEN CRACKED.

Tyre Condition & Depth

FR	: Good
FL	: Good
RR	: Good
RL	: Good
Spare	: Good
Extra Tyres	: NONE

Braking System	: Good
Extras	: AIR CONDITIONER POWER STEERING,FRONT BULL BAR,AIR SNORKEL,ROOF RACK SIDE STEPS,DUAL SRS AIRBAGS RADIO CD PLAYER.

Remarks

serviceable paint fades and scratches noted on various body windscreen cracked.

Examiners prices (Kshs) of separately insurable items

Windscreen: 40,000 **AntiTheft:** Not-Fitted **Radio/CD:** 20,000

Examiner's Opinion (Kshs)	: 2,550,000 (Kenya Shillings TWO MILLION FIVE HUNDRED FIFTY THOUSAND ONLY)
Duty Free Value (Kshs)	: 1,920,000 (Kenya Shillings ONE MILLION NINE HUNDRED TWENTY THOUSAND ONLY)

Date : 25/08/2025

Valuation & Inspection Manager *Valuation & Inspection Officer*

Photos

FRONT

(-1.2290953, 36.8201488,)

REAR

(-1.2290953, 36.8201488,)

ENGINE

(-1.2290953, 36.8201488, Mon Aug 25 2025 15:09:16 GMT +0300 (East Africa Time))

CHASIS

(-1.2315787, 36.8164476, Mon Aug 25 2025 15:08:43 GMT +0300 (East Africa Time))

ODOMETER



(-1.2290953, 36.8201488, Mon Aug 25 2025 15:05:02 GMT +0300 (East Africa Time))

DASHBOARD

Date : 25/08/2025

Valuation & Inspection Manager

Valuation & Inspection Officer

Photos (continued)

LOGBOOK

Chassis/Frame:JTEEB71J-707026906
Make: TOYOTA
Model: LAND CRUISER
Type: Motor vehicle
Fuel: Diesel
Man.Year: 2014
Rating: 4164
Engine No: 1HZ-0807722
Color: WHITE
Reg. Date: 16-JUL-15
Gross weight:
Duty: Nil
Number of previous owners: 0
For official use only:-
Authorising Signature and official seal
Tare weight: 2180
Tax class: Private
Axles: 2
Load capacity(kg):
Previous Reg. country:
NOT TRANSFERABLE WITHOUT CUSTOMS AUTHORITY
Registered Owner(s)
Pin: P051101958R
Name: UNITED NATIONS CHILDRENS FUND KENYA COUNTRY OFFICE
Box No.: 44145
Code: 00100
Town: NAIROBI

INSURANCE STICKER



(-1.2290953, 36.8201488, Mon Aug 25 2025 15:10:44 GMT+0300 (East Africa Time))

Date : 25/08/2025

Valuation & Inspection Manager

Valuation & Inspection Officer

Terms & Conditions

The examiners take every care & precaution during inspections but the AA cannot accept responsibility for claims arising as a result of latent defects or matters of opinion

The AA reserves the right to decline to examine or to report on any vehicle not of standard production or one which has not been in regular road use.

The examination to which this report refers is external only and does not involve dismantling or disturbing any structure, assembly, component or internal mechanism. Only limited road test is undertaken.

Parts that are excessively contaminated by oil or dirt may not be properly examined.

The assessed value given after a brief examination and road test is consistent with the age and condition of the said vehicle. However, it must beemphasized that it bears no relationship with any agreement between buyer and seller which is entirely dependent on willingness of the two parties to a greater or lesser degree.

Where it is stated in the inspection report that some information was suppliedby AA a third party, the AA Kenya

Vehicles over 5 years and those that have been subjected to abnormal use may have serious defects which may not be detected by external examination. The AA will not be held responsible for liability arising out of this.
No indication can be given of the availability of the spare parts for the particular make or model of a vehicle.

will not be held responsible for the reliability of the information if found to be incorrect.
Re-examination after repairs will be carried out at a fee.
The assessed value is based on the date of first registration and the odometer reading being genuine.