Automobile Association of Kenya
AA House, Airport North Road
P O Box 40087 00100 Nairobi.

T. 020 261 2300/11
C. 0722 205 106 /0733 620 966
E. aak@aakenya.co.ke
www.aakenya.co.ke

PRE-INSURANCE VEHICLE INSPECTION REPORT

ISSUING OFFICE:	**AIG**	RECEIPT NO.:	**AIG002408**
INSURED:	**WILLIAM KIBIWOTT CHESIRE**	POLICY NO:	**012071618**
INSURED TEL:	**0721 761 669**	EMAIL:	**wkchesire@gmail.com**
INSURER:	**AIG KENYA INSURANCE COMPANY LTD**	INS BROKER AGENT:	**TBA**

A Brief Examination and Road Test have been carried out on the following vehicle and the findings are as follows:-

Reg. No:	**KCV111M**	Make:	**MERCEDES BENZ E250 2WD (1990 CC)**	Type:	**SALOON**
Odo. Reading:	**52137 KMS**	Color:	**BLUE**	Year of Man:	**2014**
Date of First Reg:	**04/07/2019**	Chassis No:	**WDD2120362A959876**	Engine No:	**274-92030132535**

Body Condition:	**GOOD, NO MAJOR DAMAGES NOTED**
General Condition:	**GOOD**
Electricals:	**FUNCTIONAL**
Engine Area:	**SOUND, NO MAJOR DEFECTS NOTED**
Transmission System:	**SOUND, NO MAJOR DEFECTS NOTED**
Steering System:	**SOUND WITH GOOD STEERING GEOMETRY**
Suspension System:	**SOUND, NO MAJOR DEFECTS NOTED**
Tyres Condition & Depth in mm:	**FR :** FAIR TREAD DEPTH **RR :** GOOD TREAD DEPTH **Spare :** GOOD TREAD DEPTH **FL :** FAIR TREAD DEPTH **RL :** GOOD TREAD DEPTH **Others:** N/A
Braking System:	**GOOD WITH SATISFACTORY STOPPING DISTANCE**
Extras:	**INBUILT ALARM, ALLOY RIMS, REAR CAMERA, 3RD BRAKE LIGHT, LINEBOARD MOULD COVERS, SIDE MIRROR INDICATORS AND CAMERAS, XENON LIGHTS, FRONT CAMERA, PARKTRONICS, POWER MIRRORS, POWER WINDOWS, POWER STEERING, ABS, AIR CONDITIONER, CENTRAL LOCKING, 11 SRS AIRBAGS, INBUILT TV SCREEN AND RADIO/CD/DVD PLAYER WITH BLUETOOTH CONNECTIVITY, MULTIFUNCTIONAL STEERING WHEEL, FLAPPY PEDDLE SHIFTERS, CRUISE CONTROL, LEATHER SEATS, FRONT SEAT WARMERS AND POWER ADJUSTERS, INTERIOR WOOD TRIMS, TELESCOPIC STEERING, SMART IGNITION, KEYLESS ENTRY, TURBO INTERCOOLER**
Remarks:	**EX JAPAN**

Estimate Prices (Kshs) of Separately insurable items:-

Windscreen: **120,000** Anti Theft Device: **INBUILT** R/Cassete/ CD Player: **50,000**

Examiner's Opinion: Kshs **4,950,000 (Four Million Nine Hundred Fifty Thousand)**

(The Examiner's Opinion is for Insurance use only)

Signed: Date: **25/06/2020**

For and behalf of AA of Kenya

1177967/B / 141 / INS / 400

z

GRADING DESCRIPTION

Sound: Good mechanical condition with no obvious defects noted **Good:** A drivable vehicle needing no or only minor work to be sound.
Servicable: In satisfactory working condition, strong and functional. May need some restoration work to be good. **Restorable:** Needs complete restoration of a number of parts (body, chasis, Engine interior etc). The car needs almost everything. **Parts Car:** May not be running. It is weathered, wrecked and/or stripped to the point of being usefull primarily for parts, it is rusty and some parts are missing.

Printed on: 16/09/2025 05:23:36

AAK IS ISO/IEC 17020:2012 ACCREDITED

TERMS AND CONDITIONS

-The examiners take every care & precaution during inspections but the AA cannot accept responsibility for claims arising as a result of latent defects or matters of opinion.
-The AA reserves the right to decline to examine or to report on any vehicle not of standard production or one which has not been in regular road use.
-The examination to which this report refers is external only and does not involve dismantling or disturbing any structure, assembly, component or internal mechanism.
-Only limited road test is undertaken.
-Vehicles over 5 years and those that have been subjected to abnormal use may have serious defects which may not be detected by external examination. The AA will not be held responsible for liability arising out of this.
-No indication can be given of the availability of the spare parts for the particular make or model of a vehicle.
-Parts that are excessively contaminated by oil or dirt may not be properly examined.
-The assessed value given after a brief examination and road test is consistent with the age and condition of the said vehicle. However it must be emphasized that it bears no relationship with any agreement between buyer and seller which is entirely dependent on willingness of the two parties to a greater or lesser degree.
-Where it is stated in the inspection report that some information was supplied to the AA by a third party, the AA Kenya will not be held responsible for the reliability of the information if found to be incorrect.
-Re-examination after repairs will be carried out at a fee.
-The assessed value is based on the date of first registration and the odometer reading being genuine.

Front



Rear



Engine

Chassis




Milleage




Logbook




Letter



Pin



ID



Other Images





Others



KCV111M 1177967/B AL WIL