

DETAIL

Shipment #: LBB00828

Total : \$0.00

Status: Awaiting

PhonePartsUSA.com LLC

5145 South Arville Street Suite A Las Vegas NV 89118

Customer

TRENETY Cellphone Repair 4247 S HOPKINS AVE STE A TITUSVILLE, Florida 32780

Other Details

Tracking # N/A

Payment: store_credit Procedure: Return

Customer Data Receiving Data

LCD Type	OEM	Non-OEM	Total	Price	LCD Type	Total
iPhone 4 4S	-	0.50 x 1	1	\$0.50	iPhone 4 4S	0
iPhone 5	8.50 x 3	4.00 x 1	4	\$29.50	iPhone 5	0
iPhone 5C	8.50 x 1	4.00 x 4	5	\$24.50	iPhone 5C	0
iPhone 5S/SE	12.00 x 4	4.00 x 3	7	\$60.00	iPhone 5S/SE	0
iPhone 6	29.00 x 7	18.00 x 2	9	\$239.00	iPhone 6	0
iPhone 6 Plus	44.00 x 1	-	1	\$44.00	iPhone 6 Plus	0
iPhone 6S	60.00 x 1	-	1	\$60.00	iPhone 6S	0
iPad Mini 1/2 iC Chip	3.00 x 4	-	4	\$12.00	iPad Mini 1/2 iC Chip	0
Galaxy S5	37.00 x 1	-	1	\$37.00	Galaxy S5	0
			33	\$506.50		0

QC Data Admin Data

LCD Type	OEM	Non-OEM	Rejected	Total	LCD Type	OEM	Non-OEM	Total
iPhone 4 4S			0	0	iPhone 4 4S	0 x 1.50	0 x 0.50	\$0.00
iPhone 5			0	0	iPhone 5	0 x 8.50	0 x 4.00	\$0.00
iPhone 5C			0	0	iPhone 5C	0 x 8.50	0 x 4.00	\$0.00
iPhone 5S/SE			0	0	iPhone 5S/SE	0 x 12.00	0 x 4.00	\$0.00
iPhone 6			0	0	iPhone 6	0 x 29.00	0 x 18.00	\$0.00
iPhone 6 Plus			0	0	iPhone 6 Plus	0 x 44.00	0 x 20.00	\$0.00
iPhone 6S			0	0	iPhone 6S	0 x 60.00	0 x 25.00	\$0.00
iPad Mini 1/2 iC Chip			0	0	iPad Mini 1/2 iC Chip	0 x 3.00	0 x 0.00	\$0.00
Galaxy S5			0	0	Galaxy S5	0 x 37.00	0 x 15.00	\$0.00
				0				\$0.00