

# DFTAIL

## PhonePartsUSA.com LLC

5145 South Arville Street Suite A Las Vegas NV 89118

Customer

TRENETY Cellphone Repair 4247 S HOPKINS AVE STE A TITUSVILLE, Florida 32780 Shipment #: LBB00828

Total : \$373.00 Status: QC Completed

#### Other Details

Tracking # 9622013690007915358100790528374427

Payment: store\_credit Procedure: Return

#### Customer Data Receiving Data

LCD Type	OEM	Non-OEM	Total	Price	LCD Type	Total
iPhone 4 4S	-	0.50 x 1	1	\$0.50	iPhone 4 4S	1
iPhone 5	8.50 x 3	4.00 x 1	4	\$29.50	iPhone 5	8
iPhone 5C	8.50 x 1	4.00 x 4	5	\$24.50	iPhone 5C	5
iPhone 5S/SE	12.00 x 4	4.00 x 3	7	\$60.00	iPhone 5S/SE	7
iPhone 6	29.00 x 7	18.00 x 2	9	\$239.00	iPhone 6	12
iPhone 6 Plus	44.00 x 1	-	1	\$44.00	iPhone 6 Plus	1
iPhone 6S	60.00 x 1	-	1	\$60.00	iPhone 6S	0
iPad Mini 1/2 iC Chip	3.00 x 4	-	4	\$12.00	iPad Mini 1/2 iC Chip	4
Galaxy S5	37.00 x 1	-	1	\$37.00	Galaxy S5	1
-			33	\$506.50	•	39

### QC Data Admin Data

LCD Type	OEM	Non-OEM	Rejected	Total	LCD Type	OEM	Non-OEM	Total
iPhone 4 4S	0	1	0	1	iPhone 4 4S	0 x 1.50	1 x 0.50	\$0.50
iPhone 5	1	4	3	8	iPhone 5	1 x 8.50	4 x 4.00	\$24.50
iPhone 5C	0	1	4	5	iPhone 5C	0 x 8.50	1 x 4.00	\$4.00
iPhone 5S/SE	1	3	3	7	iPhone 5S/SE	1 x 12.00	3 x 4.00	\$24.00
iPhone 6	10	1	1	12	iPhone 6	10 x 29.00	1 x 18.00	\$308.00
iPhone 6 Plus	0	0	1	1	iPhone 6 Plus	0 x 44.00	0 x 20.00	\$0.00
iPhone 6S	0	0	0	0	iPhone 6S	0 x 60.00	0 x 25.00	\$0.00
iPad Mini 1/2 iC Chip	4	0	0	4	iPad Mini 1/2 iC Chip	4 x 3.00	0 x 0.00	\$12.00
Galaxy S5	0	0	1	1	Galaxy S5	0 x 37.00	0 x 15.00	\$0.00
,				39	•			\$373.00