

INVOICE

PhonePartsUSA.com LLC

5145 South Arville Street Suite A Las Vegas NV 89118 U.S.A

Invoice Total

519278

\$510.80

30 May 2017

Channel: Web

Free Shipping

Invoice Date: Bill To Payment Method: Cash / Credit Kracked Repair

Rajens Wilson 79 W Main St

Price, Utah, United States 84501

Price, Utan, United States 84501			•
Item Description	Qty	Rate	Amount
APL-001-2090 LCD and Touch Screen Digitizer Assembly for iPhone 5S SE - Black (Premium)	2.00	22.99	45.98
APL-001-2298 iPhone 6S LCD and Touch Screen Digitizer - Economy Plus - Black	5.00	26.99	134.95
APL-001-2299 iPhone 6S LCD and Touch Screen Digitizer - Economy Plus - White	2.00	26.99	53.98
APL-001-2278 LCD and Touch Screen Digitizer for iPhone 7 - Black (Standard)	2.00	39.99	79.98
APL-001-2279 LCD and Touch Screen Digitizer for iPhone 7 - White (Standard)	3.00	39.99	119.97
APL-003-1705 Front Camera Proximity Sensor Replacement for iPhone 7	4.00	12.99	51.96
APL-001-0730 LCD and Touch Screen Digitizer Assembly for iPhone 5S (Economy Plus) - Black	2.00	11.99	23.98
	Sub Total		\$510.80
	Shipping Tax / Extra		\$0.00
			\$0.00
		Total	\$510.80