

## DFTAIL

PhonePartsUSA.com LLC

5145 South Arville Street Suite A Las Vegas NV 89118 Total : \$10.50 Status: Completed

Shipment #: LBB00575

Customer

Bill Underwood 4811 pioneer rd Mchenry, Illinois 60051 Other Details

Tracking # 420891189500113598676069185023

Payment: cash Procedure: Dispose

Customer Data Receiving Data

| LCD Type  | OEM       | Non-OEM | Total | Price   | LCD Type  | Total |
|-----------|-----------|---------|-------|---------|-----------|-------|
| iPhone 5  | 16.00 x 1 | -       | 1     | \$16.00 | iPhone 5  | 1     |
| iPhone 5S | 16.00 x 4 | -       | 4     | \$64.00 | iPhone 5S | 2     |
|           |           |         | 5     | \$80.00 | iPhone 5C | 2     |
|           |           |         |       |         |           | 5     |

QC Data Admin Data

| LCD Type  | ОЕМ | Non-OEM | Rejected | Total | LCD Type  | OEM       | Non-OEM  | Total   |
|-----------|-----|---------|----------|-------|-----------|-----------|----------|---------|
| iPhone 5  | 0   | 0       | 1        | 1     | iPhone 5  | 0 x 16.00 | 0 x 9.00 | \$0.00  |
| iPhone 5S | 0   | 0       | 2        | 2     | iPhone 5S | 0 x 16.00 | 0 x 9.00 | \$0.00  |
| iPhone 5C | 1   | 0       | 1        | 2     | iPhone 5C | 1 x 10.50 | 0 x 6.00 | \$10.50 |
|           |     |         |          | 5     |           |           |          | \$10.50 |