#### Item Issue Box: 5

| Source     | Order/Shipment ID   | RMA     | Return ID                  | SKU         | Title  | Reason                 | Released | Received |
|------------|---------------------|---------|----------------------------|-------------|--|------------------------|----------|----------|
| storefront | 506679              | PP09039 | PP09039-APL-<br>001-2311-1 |             | LCD and Digitizer Assem bly for iPhone 6S Plus Black (Economy Plus)                              | Dispaly cuts out       |          |          |
| storefront | 505488              | PP09037 | PP09037-SRN<br>-MOT-610-1  | SRN-MOT-610 | Motorola Droid T<br>urbo XT1254 LCD<br>Assembly Black  | Intermittent           |          |          |
| mail       | 502979              | PP09024 | PP09024-SRN<br>-SAM-224-1  | SRN-SAM-224 | Galaxy S4 i9500 i9505 i337 i54<br>5 L720 M919 R970 LCD + Touch S<br>creen Digitizer - Black Mist | Lines in Display       |          |          |
| mail       | 105-8922372-6597849 | PP09042 | PP09042-BT-<br>BP-30138-1  | BT-BP-30138 | BinTEK Samsung Galaxy Ta<br>b 3 10.1 P5200 6800mAH Li<br>-Polymer Premium Battery                | charges to only 38%    |          |          |
| mail       | 503897              | PP08942 | PP08942-SRN<br>-MOT-610-1  | SRN-MOT-610 | Motorola Droid T<br>urbo XT1254 LCD<br>Assembly Black  | Digitizer Unresponsive |          |          |

### Not Tested Box: 1

| Source | Order/Shipment ID | RMA     | Return ID                  | SKU | Title   | Reason | Released | Received |
|--------|-------------------|---------|----------------------------|-----|---|--------|----------|----------|
| mail   | 502239            | PP09023 | PP09023-APL-<br>001-2215-1 |     | Apple iPad Mini & iPad Mini 2 Digi<br>tizer Touch Screen with Home Butto<br>n And IC Chip - White (Premium) |        |          |          |

### Good for Stock: 12

| Source | Order/Shipment ID   | RMA     | Return ID                  | SKU          | Title   | Reason | Released | Received |
|--------|---------------------|---------|----------------------------|--------------|---|--------|----------|----------|
| mail   | 112-8105495-8083421 | AM00693 | AM00693-BT<br>S810015-1    | BTS810015    | BinTEK 8-Piece Ce<br>11 Phone Repair To<br>ol Kit For LG/HTC                                  |        |          |          |
| mail   | 112-8105495-8083421 | AM00693 | AM00693-BT-<br>BP-30066-1  | BT-BP-30066  | BinTEK HTC One M<br>8 2600mAH Li-Ion<br>Premium Battery                                       |        |          |          |
| mail   | 505782              | PP08959 | PP08959-SRN-<br>SAM-1330-1 | SRN-SAM-1330 | Samsung Galaxy Note<br>5 LCD & Digitizer To<br>uch Screen - Blue                              |        |          |          |
| mail   | 107-7797777-3207462 | AM00700 | AM00700-BT-<br>BP-30114-1  | BT-BP-30114  | BinTEK LG Optimus G2 /<br>BL-54SG F320 2610mAH Li<br>-Ion Premium Battery                     |        |          |          |
| mail   | 108-8431530-7505847 | AM00722 | AM00722-BT<br>S810013-1    | BTS810013    | BinTEK 8-Piece Cell Phone Re<br>pair Tool Kit For iPad 1/2/3/<br>4 iPad Mini 1/2 iPad Air 1/2 |        |          |          |
| mail   | 108-8431530-7505847 | AM00722 | AM00722-BT-<br>BP-30216-1  | BT-BP-30216  | BinTEK Apple iPad A<br>ir 2 7340mAH Li-Poly<br>mer Premium Battery                            |        |          |          |
| mail   | 505671              | PP08937 | PP08937-APL-<br>001-2089-1 | APL-001-2089 | LCD and Touch Screen Dig<br>itizer Assembly for iPho<br>ne 5C - Black (Premium)               |        |          |          |
| mail   | 504924              | PP08944 | PP08944-APL-<br>001-2134-1 | APL-001-2134 | LCD and Digitizer Ass<br>embly for iPhone 6S P<br>lus Standard - Black                        |        |          |          |
| mail   | 504286              | PP08972 | PP08972-APL-<br>001-0762-1 | APL-001-0762 | LCD Screen with R<br>etina Display for<br>iPad Mini 2 3                                       |        |          |          |

| Source | Order/Shipment ID   | RMA     | Return ID                  | SKU | Title   | Reason | Released | Received |
|--------|---------------------|---------|----------------------------|-----|---|--------|----------|----------|
| mail   | 109-6510403-5113829 | AM00724 | AM00724-BT<br>S810014-1    |     | BinTEK 8-Piece Cell Pho<br>ne Repair Tool Kit For i<br>Pod Touch 1/2/3/4/5/6      |        |          |          |
| mail   | 109-6510403-5113829 | AM00724 | AM00724-BT-<br>BP-30204-1  |     | BinTEK iPod Touch<br>6 1043mAH Li-Polyme<br>r Premium Battery                     |        |          |          |
| mail   | 506034              | PP08979 | PP08979-SRN-<br>SAM-1457-1 |     | LCD and Touch Screen Digi<br>tizer for Samsung Galaxy<br>Note 5 - Silver Titanium |        |          |          |

# Customer Damage: 4

| Source | Order/Shipment ID | RMA     | Return ID                  | sku          | Title  | Reason                 | Released | Received |
|--------|-------------------|---------|----------------------------|--------------|--|------------------------|----------|----------|
| mail   | 497978            | PP08956 | PP08956-APL-<br>001-2135-1 | APL-001-2135 | LCD and Digitizer Ass<br>embly for iPhone 6S P<br>lus Standard - White                 | Received Only 3D Touch |          |          |
| mail   | 499249            | PP08973 | PP08973-APL-<br>001-1244-1 | APL-001-1244 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>6 Plus White (Standard)      | Cracked LCD            |          |          |
| mail   | 505071            | PP09025 | PP09025-SRN-<br>SAM-1426-1 | SRN-SAM-1426 | LCD and Touch Screen Digiti<br>zer for Samsung Galaxy S7 E<br>dge G935 - Gold Platinum | Damaged LCD            |          |          |
| mail   | 503422            | PP09028 | PP09028-APL-<br>001-0728-1 | APL-001-0728 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S White (Economy Plus)      | Not PPUSA Part         |          |          |

# Shipping Damage: 1

| Source | Order/Shipment ID | RMA | Return ID                  | SKU | Title  | Reason                         | Released | Received |
|--------|-------------------|-----|----------------------------|-----|--|--------------------------------|----------|----------|
| mail   | 502086            |     | PP09043-SRN-<br>SAM-1330-1 |     | Samsung Galaxy Note<br>5 LCD & Digitizer To<br>uch Screen - Blue | Cracked LCD / Not<br>Installed |          |          |

## Need To Repair: 0

| Source | Order/Shipment ID | RMA | Return ID | Title | Reason | Released | Received |
|--------|-------------------|-----|-----------|-------|--------|----------|----------|
|        |                   |     |           |       |        |          |          |

# Rejects: 49

| Item Vendor | Order/Shipment ID  | RMA | Return ID                   | SKU          | Title  | Reason             | Released | Received |
|-------------|--------------------|-----|-----------------------------|--------------|--|--------------------|----------|----------|
| Incoming    | PO20096/2260287960 | N/A | RJ-SRN-SAM-1<br>488-0002164 | SRN-SAM-1488 | LCD With Digitizer Ass<br>embly For Samsung Gala<br>xy S7 Edge - Silver            | LCD Lines          |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>136-0002140 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish            |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>136-0002141 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish            |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>136-0002142 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish            |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>136-0002143 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish            |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002144 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Digitizer Issues   |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002145 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Blemish            |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002146 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Frame Issue        |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002147 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Frame Issue        |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002148 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Frame Issue        |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002149 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Frame Issue        |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002150 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Frame Issue        |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002151 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Frame Issue        |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002152 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Frame Issue        |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>308-0002153 | APL-001-2308 | LCD Touch Screen Digitiz<br>er Assembly for iPhone 6<br>Black (Economy Plus)       | Frame Issue        |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>310-0002154 | APL-001-2310 | LCD and Digitizer Assem bly for iPhone 6S Plus White (Economy Plus)                | Flex/LCD Connector |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>310-0002155 | APL-001-2310 | LCD and Digitizer Assem bly for iPhone 6S Plus White (Economy Plus)                | Flex/LCD Connector |          |          |
| DATAN INC   | PO20105            | N/A | RJ-APL-001-2<br>310-0002156 | APL-001-2310 | LCD and Digitizer Assem<br>bly for iPhone 6S Plus<br>White (Economy Plus)          | Home Button Flex   |          |          |

| Item Vendor | Order/Shipment ID | RMA | Return ID                   | SKU          | Title  | Reason                   | Released | Received |
|-------------|-------------------|-----|-----------------------------|--------------|--|--------------------------|----------|----------|
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>310-0002157 | APL-001-2310 | LCD and Digitizer Assem bly for iPhone 6S Plus White (Economy Plus)                | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>310-0002158 | APL-001-2310 | LCD and Digitizer Assem bly for iPhone 6S Plus White (Economy Plus)                | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>310-0002159 | APL-001-2310 | LCD and Digitizer Assem<br>bly for iPhone 6S Plus<br>White (Economy Plus)          | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>310-0002160 | APL-001-2310 | LCD and Digitizer Assem bly for iPhone 6S Plus White (Economy Plus)                | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>310-0002161 | APL-001-2310 | LCD and Digitizer Assem<br>bly for iPhone 6S Plus<br>White (Economy Plus)          | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>310-0002162 | APL-001-2310 | LCD and Digitizer Assem<br>bly for iPhone 6S Plus<br>White (Economy Plus)          | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>310-0002163 | APL-001-2310 | LCD and Digitizer Assem<br>bly for iPhone 6S Plus<br>White (Economy Plus)          | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002116 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Flex or Digitizer Issues |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002117 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Flex or Digitizer Issues |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002118 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Flex or Digitizer Issues |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002119 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Frame Issue              |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002120 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Frame Issue              |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002121 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Frame Issue              |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002122 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Frame Issue              |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002123 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Frame Issue              |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-0<br>730-0002124 | APL-001-0730 | LCD and Touch Screen Digi<br>tizer Assembly for iPhone<br>5S Black (Economy Plus)  | Frame Issue              |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002125 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002126 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish                  |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002127 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Backlight                |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002128 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish                  |          |          |

| Item Vendor | Order/Shipment ID | RMA | Return ID                   | SKU          | Title  | Reason  | Released | Received |
|-------------|-------------------|-----|-----------------------------|--------------|--|---------|----------|----------|
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002129 | APL-001-2136 | LCD Touch Screen Digitize r Assembly for iPhone 6 P lus White (Economy Plus)       | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002130 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002131 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002132 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002133 | APL-001-2136 | LCD Touch Screen Digitize r Assembly for iPhone 6 P lus White (Economy Plus)       | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002134 | APL-001-2136 | LCD Touch Screen Digitize r Assembly for iPhone 6 P lus White (Economy Plus)       | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002135 | APL-001-2136 | LCD Touch Screen Digitize r Assembly for iPhone 6 P lus White (Economy Plus)       | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002136 | APL-001-2136 | LCD Touch Screen Digitize<br>r Assembly for iPhone 6 P<br>lus White (Economy Plus) | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002137 | APL-001-2136 | LCD Touch Screen Digitize r Assembly for iPhone 6 P lus White (Economy Plus)       | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002138 | APL-001-2136 | LCD Touch Screen Digitize r Assembly for iPhone 6 P lus White (Economy Plus)       | Blemish |          |          |
| DATAN INC   | PO20105           | N/A | RJ-APL-001-2<br>136-0002139 | APL-001-2136 | LCD Touch Screen Digitize r Assembly for iPhone 6 P lus White (Economy Plus)       | Blemish |          |          |