ECE222 Chapter 2 Notes

Instruction Set Architecture

- Instruction set architecture (ISA) defines the interface between hardware and software.
- RISC-V instructions are 32-bits (instruction[31:0]).
- RISC-V assembly uses 64-bit registers (double word) and 32-bit word registers.
- There are 32 registers (x0-x31), with x0 always being zero.
- Arithmetic operations require data to be in registers.
- 'Less frequently used' variables are 'spilled' into memory.
- Registers are faster and more energy efficient than memory.
- RISC-V has a 16-bit instruction set (RISC-V compressed) for embedded applications with code size constraints.
- Memory is byte-addressable with little endian byte ordering.
- RISC-V uses a Harvard architecture with separate instruction and data caches.

Instruction Formats

- R-type instructions: Use three register operands (2 sources and 1 destination).
- I-type instructions: Use two register operands and a 12-bit immediate value
- S-type instructions: Use two register operands and a 12-bit immediate value for stores.
- SB-type instructions: Conditional branch instructions with PC-relative addressing.
- U-type instructions: Upper immediate format for adding immediate value to PC.
- UJ-type instructions: Unconditional jump instructions for jumps and links.

Examples

- R-type instruction example: add x5,x6,x2 is coded as 0000000 00010 00110 000 00101 0110011.
- I-type instruction example: ld x9, 64(x22) is coded as 0000 0100 0000 10110 011 01001 0000011.
- S-type instruction example: sd x9, 240(x10) is coded as 0000111 01001 01010 011 10000 0100011.
- \bullet SB-type instruction example: bne x10, x11, 2000 is coded as 1100000 01011 01010 001 11110 1100011.
- U-type instruction example: auipc x1, 1000 is coded as 0000000 10001 00000 11011 0010111.
- UJ-type instruction example: jal x11, 2000 is coded as 1000000 01011 00000 11011 1101111.

Code Examples

Compilers and Branches

Compilers frequently create branches and labels where they do not appear in the programming language.

RISC-V Logical Operations

RISC-V logical operations include shift left/right, right arithmetic, bitwise AND/OR/NOT/XOR.

```
0.0.1 Example 1
```

```
if (i == j)
    f = g + h;
else
    f = g - h;

assume f through j correspond to values in registers x19 through x23
bne x22, x23, Else // go to Else if i != j
add x19, x20, x21 // f = g + h
beq x0, x0, Exit // go to Exit

Else: sub x19, x20, x21 // f = g - h

Exit:
```

Example 2

```
while (save[i] == k)
    i += 1;
```

assume value of i is in register x22 and value of k is in register x24. Assume base of array save[] is in x25.

Exit:

Procedures

Procedures allow programmers to concentrate on just one portion of the task at a time.

0.0.2 Procedure Instructions

By convention in RISC-V:

- 8 parameter registers x10-x17 are used to pass parameters or return values.
- One return address register x1 holds the return address to return to the point of origin.

In RISC-V, there are special procedure instructions:

• Jump and link instruction, jal (jump and link, UJ type) for procedures, which branches to an address and saves the address of the following instruction (PC+4) to rd=x1.