From: Mpls_Er_Sbi/RAILTEL Arpanroy/RAILTEL@RAILTEL To:

Pbiswas/RAILTEL@RAILTEL, Sanjaykumar/RAILTEL@RAILTEL, Siddharth Kgp2003/RAILTEL@RAILTEL, Ardhendu/RAILTEL@RAILTEL, Sanjeevkumar/RAILTEL@RAILTEL, Singhnk/RAILTEL@RAILTEL, Surajitroy/RAILTEL@RAILTEL, Mk Manu/RAILTEL@RAILTEL, Cc:

Rkbera/RAILTEL@RAILTEL

Date: Tuesday, September 24, 2024 03:32PM

Subject: Need 01 no DC SWITCH require For Belmuri POP.

Need 01 no 1G DC SWITCH require For Belmuri POP due to exsisting Switch was faulty.

Faulty Switch details:

Model No:DGS-3000-28L

Serial No:SY3010C000107

Kindly arrange the same, if available in store.

Reqid-ReqNOC-640

Switch needed in POP

SL No	. Branch o. Name	Branch Code	State	Originating / Handover RailTel PoP	Territory	Section-in- charge	Teritorry In- Charge	LMC Parner	RailWire / Vendor Model	BW (Mbps)	LMC Media Type	Required PoP end / LMC PoP Switch (Y/N)		No. of required switch	Remarks	SFP require
1	3 Branch		West- Bengal	BMAE	KOAA	Sr.Mgr/HWH	TM/KOL		Vendor		RF	Y	N	1	1 DC Switch	NA

Thanks & Regards:-

SBI-ER-Team

Railtel Corporation Of India Ltd. (Under Ministry of Railway) (A Miniratna category-I Enterprise) Eastern Region, Kolkata NKG Building, Kolkata 700001 mpls_er_sbi@railtelindia.com

Mob: 9007044148

Toll free 1800117245 Dial 11

Email: mplshelpdesk@railtelindia.com

E-mail: mpls er sbi@railtelindia.com