

Annexure A

Architect's Certificate*		
Report for Quarter ending		DEC-25
Subject		Certificate of progress of construction work
1.	I/We have undertaken assignment as architect for certifying progress of construction work in the below mentioned project as per the approved plans	
Sr. No.	Particulars	Information
1.	Project/Phase of the project	Urban Oasis Phase-01 & 02
2.	Location	SECTOR-62, GURUGRAM
3.	Licensed area in acres	177.86 ACRES
4.	Area for registration in acres	6.64 Acres
5.	HARERA registration no.	85 of 2023 RC/REP/HARERA/GGM/741/473/2023/85 dt 07.08.2023
6.	Name of licensee	10 of 2009 dated 21.05.2009 valid upto 20.05.2024. 113 of 2011 dated 22.12.2011 valid upto 21.12.2024. 117 of 2022 dated 12.08.2022 valid up to 11.08.2027
7.	Name of collaborator	M/S Active Promoter Pvt Ltd and Others
8.	Name of developer	EMAAR INDIA LTD (Formerly Known as EMAAR MGF LAND LIMITED)
2.	Details related to inspection are as under	
1.	Date of certifying of percentage of construction work/ site inspection	01-JAN-26
2.	Name of Architect/ Architect's firm	Manmeet Singh / DSP Design Associates Pvt Ltd
3.	Date of site inspection	31-DEC-25

3.	Following technical professionals are appointed by promoter: - (as applicable)		
	Sr. No.	Consultants	Name
	1.	Site engineer	Mr. Vikas Kalra
	2.	Structural consultant	TPC -Technical Projects Consultants Pvt Ltd.
	3.	Proof consultant	Nadig consulting
	4.	MEP consultant	AEON
	5.	Site supervisor/incharge	Manoj Soni
4.	I certify that the work has been executed as per approved drawings, statutory/ mandatory approvals, Haryana Building Code, 2017/ National Building Code (wherever applicable) and the material used in the construction, infrastructure works and internal development works are as per the projected standard as envisaged in the registration and brochure, publication material and other documents shared with the buyers in this regard.		
5.	I also certify that as on the date, the percentage of work done in the project for each of the building/ tower of the real estate project/phase of the project under HARERA is as per table A and table B given herein below. The percentage of the work executed with respect to each of the activity of the entire project/ phase is detailed in table A and table B.		

Date:	08-01-26	Yours faithfully,
Place:	Gurgaon	
Council of Architects (CoA) registration No.:	CA/2003/30546	MANMEET SINGH BALI Signature & name (in block letters) with stamp of architect
Council of architects (CoA) registration valid till (date) :	31.12.2028	FOR DSP Manmeet Singh Bali Architect (B.Arch, MCA) CA/2003/30546

CA/2003/30546

Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		TOWER - 01		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	147.21	666.35	22%
2.	Super structure (slabs, brick work, block work, staircase, lift wells, machine rooms, water tank, etc.)	257.72	1146.51	22%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)			
	3.2 Electrical (conduiting, wiring, fixtures, etc.)			4.28%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			7.99%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			-
	4.2 External (plaster, painting, facade, etc.)			-

FOR DSP

Manmeet Singh Bali

FOR DSP
Manmeet Singh Bali

Architect (B.Arch, MCA)

CA/2003/30546

Manmeet Singh

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work		
	Sub-Structure Status					
1.	Excavation		Completed	100%		
2.	Laying of foundation					
	(i)	Raft	Completed	100%		
	(ii)	Pile	NA	NA		
3.	Number of basement(s) - 02					
	(i)	Basement Level 1	Completed	100%		
	(ii)	Basement level 2	Completed	100%		
4.	Waterproofing of the above sub-structure (wherever applicable)		Not Started	0%		
	Super-Structure Status					
5.	Total floors in the tower/ building		30	20%		
6.	Total area on each floor		Not Started	0%		
7.	Stilt floor/ ground floor		Not Started	0%		
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		Not Started	0%		
9.	Status of construction					
	(i)	Walls on floors	Not Started	0%		
	(ii)	Staircase	Not Started	0%		
	(iii)	Lift wells along with water proofing	Not Started	0%		
	(iv)	Lift lobbies/ common areas floor wise	Not Started	0%		
10.	Fixing of door and window frames in flats/ units		Not Started	0%		
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Not Started	Not Started	0%	0%
	(ii)	Electrical work including wiring	Started	Not Started	7%	0%
	(iii)	Plumbing works	Not Started	Not Started	0%	0%
12.	Status of wall plastering					
	(i)	External plaster	NA	NA		
	(ii)	Internal plaster	Not Started	0%		
13.	Status of wall tiling					
	(i)	In bathroom	Not Started	0%		
	(ii)	In kitchen	Not Started	0%		
14.	Status of flooring					
	(i)	Common areas	Not Started	0%		
	(ii)	Units/ flats	Not Started	0%		

FOR DSP .
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546

minty

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Not Started	0%
	(ii)	External walls	Not Started	0%
16.	Status of finishing			
	(i)	Staircase with railing	Not Started	0%
	(ii)	Lift wells	Not Started	0%
	(iii)	Lift lobbies/ common areas floor wise	Not Started	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Not Started	0%
	(ii)	Sanitary fixtures	Not Started	0%
	(iii)	Modular kitchen	Not Started	0%
	(iv)	Electrical fittings/ lighting	Not Started	0%
	(v)	Gas piping (if any)	NA	-
	(other than flat/units)			
	(vi)	Lifts installation	Not Started	0%
	(vii)	Overhead tanks	Not Started	0%
	(viii)	Underground water tank	Not Started	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Not Started	0%
	(x)	Electrical fittings in common areas	Not Started	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	NA	NA
18.	Waterproofing of terraces		Not Started	0%
19.	Entrance lobby finishing		Not Started	0%
20.	Status of construction of compound wall		NA	NA

Note: (*) extend rows as per requirement.

FOR DSP
Manmeet Singh Bali
Architect (B.Arch, MCA)
CA/2003/30546

Manmeet Singh Bali

Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		TOWER – 02		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	212.49	654.14	32%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	226.40	981.07	23%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)			-
	3.2 Electrical (conduiting, wiring, fixtures, etc.)			5.53%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)			7.75%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			-
	4.2 External (plaster, painting, facade, etc.)			-

FOR DSP
Srikanth Reddy

FOR DSP
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546

Minit

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work		
	Sub-Structure Status					
1.	Excavation		Completed	100%		
2.	Laying of foundation					
	(i)	Raft	Completed	100%		
	(ii)	Pile	NA	NA		
3.	Number of basement(s) - 02					
	(i)	Basement Level 1	Completed	100%		
	(ii)	Basement level 2	Completed	100%		
4.	Waterproofing of the above sub-structure (wherever applicable)		Not Started	0%		
	Super-Structure Status					
5.	Total floors in the tower/ building		27	24%		
6.	Total area on each floor		Not Started	0%		
7.	Stilt floor/ ground floor		Not Started	0%		
8.	Status of laying of slabs floor wise					
	Cumulative number of slabs in the building/ tower laid by end of quarter		Not Started	0%		
9.	Status of construction					
	(i)	Walls on floors	Not Started	0%		
	(ii)	Staircase	Not Started	0%		
	(iii)	Lift wells along with water proofing	Not Started	0%		
	(iv)	Lift lobbies/ common areas floor wise	Not Started	0%		
10.	Fixing of door and window frames in flats/ units		Not Started	0%		
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Not Started	Not Started	0%	0%
	(ii)	Electrical works including wiring	Started	Not Started	10%	0%
	(iii)	Plumbing works	Not Started	Not Started	0%	0%
12.	Status of wall plastering					
	(i)	External plaster	NA	NA		
	(ii)	Internal plaster	Not Started	0%		
13.	Status of wall tiling					
	(i)	In bathroom	Not Started	0%		
	(ii)	In kitchen	Not Started	0%		
14.	Status of flooring					
	(i)	Common areas	Not Started	0%		
	(ii)	Units/ flats	Not Started	0%		

FOR DSP
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Not Started	0%
	(ii)	External walls	Not Started	0%
16.	Status of finishing			
	(i)	Staircase with railing	Not Started	0%
	(ii)	Lift wells	Not Started	0%
	(iii)	Lift lobbies/ common areas floor wise	Not Started	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Not Started	0%
	(ii)	Sanitary fixtures	Not Started	0%
	(iii)	Modular kitchen	Not Started	0%
	(iv)	Electrical fittings/ lighting	Not Started	0%
	(v)	Gas piping (if any)	NA	-
	(other than flat/units)			
	(vi)	Lifts installation	Not Started	0%
	(vii)	Overhead tanks	Not Started	0%
	(viii)	Underground water tank	Not Started	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Not Started	0%
	(x)	Electrical fittings in common areas	Not Started	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	NA	NA
18.	Waterproofing of terraces		Not Started	0%
19.	Entrance lobby finishing		Not Started	0%
20.	Status of construction of compound wall		NA	NA

Note: (*) extend rows as per requirement.

FOR DSP
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546

Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		TOWER - 03		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	427.52	1138.86	38%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	550.35	1476.44	37%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)			
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	99.34	219.94	45%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	112.95	281.78	40%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			-
	4.2 External (plaster, painting, facade, etc.)			-

FOR DSP
Manmeet Singh Bali

FOR DSP
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546

Manmeet Singh

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work		
	Sub-Structure Status					
1.	Excavation		Completed	100%		
2.	Laying of foundation					
	(i)	Raft	Completed	100%		
	(ii)	Pile	NA	NA		
3.	Number of basement(s) - 02					
	(i)	Basement Level 1	Completed	100%		
	(ii)	Basement level 2	NA	NA		
4.	Waterproofing of the above sub-structure (wherever applicable)		Started	52%		
	Super-Structure Status					
5.	Total floors in the tower/ building		25	100%		
6.	Total area on each floor		Not Started	0%		
7.	Stilt floor/ ground floor		Not Started	0%		
8.	Status of laying of slabs floor wise		25	100%		
	Cumulative number of slabs in the building/ tower laid by end of quarter		Started	100%		
9.	Status of construction					
	(i)	Walls on floors	Started	89%		
	(ii)	Staircase	Started	100%		
	(iii)	Lift wells along with water proofing	Started	100%		
	(iv)	Lift lobbies/ common areas floor wise	Started	89%		
10.	Fixing of door and window frames in flats/ units		Not Started	0%		
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Not Started	Not Started	0%	0%
	(ii)	Electrical work including wiring	Started	Not Started	69%	0%
	(iii)	Plumbing works	Started	Not Started	59%	0%
12.	Status of wall plastering					
	(i)	External plaster	NA	NA		
	(ii)	Internal plaster	Started	70%		
13.	Status of wall tiling					
	(i)	In bathroom	Started	16%		
	(ii)	In kitchen	Started	10%		
14.	Status of flooring					
	(i)	Common areas	Not Started	0%		
	(ii)	Units/ flats	Started	44%		

FOR DSP.
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Not Started	0%
	(ii)	External walls	Not Started	0%
16.	Status of finishing			
	(i)	Staircase with railing	Not Started	0%
	(ii)	Lift wells	Not Started	0%
	(iii)	Lift lobbies/ common areas floor wise	Not Started	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Not Started	0%
	(ii)	Sanitary fixtures	Not Started	0%
	(iii)	Modular kitchen	Not Started	0%
	(iv)	Electrical fittings/ lighting	Not Started	0%
	(v)	Gas piping (if any)	NA	-
	(other than flat/units)			
	(vi)	Lifts installation	Not Started	0%
	(vii)	Overhead tanks	Not Started	0%
	(viii)	Underground water tank	Not Started	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Not Started	0%
	(x)	Electrical fittings in common areas	Not Started	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	NA	NA
18.	Waterproofing of terraces		Not Started	0%
19.	Entrance lobby finishing		Not Started	0%
20.	Status of construction of compound wall		NA	NA

Note: (*) extend rows as per requirement.

FOR DSP
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546


Table – A				
Building/ Tower no. (to be prepared separately for each building/ tower in the project/ phase of the project)		TOWER - 04		
A1	Cumulative progress of the project/phase at the end of the quarter.			
Sr. No.	Project components	Work done value during the quarter	Cumulative work done value till date	Percentage of work done to the total proposed work
1.	Sub structure (inclusive of excavation, foundation, basements, water proofing, etc.)	335.09	1041.64	32%
2.	Super structure (slabs, brick work, block work, stair case, lift wells, machine rooms, water tank, etc.)	370.65	1290.49	29%
3.	MEP			
	3.1 Mechanical (lifts, ventilation, etc.)			
	3.2 Electrical (conduiting, wiring, fixtures, etc.)	59.49	179.27	33%
	3.3 Plumbing & Firefighting (piping, pumps and pump room, fixtures, etc.)	119.54	287.24	42%
4.	Finishing			
	4.1 Internal (plaster, tilling, flooring, painting, etc. within units and common areas)			-
	4.2 External (plaster, painting, facade, etc.)			-

FOR DSP
Manmeet Singh D

FOR DSP
Manmeet Singh Bali

Architect (B.Arch, MCA)
CA/2003/30546

Manmeet Singh
2

Sr. No.	Tasks/ Activity		Description of work done		Percentage of total proposed work	
	Sub-Structure Status					
1.	Excavation		Completed		100%	
2.	Laying of foundation					
	(i)	Raft	Completed		100%	
	(ii)	Pile	NA		NA	
3.	Number of basement(s) - 02					
	(i)	Basement Level 1	Completed		100%	
	(ii)	Basement level 2	NA		NA	
4.	Waterproofing of the above sub-structure (wherever applicable)		Started		34%	
	Super-Structure Status					
5.	Total floors in the tower/ building		27		92%	
6.	Total area on each floor		Not Started		0%	
7.	Stilt floor/ ground floor		Completed		100%	
8.	Status of laying of slabs floor wise		27		92%	
	Cumulative number of slabs in the building/ tower laid by end of quarter		Started		92%	
9.	Status of construction					
	(i)	Walls on floors	Started		70%	
	(ii)	Staircase	Started		92%	
	(iii)	Lift wells along with water proofing	Started		92%	
	(iv)	Lift lobbies/ common areas floor wise	Started		92%	
10.	Fixing of door and window frames in flats/ units		Not Started		0%	
11.	Status of MEP		Internal (within flat)	External works	Internal (within flat)	External works
	(i)	Mechanical works	Not Started	Not Started	0%	0%
	(ii)	Electrical works including wiring	Started	Not Started	50%	0%
	(iii)	Plumbing works	Started	Not Started	40%	0%
12.	Status of wall plastering					
	(i)	External plaster	NA		NA	
	(ii)	Internal plaster	Started		56%	
13.	Status of wall tiling					
	(i)	In bathroom	Started		6%	
	(ii)	In kitchen	Started		6%	
14.	Status of flooring					
	(i)	Common areas	Not Started		0%	
	(ii)	Units/ flats	Started		42%	

FOR DSP
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546
Manmeet Singh

Sr. No.	Tasks/ Activity		Description of work done	Percentage of total proposed work
	Sub-Structure Status			
15.	Status of white washing			
	(i)	Internal walls	Not Started	0%
	(ii)	External walls	Not Started	0%
16.	Status of finishing			
	(i)	Staircase with railing	Not Started	0%
	(ii)	Lift wells	Not Started	0%
	(iii)	Lift lobbies/ common areas floor wise	Not Started	0%
17.	Status of installation			
	(within flat/unit)			
	(i)	Doors and windows panels	Not Started	0%
	(ii)	Sanitary fixtures	Not Started	0%
	(iii)	Modular kitchen	Not Started	0%
	(iv)	Electrical fittings/ lighting	Not Started	0%
	(v)	Gas piping (if any)	NA	-
	(other than flat/units)			
	(vi)	Lifts installation	Not Started	0%
	(vii)	Overhead tanks	Not Started	0%
	(viii)	Underground water tank	Not Started	0%
	(ix)	Firefighting fitting and equipment's as per CFO NOC	Not Started	0%
	(x)	Electrical fittings in common areas	Not Started	0%
	(xi)	Compliance to conditions of environment/ CRZ NOC	NA	NA
18.	Waterproofing of terraces		Not Started	0%
19.	Entrance lobby finishing		Not Started	0%
20.	Status of construction of compound wall		NA	NA

Note: (*) extend rows as per requirement.

FOR DSP
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546

Manmeet Singh

Table – B

Sr. No.	Common areas and facilities amenities	Proposed (Yes/ No)	Percentage of work done	remarks
B-1	Services			
1.	Internal roads & pavements	Yes	0%	
2.	Parking	Yes	0%	
	Covered no.	Yes	0%	
	Open no.	Yes	0%	
3.	Water supply	Yes	0%	
4.	Sewerage (chamber, lines, septic tanks, STP)	Yes	0%	
5.	Storm water drains	Yes	0%	
6.	Landscaping & tree plantation	Yes	0%	
7.	Parks and playgrounds	Yes	0%	
	Fixing of children play equipment's	Yes	0%	
	Benches	Yes	0%	
8.	Shopping area	Yes	0%	
9.	Street lighting/ electrification	Yes	0%	
10.	Treatment and disposal of sewage and sullage water/ STP	Yes	0%	
11.	Solid waste management & disposal	Yes	0%	
12.	Water conservation, rain water, harvesting, percolating well/ pit	Yes	0%	
13.	Energy management (solar)	Yes	0%	
14.	Fire protection and fire safety requirements	Yes	0%	
15.	Electrical meter room, sub-station, receiving station	Yes	0%	
16.	Other (option to add more)			
B-2				
17.	Community centre	NA		
18.	others			
B-3	Community buildings not to be transferred to RWA/competent authority			
19.	Schools	NA		
20.	Dispensary	NA		
21.	Club	Yes	0%	
22.	Others			
B-4	Services/ facilities to be transferred to competent authority			
23.	*			

Note: (*) extend as per requirement

FOR DSP
Manmeet Singh Bali
 Architect (B.Arch, MCA)
 CA/2003/30546

Manmeet Singh