Fahs (فحص) — Used Car Inspection

Vehicle inspection report

Report No: FAHS-2026-0042
Date: 2026-11-11

Brand	Model	Generation	Year
Peugeot	208	Phase 1 (2012–2019)	2018
Fuel	**Gearbox**	**Mileage**	**Plate / Label**
ESSENCE	MANUELLE	142 000 km	11845-118-16

42 /100

High Risk — Mechanic Opinion Required / Walk Away (Capped: 42/100 | Raw: 96/100)

Score capped at 42 (raw checklist score: 96/100) because of 1 critical problem: Does the chassis number stamped on the car match the carte grise?
. This deserves a trusted mechanic's opinion before committing. Items not checked: 3 out of 110.

Plain-Language Summary (Strengths, Problems & What to Ask a Mechanic)

On this Peugeot 208 (2018), the main strengths are in 3. Exterior & Bodywork and 5. Interior & Controls, with 103 passed checks overall. The main problems found are 1 critical issue(s) and 3 other defect(s), led by: Does the chassis number stamped on the car match the carte grise?; Did the seller agree to keep the engine completely cold before your arrival?. The electronic OBD2 scan also flagged an alert (2 fault code(s) found: P0420 (STORED), P0299 (STORED)) that needs verification. Ask a trusted mechanic to inspect these flagged items on a workshop lift and give you a written repair quote in DZD before negotiating.

Scores per Inspection Area

1. Before the Visit	56% (8/10)
2. Documents & Identity	79% (9/10)
3. Exterior & Bodywork	100% (17/17)
4. Under the Bonnet (Engine Cold)	100% (14/14)
5. Interior & Controls	100% (17/17)
6. Underneath & Suspension	100% (11/11)
7. Engine Start & Idle	100% (10/10)
8. Test Drive	100% (13/13)
9. After the Drive	100% (8/8)

Problems Found — Most Serious First (4)

Item & Finding	Severity	User's Note	Approx. Cost	Photo
Does the chassis number stamped on the car match the carte grise? (2. Documents & Identity)	Critical	Suintement d'huile visible + courroie humide à vérifier d'urgence	Mechanic quote	
Did the seller agree to keep the engine completely cold before your arrival? (1. Before the Visit)	Important	Usure prononcée à l'avant (DOT 1419), prévoir remplacement	Mechanic quote	—

Item& Finding	Severity	User's Note	Approx. Cost	Photo
Is the seller on the phone the actual owner named on the registration card? (1. Before the Visit)	Important	Légère vibration au freinage à 90 km/h (disques avant)	Mechanic quote	—
Are you inspecting the car in full daylight, dry weather, and a quiet spot? (1. Before the Visit)	Minor	Rayure superficielle pare-chocs arrière droit	Mechanic quote	—

OBD2 Electronic Diagnostic Section

- ECU connection: Connected to car ECU (ISO 15765-4 CAN (11 bit, 500 kbps))
- Cleared-codes finding: ⚠ Warning: fault memory cleared very recently (18 km since clearing, 1 warm-ups)
- Check-Engine light: Bulb works at key-on; commanded ON by ECU (active fault present)
- ECU VIN comparison (09 02): Matches the carte grise (VF3CC8HR0JW049281) ✓
- [P0420 — Stored (Mode 03)] Catalyst System Efficiency Below Threshold (Bank 1): Very common: the catalytic converter is worn out, clogged, or has been hollowed out.
- [P0299 — Stored (Mode 03)] Turbocharger / Supercharger Underboost Condition: The turbocharger is not building enough boost pressure, causing sluggish uphill acceleration due to a boost leak, faulty solenoid, or worn turbo.

Live Engine Readings (with status markers):

- Idle Engine Speed: 780 tr/min (Normal: 680 - 900 tr/min) [OK]
- Coolant Temperature: 91 °C (Normal: 80 - 98 °C) [OK]
- Charging Voltage: 13.3 V (Normal: 13.5 - 14.7 V) [WARN]
- Fuel Trim (STFT/LTFT): +9.4 % (Normal: -10% .. +10%) [WARN]

Not Checked (3 of 110)

[CRITICAL — NOT CHECKED] 2. Documents & Identity: Does the carte grise name match the seller's ID?

- 1. Before the Visit: Did you ask over the phone which panels have been resprayed or replaced?
- 1. Before the Visit: For this mileage, does the seller know the exact date and mileage of the last timing belt/chain replacement?

Negotiation Total & Approximate Repair Cost

Total approximate repair cost: 65 000 DZD (6.5 Million centimes)
Seller's Asking Price: 235M → Target Offer After Repairs: 228.5 Million centimes (2285 000 DZD)