SpeedAC iQ – In Process V3.2.2 changes summary:

IMPORTANT: Databases from the previous versions are compatible

Improvements/New features:

Fixes:

- Fault Discharge door not closed fixed;
- Fault Exceeded Capacity fixed;