

LOTO GOLDEN RULES

LOCKOUT / TAGOUT SAFETY

LOCK • TAG • VERIFY

01

IDENTIFY ENERGY SOURCES

- Identify all electrical, mechanical and pressure energy sources.

02

SHUT DOWN EQUIPMENT

- Use the normal shutdown procedure and notify affected personnel.

03

ISOLATE

- Place every required isolation point in a safe position.

04

LOCK AND TAG

- Each worker must apply their own personal lock and tag.

05

RELEASE STORED ENERGY

- Control pressure, springs, capacitors and residual movement.

06

VERIFY ZERO ENERGY

- Verify effective isolation using an appropriate test method.

NEVER

- ✓ Remove another person's lock
- ✓ Rely on a stop button
- ✓ Start work without verification
- ✓ Use an unidentified lock