

HOUSEKEEPING

Maintain clear walkways, organised work areas and safe waste control.

PURPOSE AND SCOPE

Review slip, trip, fall, fire and access hazards caused by poor housekeeping, waste, spills, unsafe storage and obstructed walkways, and maintain an orderly work area throughout the task. Housekeeping is not limited to cleaning at the end of the job. Materials, tools, cables, hoses, packaging and waste must be controlled safely throughout the work.

KEY HAZARDS

 TRIP	 SLIP	 SHARP WASTE	 COMBUSTIBLE WASTE
 BLOCKED ROUTE	 LOOSE CABLE	 UNSTABLE STACK	 SPILL

CRITICAL VALUES TO VERIFY IN THE FIELD

0 Blocked aisles, stairs or exits	Immediately Spill and waste response	100% Correct waste segregation
---	--	--



REMEMBER - SERNEM

S

Stop and think

E

Evaluate the risk

R

Remove or reduce

N

Never assume

E

Ensure protection

M

Monitor and communicate

HOUSEKEEPING

Maintain clear walkways, organised work areas and safe waste control.

STANDARDS AND FIELD REQUIREMENTS

OSHA 1926.25, 1910.22 and 1910.176 require clean, dry, unobstructed work areas, controlled waste and stable storage.

OSHA 1926.25(a) WORK AREA

Regularly remove waste, scrap and debris from work areas, passageways and stairs during the work.

OSHA 1926.25(b) COMBUSTIBLE WASTE

Collect oily and combustible waste in covered metal containers and remove it regularly.

OSHA 1910.22 WALKING-WORKING SURFACES

Keep floors clean, orderly and as dry as feasible; correct hazards or prevent access.

OSHA 1910.176(c) SAFE STORAGE

Stack materials so they remain stable and secure against sliding, collapse or overturning.


MINIMUM EVIDENCE BEFORE START

- | | |
|---|--|
| ☐ Housekeeping responsibility plan | ☐ Walkway and exit layout |
| ☐ Waste-segregation plan | ☐ Spill-kit inspection |
| ☐ Storage-area inspection | ☐ End-of-shift checklist |

SUPERVISOR DISCUSSION POINTS

- Are today's access and escape routes completely clear?
- Have cables and hoses been routed safely?
- Where are the waste containers and are they correctly labelled?

CLEAN, SEGREGATED AND UNOBSTRUCTED WORK AREA



Clear route - Cable management - Waste segregation - Spill control - Safe storage

HOUSEKEEPING

Maintain clear walkways, organised work areas and safe waste control.

CRITICAL CONTROL MEASURES (HIERARCHY OF CONTROLS)

1. PREVENT WASTE AT SOURCE

Keep access and escape routes clear at all times. Route cables and hoses safely.

2. ROUTE CABLES AND SERVICES SAFELY

Clean spills immediately and mark the area. Place waste in correctly labelled containers. Store materials securely and in a stable condition.

3. CLEAN, SEGREGATE AND STORE

Keep firefighting equipment and panels accessible. Dispose of sharp waste in suitable containers. Avoid unnecessary material accumulation on platforms.

4. END-OF-SHIFT CLOSEOUT

Inspect the work area at the end of the shift. Correct or report poor housekeeping immediately.

CRITICAL WARNING



A clean and organised workplace does more than look professional; it prevents falls, fires, equipment damage and delays during emergencies.

SITE CHECKLIST (BEFORE STARTING WORK)

- | | |
|---|--|
| ☐ Walkways clear | ☐ Emergency exits clear |
| ☐ Cables organised | ☐ Hoses routed safely |
| ☐ Waste containers ready | ☐ Storage stable |
| ☐ No spills present | ☐ Fire equipment accessible |
| ☐ Platforms clean | |

HOUSEKEEPING

Maintain clear walkways, organised work areas and safe waste control.

ATTENDANCE AND APPROVAL

Project / Site: _____ Date: _____

Presented by: _____ Work area: _____

No	Full Name	Company / Role	Signature
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			