


RIGGING EQUIPMENT INSPECTION

Identification, capacity, damage criteria and quarantine control.

PURPOSE AND SCOPE

Slings, shackles, hooks, master links and lifting attachments must be inspected each shift and before use by a qualified user. Equipment with missing identification or working-load limit, or with cuts, wear, deformation, heat or chemical damage, must not be used. Record the result and physically quarantine defective gear.

KEY HAZARDS



CRITICAL VALUES TO VERIFY IN THE FIELD

100%

Inspection each shift and before use

≤ WLL

Working-load limit for every component

0

Knots, improvised connections and mismatched gear



REMEMBER - SERNEM

S

Stop and think

E

Evaluate the risk

R

Remove or reduce

N

Never assume

E

Ensure protection

M

Monitor and communicate

RIGGING EQUIPMENT INSPECTION

Identification, capacity, damage criteria and quarantine control.

STANDARDS AND FIELD REQUIREMENTS

OSHA 1926.251 governs rigging identification, inspection, capacity and removal criteria. Manufacturer instructions and applicable ASME B30.9 / B30.26 criteria apply to the equipment type.

OSHA 1926.251(a)(1)

SHIFT INSPECTION

Rigging equipment must be inspected each shift and as necessary during use; defective gear must be removed immediately.

OSHA 1926.251(a)(2)

IDENTIFICATION AND CAPACITY

Rigging equipment, including custom devices, must carry legible safe-working-load or equivalent capacity identification.

OSHA 1926.251(c)-(f)

SLING CRITERIA

Evaluate wire rope, chain, synthetic web and other sling types against their specific damage and use criteria.

ASME B30.9 / B30.26

SLING AND HARDWARE CRITERIA

Select slings and hardware to manufacturer instructions, angle effects, connection method and removal criteria.


MINIMUM EVIDENCE BEFORE START

- | | |
|---|--|
| ☐ Rigging-equipment register | ☐ Shift inspection record |
| ☐ Certificates and WLL data | ☐ Lift plan and angle calculation |
| ☐ Quarantine record | ☐ Qualified-rigger record |

SUPERVISOR DISCUSSION POINTS

- How does sling angle affect capacity?
- What is the removal criterion for this gear?
- How is defective gear prevented from returning to service?

PRE-USE INSPECTION OF SLINGS AND RIGGING HARDWARE



Identification - WLL - Webbing / wire - Stitching - Hook - Shackle - Quarantine

RIGGING EQUIPMENT INSPECTION

Identification, capacity, damage criteria and quarantine control.

CRITICAL CONTROL MEASURES (HIERARCHY OF CONTROLS)

1. SELECT THE RIGHT LIFT METHOD

Determine the load, center of gravity, lifting points and environment before the lift.

2. SELECT SUITABLE GEAR

Evaluate sling type, WLL, angle, temperature, edges and chemical exposure together.

3. INSPECT AND PROTECT

Check tags, webbing, wires, stitching, hooks, shackles and pins; use edge protection.

4. QUARANTINE AND RECORD

Mark and physically segregate defective gear; leave repair decisions to an authorized person.

CRITICAL WARNING



**Do not use a sling with missing WLL identification or damage, even for a light load.
Never knot slings, side-load a hook throat or leave a screw-pin shackle loose.**

SITE CHECKLIST (BEFORE STARTING WORK)

- | | |
|---|---|
| ☐ Lift plan and load weight known | ☐ Identification and WLL legible on all gear |
| ☐ Sling type and capacity suitable | ☐ Sling-angle effect considered |
| ☐ Webbing, wires and stitching sound | ☐ Hooks, shackles and pins sound |
| ☐ Edge protection available | ☐ Compatible connection and orientation verified |
| ☐ Defective gear quarantined | |

RIGGING EQUIPMENT INSPECTION

Identification, capacity, damage criteria and quarantine control.

ATTENDANCE AND APPROVAL

Project / Site: _____ Date: _____

Presented by: _____ Work area: _____

No	Full Name	Company / Role	Signature
1			
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			