Sheet1

FE-ASIC V4 control bits

Test Pulse	Baseline	Gain	Peaking time	Output coupling	Output buffer
0 = OFF	0 = 900 mV	00 = 4.7 mV/fC	10 = 0.5 usec	0 = DC	0 = OFF
1 = ON	1 = 200 mV	10 = 7.8 mV/fC	00 = 1 usec	1 = AC (don't use)	1 = ON (typical)
		01 = 14 mV/fC	11 = 2 usec		
		11 = 25 mV/fC	01 = 3 usec		

Just read across the table left to right to figure out the bits

For example: typical settings in a TPC and with external test pulse:

Test Pulse = ON, Baseline = 900 mV, Gain = 14 mV/fC, Peaking = 2 usec

Gives bits: 1001 1101 which is hex: 9D

HEX
0
1
2
3
4
5
6
7
8
9
А
В
С
D
E
F