

कार्यालय प्रधान महालेखाकार (लेखापरीक्षा)
हिमाचल प्रदेश, गॉर्टन कैसल
शिमला - 171 003



Office of the Principal Accountant General (Audit)
Himachal Pradesh,
Gorton Castle, Shimla-171 003

Legal Cell/Audit/RTIAct,2005/Sanjay Kumar/2026-27/139

Dated 08.10.2026

To,

Shri Sanjay Kumar,




Subject: Supply of information under Right to Information Act, 2005.

Refer to your application bearing registration No. AGHPS/R/E/26/00058 dated 17.09.2026 submitted under RTI Act, 2005. The requisite information is attached herewith as detailed below:

- Point No.1 to 3: The latest Inspection Report of the Executive Engineer, Electrical Division, Himachal Pradesh State Electricity Board Limited, Karsog (for the years 2010-22), comprising of Part I, Part II, Part III Part IV and Part V.
- Point No. 4: The requested Inspection Report and its audit findings have not been published for suo motu disclosure under Section 4(1)(b) and Section 4(2) of the RTI Act, 2005, Consequently, no web link is available for it.

First appeal under section 19(1) of the Act can be submitted within 30 days of receipt of this reply to the First Appellate Authority (FAA).


Sr. Dy. Accountant General (Audit)-cum-
Central Public Information Officer

Name and Address of the First Appellate Authority:

Shri Purushottam Tiwary
Principal Accountant General (Audit)
Himachal Pradesh

Phone: +91-177-2652607

E-mail: agauhimachalpradesh@cag.gov.in

Draft inspection Report on the audit of office of the Executive Engineer Electrical Division
Himachal Pradesh State Electricity Board Limited Karsog

PART-I- (Introduction)

The audit of office of the Executive Engineer Electrical Division Himachal Pradesh State Electricity Board Limited Karsog was conducted from 16/05/2022 to 25/05/2022 by the following members of field audit party of office of the Audit, Himachal Pradesh.

Name	Designation	Member from	Member till
LAXMI KANT	Sr. Audit Officer	11/05/2022	31/03/2026
Jagjeet Kumar	Assistant Audit Officer	13/09/2021	31/05/2043

The audit was supervised by the following officers.

Name	Designation	Effective from	Effective to
LAXMI KANT		11/05/2022	

1.Organisation:-Office of the Sr. Executive Engineer, Electrical Division, Himachal Pradesh State Electricity Board Limited (HPSEBL), Karsog broadly deals with the Operation, repairs and maintenance of the distribution system of electricity through various Sub-Divisions. Electrical sub-division along with maintenance of distribution system executes the work of granting of new connection and consumer billing.

2.Functional/Geographical jurisdiction:-For executing the above functions Sr. Executive Engineer, is having under its control five sub-divisions :

- (i) ESD, HPSEBL, Karsog.
- (ii) ESD, HPSEBL, Seri
- (iii) ESD, HPSEBL, Chhatri
- (iv) ESD, HPSEBL, Churaag
- (v) ESD, HPSEBL, Pangna

3. Staff Position: The sanctioned strength of staff vis-à-vis men-in-position of the office of the Sr. Executive Engineer, Electrical Division, HPSEB Ltd., Karsog as on 31 March 2022 is tabulated below :-

As on	Sanctioned Strength	Men-in-Position	Vacant
31 March 2021	278	152	126

4. Financial Indicators:-The budgeted vis-à-vis actual expenditure during 2019-20, 2020-21 and 2021-22 is tabulated below:

(₹ in lakh)

Year	Budget Allotment	Actual expenditure	Excess(+) /deficit(-)	%age
2018-19	2018-19	774.76	687.76	87
2019-20	2019-20	2343.68	1905.63	438.05
2020-21	2020-21	2031.36	2023.65	7.71

5.Implementing units: Five units viz.ESD, HPSEBL, Karsog, Pangna, Churaag, Seri and Chhatri.

6. Scope of Audit: The audit of Sr. Executive Engineer, Electrical Division, HPSEBL, Karsog was conducted for the period from April 2010 to March 2022 and that of implementing units viz. ESD, HPSEBL, Pangna for the period April 2011 to March 2022 and ESD, HPSEBL, Churrag for the period April 2007 to March 2022, covering operation, repairs & maintenance of distribution system and consumer billing.

The scope and objectives of compliance audit for the period from April 2010 to March 2022 were discussed with Sr. Executive Engineer, Electrical Division, HPSEB Ltd., Karsog in brief during entry meeting on 17th May 2022. The audit findings were discussed with Sr. Executive Engineer at the conclusion of audit on 18th June 2022.

Present audit was conducted from 17.05.2022 to 18.06.2022 by a team comprising of Sh. Laxmi Kant Walia, Sr. Audit Officer, Sh. Jagjeet Kumar, Asstt. Audit Officer and Sh. Datul Chauhan, Asstt. Supervisor.

Past Audit Coverage:- The previous audit covering period from April 2009 to March 2010 was conducted from 31.05.2010 to 07.06.2010 by a team comprising of Shri Beerendar Singh Chauhan, Asstt. Audit Officer. Sh. Nar Singh Chauhan and Rajinder Singh Mehta, Sr. Auditors.

7. Persistent Irregularities:

Nil

DISCLAIMER

The Compliance Audit and Inspection Report has been prepared on the basis of information furnished and made available by various sections of the office of the Sr. Executive Engineer, Electrical Division, HPSEBL, Karsog. The office of the Principal Accountant General (Audit) H.P., Shimla disclaims any responsibility for any misinformation and/or non-supply of information on the part of Auditee.

PART-II

(Audit Findings)

PART-II-(A)

(Significant Audit Findings)

PART-II-(B)

(Other incidental Audit Findings)

Para-1: Non-taking over of works executed by consumers-Rs.4.20 crore.

The HPSEBL undertakes electrical construction, works for Govt. departments, local bodies and other private organizations as deposit works. The instructions regarding deposit works stipulates that in case the applicant is willing to opt for getting the job done by himself (Self Execution) under the supervision of HPSEBL, the estimate-abstract of cost will also be submitted to the prospective consumer/applicant immediately after its sanction by the field unit for getting the 6.25 *per cent* departmental charges, 18 *per cent* GST and 1 *per cent* W.W.C. It was further directed that all such assets created against such works will be transferred by the applicant/prospective consumer after completion and commissioning of the

job, to the HPSEBL without value. The HPSEBL shall maintain these assets, ever since, thereafter, at its own cost and it will become a part of Board's assets.

Scrutiny of works records at Electrical Division Karsog, revealed that forty-four works of total cost of Rs. 4,19,85,180/- as detailed in Annexure-..... were executed under self-execution mode during the period between 2017-18 and 2021-22. It was further noticed that the field units had not initiated any action to take over the completed assets till the date of audit (May 2022) in contravention to instructions *ibid*. Due to non-taking over these works in HPSEBL assets list, these were not shown in asset list resultantly actual requirement of O&M expenses on these works could not be assessed. Due to non-capitalization of these works depreciation on these works has not been charged by the company. Timely capitalization is also important for charging depreciation on these completed projects and also important for presenting true and fair view of accounts. Moreover, due to non-capitalisation of these works the Company could not claim O&M expenses and depreciation of these assets through Annual Revenue Requirement presented to HPERC.

Reasons for non-taking over and non-capitalization of completed self-executed works may please be intimated to audit.

Para-2: Huge outstanding on account of energy bills-₹ 266.74 lakh.

The HPSEB Ltd. raises energy bills every month according to the schedule of tariff revised by the HPERC from time to time. Timely collection of assessed revenue is of utmost importance as any delay in realization of revenue results in gaps in cash flow of the Company. During scrutiny of revenue records of Electrical Division Karsog, it was noticed that at the end of March 2022 an amount of ₹ 266.74 lakh was lying outstanding (running arrear of revenue) from the various categories of consumers. The position of revenue outstanding during the period from 2018-19 to 2021-22 was as under:

(Amount ₹ in lakh)

Particulars	I&PH	Govt. Deptt.	S. Light	Domestic	Commercial	Industrial	Agri.	TMS	Total
2018-19	-5.90	1.84	0.14	106.16	31.95	2.47	0.12	0.03	136.81
2019-20	73.90	15.20	0	101.48	53.47	6.69	0.53	3.80	255.07
2020-21	69.87	3.75	0.35	19.87	13.98	2.39	0.20	1.52	111.93
2021-22	171.91	7.21	0.12	52.33	23.24	3.36	0.44	8.13	266.74

It is evident from the above table that at the end of financial year 2018-19 there were ₹136.81 lakh outstanding from the consumers but at end of financial year 2021-22, it increased to ₹266.74 lakh i.e an increase by 94.95%. Further audit noticed that arrears of I&PH Deptt. has increased from ₹ -5.90 lakh to ₹171.91 lakh between the period 2018-22. The Company being a commercial organization cannot afford such a heavy outstanding energy charges from consumers as Company is sustaining its working capital requirement by availing overdraft facility. This indicates that the field units had not exercised the proper checks to monitor the timely recovery of revenue from consumers which needs justification.

Para-3: Blockade of funds Rs.24011564/- in low voltage scheme

Himachal Pradesh State Electricity Board Ltd (HPSEBL) accorded (4 September 2019) expenditure sanction of Rs.158.10 crore to System Improvement scheme for Low Voltage (LV) pockets in Himachal Pradesh. As per current power distribution infrastructure in Himachal Pradesh particularly in the low voltage distribution system, supply at low voltages

alongwith long LT lines using smaller conductor sizes was prevalent which causes high line losses and voltage drop due to lengthy feeders. In order to address these issues, HPSEBL framed LV scheme. The scheme envisages provision of installation of new DTRs. 63 KVA to address the low voltage problems in far flung areas and to optimize the HT/LT ratio.

In order to implement the scheme in Electrical Division Karsog, the work orders for erection of LT lines and supply of materials were issued to the contractors. The 63 kva distribution transformers (DTR)/ stay wire/GI wire/ disc insulators/pin insulators were to be provided by HPSEBL. During the scrutiny of records, it was observed that the HPSEBL incurred an expenditure of Rs.2.40 crore (June 2022) for supply and erection of materials under low voltage scheme. However, the above works could not be fully completed and executed for want of 63 KVA DTRs/ stay wire/GI wire/ disc insulators/pin insulators. As the HPSEBL did not supply the 63 KVA transformers, the expenditure of Rs.2.40 crore incurred on LT Lines is blocked and materials is getting deteriorated day by day. Moreover, the objective of the LV schemes i.e. to reduce line losses and optimize HT/LT ratio could not be achieved so far (June 2022). In this regards, the reasons for non-completion of work and non-supply of materials by HPSEBL may be intimated to audit. Further, effective steps may be taken to reduce above losses under intimation to audit.

Para-4: Delay in providing SOP to LWSS Kashapadi Jujer Khad even after deposit of Rs.22.66 lakh

Irrigation and Public Health Department (Consumer) deposited Rs.22.66 lakh with HPSEBL (Company) on 29 March 2019 for providing SOP to LWSS Kashapadi Jujer Khad. During the scrutiny of records, it revealed that there were delay in issue of NIT and award to the contractor for release of SOP to the consumer. This is evident from the fact that the Company issued (8 August 2021) letter of award (LOA) to M/s Harish Bhardwaj (Contractor) for the supply of material for providing supply of power (SOP) after delay of more than 28 months. As per terms of LOA, the work was to be completed within one month from the date of issue of the LOA i.e. upto 10 September 2021.

Test check of records revealed that initially there was delay on the part of the Company for framing estimates, issue of LoA etc. hence work could not be completed in time. As such the company failed to provide SOP to LWSS Kashapadi Jujer Khad even after passing of more than 3 years.

Due to above delay the objective of the Company to ensure timely release of SOP to the consumer was not achieved. In this regard, the details of amount of loss incurred due to delay in completion of work may also be calculated and intimated to audit.

Para-5: Non-conducting the review of security deposit of the consumer resulting in shortfall of security deposit: ₹ 13.69 lakh.

According to stipulations contained in the “Himachal Pradesh Electricity Regulatory Commission (Security Deposit) Regulations, 2005”, the consumer shall, at all times maintain with the licensee an amount equivalent to consumption charges for the billing cycle period, as security during the period the agreement for supply of energy to such consumer remains in force. The adequacy of the amount of security deposit in respect of the consumers, shall be reviewed by the licensee generally once in every year based on the average consumption for the period representing 12 (twelve) months from April to March of the previous year. Based

on the review, the demand for shortfall will be made by the licensee. If there is any delay in payment, the consumer shall pay simple interest thereon at 12% per annum or at such rates as may be fixed by the Commission from time to time, without prejudice to the licensee's right to disconnect supply of electricity.

While scrutinising the records relating to security deposit of consumers under ED, HPSEBL, Karsog, it was noticed that based on average energy bill for the period of last 12 months in respect of the various consumers, there was shortage in security deposit by ₹ 13.69 lakh as detailed below:

S. No.	Name of Sub-Division	Average (2021-22)	ACD Deposited	Shortage in security deposit (In ₹)
1	ESD, HPSEBL, Karsog	49866.	30870	18996
2	ESD, HPSEBL, Seri	305440	18840	286600
3	ESD, HPSEBL, Churag (11 consumers of WPS)	1246344	241920	1004424
4	ESD, HPSEBL, Pangna	35173	5940	29233
5	ESD, HPSEBL, Chhatri	46860	16680	30180
	Total	1683683	314250	1369433

Reasons for non-review of the security deposit of the consumers in light of average consumption of the respective consumers may please be stated to audit.

Corrective action may be taken now and results be intimated to audit.

Para-6: Non recovery of excess expenditure incurred on deposit works- ₹ 6.84 lakh.

As per guidelines issued by the Himachal Pradesh State Electricity Board Ltd (HPSEBL) and Himachal Pradesh Electricity Regulatory Commission (HPERC), while preparing estimates for work regarding supply of power to consumer calculation of amount of cost of work should be done meticulously. It should also be ensured that when the work is in progress and by any unforeseen reasons the cost of work is to be increased, demand notice should be issued promptly to the consumer to deposit the amount.

During the scrutiny of deposit works records, it was noticed that Electrical Division Karsog, has incurred expenditure of ₹ 6,83,694/- over and above the deposited amount /sanctioned estimates for one deposit work. Audit noticed that an estimate of ₹ 61,48,430 was framed by ED Karsog for providing S.O.P. to LWSS Chaira Khud to Dhamoon Stage Ist, at Chaira, Stage IInd, at Kot and 3Ø Service connection to Stage IIIrd, at Chairidhar under (E) Sub-Division HPSEBL, Seri. The consumer had deposited amount of ₹ 51,16,910 through RTGS No. 404510 dated 23.03.2018 and ₹ 10,17,155 through RTGS vide UTR No. NEFTN19036613637 dated 05.02.2019. Scrutiny of records further revealed that Electrical Division Karsog, has incurred expenditure of ₹ 68,32,124 so far (May 2022) on this deposit work, which is ₹ 6,83,694/- over and above the deposited amount /sanctioned estimates.

Audit further noticed that the work was awarded to contractor during July 2019, however, as on May 2022 the work is still under progress and no action to recover the expenditure incurred by the HPSEBL from its own funds has been taken so far. The field units have not served any notice to the consumer to recover the expenditure incurred by the company from its own funds in accordance with the provisions of expenditure regulations of HPERC. It is pertinent to mention here that HPSEBL is already reeling under losses and it cannot afford to incur expenditure over and above the sanctioned estimates from its own funds.

Para-7: Material lying unused for more than one to five years ₹ 5.12 lakh.

According to instructions issued by the HPSEB Ltd., from time to time purchases should be made for the store by taking into account the needs and it should be ensured that material purchased should not become obsolete or unusable because of non-usage of material for a considerable period, if the material cannot be put to use in a particular area of operation possibilities should be explored to use it in another area of operation.

During the test check of stores records at Electrical Division Karsog, audit noticed that materials worth ₹ 46.89 lakh was lying in the Divisional store as on 31.03.2022 out of which material valuing ₹ 5.12 lakh /- was lying unused in the store for one to more than five years. Detail of some major material that was lying unused is as under:-

S. No.	Description of Material	One to more than five years	
		Oty. (Nos. and Mtrs.	Amount.
1	22 KV XLPE Cable 3 core 95 mm	269	238859
2	250 KVA Transformer (Repaired)	1	181831
3	Knee bracing Set.	55	29150

It is evident from the above that there is serious flaw in the material management resulting in blockade of funds of the Company worth ₹ 5.12 lakh. Efforts should be made to transfer the surplus material to other units of Company, since HPSEB Ltd., is a commercial organization managing its working capital requirement by availing overdraft facility at high rate of interest, it can't afford blockade of funds to this extent.

Matter may be looked in to and necessary action in this regard be initiated under intimation to audit.

Para-8: Non condemnation/ disposal of vehicle

Government of Himachal Pradesh, Department of Finance (Exp.) has circulated/ issued the revised instructions regarding condemnation and disposal of the vehicles vide letter No. Fin.-F (A)-(11)-11/2004 dated 07th September 2020, whereby the revised criteria for condemnation of vehicle has been modified, according to that when Cars of all make (s) has covered 2.50 lakh kilometres or 10 years of service, Jeeps of all make (s) has covered 3.00 lakh kilometres or 10 years of service, & Motorcycle (s) has 10 years of service or covered 70,000 kilometres, it should be condemned/ disposed of.

During test check of records of O/o the Sr. Executive Engineer, Electrical Division Karsog, it was noticed that the HP-26-0125 Tata 407 Pickup purchased in October 1996 has outlived its

life as per prescribed criteria as such it should have been condemned and disposed off. In this regard, the reasons for non-condemnation of vehicle may be intimated to audit.

Para-9: Less recovery of Low Voltage Supply Surcharge (LVSS): ₹ 0.27 lakh.

In the schedule of Tariff issued for every year by HPSEB Ltd it is stipulated that Consumer availing electricity supply at a voltage lower than the "Standard Supply Voltage" as specified under the relevant category, shall be charged a "Lower Voltage Supply Surcharge"(LVSS) at the specified rates only on amount of energy charges, billed, for each level of specified step down from the "Standard Supply Voltage" to the level of actually availed supply. Standard Supply voltage for commercial category consumer with connected load of more than 50 KW is specified as 11KV or 15 KV or 22KV. Further according to the said stipulation if such consumers are availing supply below 11 KV they are liable to pay LVSS @ 5%.

During the test check of consumer billing records at Electrical Sub-Division, Karsog, it was noticed that one Commercial Supply and one MIPS consumer with connected load above 50 KW was being supplied at LT supply and was liable to pay LVSS @ 5% of energy charges, but the same was recovered @ 2.5% from the consumer. Thus, from these consumers Low Voltage Supply Surcharge (LVSS) of ₹ 27,064/- were less recovered for the period December 2019 to May 2022 as detailed below:-

Name of consumer (Consumer ID)	Connected Load (in KW)	Contract Demand (in KVA)	Total consumption for the period	LVSS recovered @2.5%	LVSS to be recovered @5%	Less recovery of LVSS
The Manager HPTDC [REDACTED]	70.13	33	68277x4.85 =331143	8278	16557	8278
M/s Valley Extraction [REDACTED]	72	50	163358x4.60 =751446	18786	37572	18786
Total						27,064

Matter may be looked in to and necessary action in this regard be initiated under intimation to audit.

Para-10: Loss of revenue due to delay in construction of Chhatri sub-station

The office of ESD HPSEBL Karsog proposed for construction of new 33/22 KV, 2 x 1.6 MVA Sub-station, at Chhatri under Mandi circle with the objective to reduce large number of tripping in lengthy lines, and to ensure un-interrupted power supply to whole area under ESD Chhatri. More over due to commissioning of new sub-station, the Transmission & Distribution losses were also to be reduced by reducing length of LT as well as centralization of load.

Office of Chief Engineer (P&M) HPSEBL Shimla vide its office order dated 27 November 2018 accorded administrative approval amounting to Rs.6.88 crore to the 'System

Improvement scheme for new 33/22 KV, 2 x 1.6 MVA Sub-station, at Chhatri. M/s REC sanctioned (11 January 2019) financial assistance of Rs.5.85 crore to HPSEBL for system improvement scheme for construction of 2 x 1.6 MVA 33/22 KV sub-station Chhatri under ESD Karsog.

HPSEBL (Company) issued letter of award (LoA) to M/s T.S. Power Company, Arunachal Pradesh (Contractor) for construction of above Sub-station for total cost of Rs.2.70 crore. As per terms of the LoA, the work was to be completed upto 31 July 2021. It was noticed during audit that against the sanctioned amount of Rs.6.88 crore, the Company incurred an expenditure of Rs.7.18 crore upto 31 March 2022 and the work has not been completed so far (May 2022).

Due to delay in commissioning of sub-station, benefits envisaged at the time of their conceptualization, viz. additional revenue due to reduction in transmission and distribution loss, stable transmission and supply of quality power to consumers could not be derived. In this connection, following observations may be replied / justified to audit:-

As the company incurred Rs.7.18 crore against the sanctioned amount of Rs.6.88 crore, Copy of approval of excess expenditure may be shown to audit.

Reasons of delay in construction and commissioning of sub-station.

Details of LD deducted on account of delay in construction of sub-station.

Latest position of the case.

Para-11: Not adhering to the guidelines of Himachal Pradesh Distribution Code 2009 in respect of HT/LT Ratio

As per Himachal Pradesh Distribution Code 2009, Chapter – 3, para 3.13.4 the ratio of the lengths of HT and LT distribution lines for the new lines planned shall be 1:1 by adopting measures such as High Voltage Distribution System and the existing distribution system shall be modified in a phased manner to reduce distribution losses and problem of low voltage supply to consumers. Long distance LT lines without provision of transformers at adequate spacing are the main cause of line losses, LT faults and failure of Distribution Transformers.

During audit it was noticed that this office had failed to comply with the guidelines of Himachal Pradesh Distribution Code 2009 by reducing HT/LT ratio to 1:1. However, during this period, Government had launched various schemes i.e. DDUGJY and System Improvement Schemes with the objective of improvement of HT/LT line ratio and reduction T&D/AT&C losses.

The HT/LT ratio during the last three years ending March 2022 as detailed below:-

Year	HT Lines (kms)	LT Lines (kms)	HT/LT Ratio
2019-20	628.841	1887.942	1: 3
2020-21	525.470	1477.754	1: 2.8
2021-22	558.143	1490.940	1: 2.7

From above table, it can be seen that length of LT line was more than that of HT, consequently ratio of HT / LT lines was not as per the standard fixed by HPSEBL, which was one of the reasons for higher T&D losses. The main reason for non-achievement of 1:1 ratio of HT / LT lines was non conversion of LT lines into HT lines and non-construction of

adequate HT lines. Adequate steps for achieving the reduction in T&D losses may be taken by improving the ratio of HT / LT lines, under intimation to Audit.

Para-12: Increase in defective DTRs Meters

As per Para 8.2 of supply code 2009 issued by Himachal Pradesh Electricity Regulatory Commission, to prevent/discourage theft and unauthorized use of electricity and initiate effective energy audit, energy meters should be installed on Distribution Transformers (DTRs). Thus, if the energy meter is defective then *ibid* purpose could not be served in true manner hence the same should be replaced at the earliest possible time.

In Electrical Division, HPSEBL, Karsog, 1120 DTRs Meter were installed under various schemes viz. Rajiv Gandhi Gramin Vidhyutikaran Yojana and General Service Connection Schemes for System improvement and Strengthening of power supply which would help in reduction of technical loss. However, there was huge number of defective meters as tabulated below:-

Month	Total DTRs	Meters in working order	Defective Meters	Defective Meter Percentage (%)
03/2020	410	175	235	57.32
03/2021	345	148	197	57.10
03/2022	365	196	169	46.30
	1120	519	601	

From the above table, it is clearly evident that for the last three years the percentage of defective meters were ranged between 46% to 57%, the same should be replaced at the earliest for effective energy audit and identification of excess loss prone areas. Further in fourth Annual performance Review (APR) Order- 3rd MYT Control Period (FY15 - FY19) HPSEBL informed the Commission that as on 31.12.2017 there are 30,162 number of installed DTR meters in HP out of which 8140 DTR meters are defective. The same are targeted to be replaced within six months and Chairman directed the HPSEBL to replace all the defective meters on war footing. Audit noted that the concerned office failed to replace above mentioned defective DTRs meter thus defeating the purpose of scheme under which meters were installed and further resulted in unfruitful expenditure on above defective meter.

The reason for non-replacement of above DTR meters in prompt manner along with the action taken on the matter may be intimated to audit .

Para-13: Excessive Aggregate Technical & Commercial losses

Government of India Ministry of Power (MoP) fixed target of Aggregate Technical & Commercial (AT & C) losses of 10 *per cent* for the year 2019-20 and 2020-21. During scrutiny of records of Karsog division office HPSEBL relating to AT & C losses for the period 2020-22 it was observed that against the target of AT&C losses of 10 *per cent* during the above period, actual losses under the ED Karsog were on higher side as detailed below:

Period	Energy received	Energy sold	Energy Loss (2-3)	Actual T&D losses (4/2*100)	Assessment	Realization	Collection efficiency (7/6)	Units realized (8*3)	AT & C losses
1	2	3	4	5	6	7	8	9	10
2019-20	36638586	25152488	11486098	31.35%	147129223	133193352	90.5%	20216980	24.48%

2020-21	31792462	24211803.00	7580659	23.84%	145674200.7	146203015.8	100.4%	24299695	23.57%
2021-22	33646766	24415608	9231158	27.44%	152271063.6	144772321.1	95.1%	23213237	31.01%

From the above it could be seen that there were increase in AT & C losses in 2021-22 whereas it was 23.57% in 2020-21. Therefore, due to high incidence of AT & C losses in , Karsog, HPSEBL had to suffer loss of revenue due to excessive AT & C losses than the target. Reasons for increase in AT & C losses may be intimated to audit. Effective steps may be taken to reduce above losses under intimation to audit.

PART-III

(Follow up on findings outstanding of previous Inspection Reports)

Audit & Inspection Report for the year 2008-09

Para-2 Non-following the technical guidelines as well as order regarding erection of steel tubular poles of the value of Rs.184.48 lakhs thereby depriving of longer life and proper/upright position of STPs

Management in its reply stated that as per the direction of audit party now all the STPs are being erected with muffs and cement concrete mix. The facts have been verified locally. As the division office comply with the observations raised in para, the para settled.

Audit & Inspection Report for the year 2009-10

Para 4: Non-conducting of MRI of 3 phase energy meters

Management in its reply stated that during the particular period MRI facility was not available in ED Karsog. Now all the consumers having connected load above 20 KW, the reading is being done with MRI and consumers are being billed accordingly. The facts have been verified locally. In view of reply and facts verification, the para is settled.

PART-IV (Best Practice)

Nil

PART-V (Acknowledgement)

We would like to express our thanks to the staff of the office of the Sr. Executive Engineer, Electrical Division HPSEBL, Karsog for their co-operation in all the matters including production of records called for in audit. All the minor points were settled on the spot as per assurance given by Sr. Executive Engineer, Electrical Division HPSEBL, Karsog.