

PROPERTY INSPECTION FORM

Property Intelligence System
AI-Assisted Field Inspection Report

PROPERTY DETAILS

Property address
City / State / ZIP

Builder / Owner **Texas Homes**
Year built **2006**
Sq ft **2201**
Beds **4**
Baths **3**

Inspector name **Mark Bill**
License no. **286947**
Inspection date **06/28/2026**
Time **14:00 CT**

Overall condition score (circle): 1 2 3 4 5 6 7 8 9 10

1. FLOORING ASSESSMENT

1.1 Floor Type

- | | |
|---|---|
| ☐ Solid hardwood | ☒ Engineered hardwood |
| ☐ Luxury vinyl plank (LVP) | ☐ Ceramic / porcelain tile |
| ☐ Carpet | ☐ Laminate |
| ☐ Concrete / polished | ☐ Other (specify in notes) |

Notes / observations:

1.2 Floor Condition

- | | |
|---|---|
| ☐ Excellent — no visible wear | ☐ Good — minor surface scratches |
| ☐ Fair — moderate wear / dull finish | ☐ Poor — deep scratches / staining |
| ☒ Warping / cupping present | ☐ Gaps between boards |
| ☐ Loose / squeaky boards | ☒ Water damage visible |

Notes / observations:

1.3 Estimated Floor Age

- | | |
|---|--------------------------------------|
| ☐ 0-5 years | ☐ 6-10 years |
| ☒ 11-20 years | ☐ 21-30 years |
| ☐ 30+ years | ☐ Unknown |

Recommended action:

2. WOOD QUALITY ASSESSMENT

2.1 Wood Species (If applicable)

- | | |
|--|---|
| ☐ Red / white oak | ☐ Maple |
| ☒ Walnut | ☐ Cherry |
| ☐ Pine | ☐ Bamboo |
| ☐ Unknown species | ☐ Not applicable |

Notes / observations:

2.2 Wood Grade

- | | |
|--|---|
| ☐ Select grade (fewest knots) | ☐ No. 1 Common |
| ☐ No. 2 Common | ☐ Rustic / cabin grade |
| ☒ Mixed / inconsistent grade | ☐ Unable to determine |

Notes / observations:

2.3 Finish & Sealing

- | | |
|--|--|
| ☐ Well sealed — no penetration | ☐ Lightly sealed |
| ☐ Finish worn through in places | ☐ Unfinished / bare wood |
| ☐ Wax finish | ☒ Oil finish |
| ☐ Polyurethane finish | ☐ Refinishing recommended |

Notes / observations:

3. WALLS & PAINT

3.1 Paint Condition

- | | |
|---|--|
| ☐ Fresh / excellent | ☐ Good — minor scuffs |
| ☐ Fair — fading / patches | ☒ Poor — peeling / flaking |
| ☐ Water stains present | ☐ Mold / mildew visible |
| ☒ Cracks in walls | ☐ Full repaint required |

Notes / observations:

3.2 Wall Material

- | | |
|---|--|
| ☐ Drywall / gypsum | ☐ Plaster |
| ☒ Brick / exposed masonry | ☐ Wood paneling |
| ☐ Tile (bathroom / kitchen) | ☐ Mixed materials |

Notes / observations:

4. ROOF CONDITION

4.1 Roofing Material

- ☐ Asphalt shingles
- ☐ Clay / concrete tile
- ☐ Flat / membrane (TPO / EPDM)

- ☐ Metal / steel
- ☒ Wood shake / shingle
- ☐ Unknown

Notes / observations:

4.2 Roof Condition

- ☐ Excellent — no visible damage
- ☒ Fair — granule loss / aging
- ☐ Missing shingles present
- ☐ Gutters damaged / blocked
- ☐ Good — minor wear
- ☐ Poor — curling / cracking
- ☒ Active leak signs
- ☐ Full replacement recommended

Notes / observations:

5. HVAC & MECHANICAL SYSTEMS

5.1 HVAC System Age

- ☐ 0–5 years
- ☒ 11–15 years
- ☐ 20+ years (end of life)
- ☐ 6–10 years
- ☐ 16–20 years
- ☐ Unknown

Notes / observations:

5.2 HVAC Condition

- ☐ Fully operational
- ☐ Inefficient — high energy use
- ☐ Not cooling / heating properly
- ☐ Operational — minor issues
- ☒ Noisy / vibrating
- ☐ Replacement recommended

Notes / observations:

6. KITCHEN & BATHROOM

6.1 Kitchen Condition

- ☐ Updated — modern finishes
- ☒ Cabinets need refacing / replacing
- ☐ Appliances outdated
- ☐ Ventilation inadequate
- ☐ Functional — dated style
- ☒ Countertops worn / damaged
- ☐ Plumbing issues present
- ☐ Full remodel recommended

Notes / observations:

6.2 Bathroom Condition

- ☐ Excellent — updated fixtures
- ☐ Fair — dated vanity / tiles
- ☒ Water damage around tub / shower
- ☐ Good — clean and functional
- ☒ Grout / caulk deteriorating
- ☐ Ventilation fan missing / broken

☐ Toilet / sink issues

☐ Full renovation recommended

Notes / observations:

7. EXTERIOR & CURB APPEAL

7.1 Exterior Condition

☐ Excellent — well maintained

☐ Good — minor touch-ups needed

☒ Siding damaged / faded

☐ Brickwork / mortar deteriorating

☐ Window frames rotting / cracked

☒ Entry door needs replacement

☐ Garage door worn

☐ Stone veneer / cladding loose

Notes / observations:

8. RENOVATION COST ESTIMATE (INSPECTOR)


Renovation item	Priority	Est. cost (\$)	Value uplift (\$)	ROI (%)
Roof replacement	1	8000 - 10,000 USD	1.40x	140%
HVAC system	1	5000 - 10,000 USD	1.20x	120%
Kitchen remodel	2	9000 - 18,000 USD	1.50x	150%
Bathroom updates	2	5000 - 10,000 USD	1.25x	125%
Flooring refinish	2	4000 - 9,000 USD	1.42x	142%
Exterior / curb appeal	1	3000 - 7000 USD	1.50x	150%
Paint (interior)	2	1000 - 3000 USD	1.52x	152%
Other				
TOTAL				

9. INSPECTOR SIGN-OFF

Inspector signature

Date

Company stamp



06/28/2026