

The 10 Debugging commandments

- I. Understand the system
- II. Make it fail
- III. Quit Thinking and Look
- IV. Divide and Conquer
- V. Change one Thing at a Time
- VI. Keep an Audit Trail
- VII. Check the Plug
- VIII. Get a fresh View
- IX. Double check it really is fixed
- X. Make it easy to debug