

Laboratory Safety SOP

Version 2.0 · Effective: January 10, 2023

Personal Protective Equipment

Lab coats must be worn at all times in the Wet Labs. Safety goggles are required when handling corrosive reagents.

Emergency Equipment

Eyewash stations must be tested weekly by the duty technician. The facility is staffed by 3 safety officers.

Spill Response

Chemical spills larger than 500 mL must be reported to the Safety Officer within 15 minutes of discovery.