

<b>FeatureFlag_Validation</b>		Computer name	Language
Execution time	Operating system	Screen dimension	Duration
05-12-2019 02:52:59	Windows 10 64bit	FSWIRAY23	en-GB
		1600x900	1.7h
 41 x Success 41 x Failed	Total warnings <b>0</b>	Total errors <b>41</b>	

## Table of Contents

■ FeatureFlag_Validation_Folder.....	6
■ FeatureFlag_Validation_Folder.....	6
■ Installing_Builds.....	6
■ Installation.....	6
■ Verifying_Feature_Availability.....	7
■ ValidatingXML_And_Excel.....	7
■ [TEARDOWN].....	8
■ FeatureFlag_Validation_Folder.....	8
■ Installing_Builds.....	8
■ Installation.....	8
■ Verifying_Feature_Availability.....	9
■ ValidatingXML_And_Excel.....	9
■ [TEARDOWN].....	10
■ FeatureFlag_Validation_Folder.....	10
■ Installing_Builds.....	11
■ Installation.....	11
■ Verifying_Feature_Availability.....	12
■ ValidatingXML_And_Excel.....	12
■ [TEARDOWN].....	13
■ FeatureFlag_Validation_Folder.....	13
■ Installing_Builds.....	13
■ Installation.....	13
■ Verifying_Feature_Availability.....	14
■ ValidatingXML_And_Excel.....	14
■ [TEARDOWN].....	15
■ FeatureFlag_Validation_Folder.....	15
■ Installing_Builds.....	15
■ Installation.....	15
■ Verifying_Feature_Availability.....	16
■ ValidatingXML_And_Excel.....	16
■ [TEARDOWN].....	18
■ FeatureFlag_Validation_Folder.....	18
■ Installing_Builds.....	18
■ Installation.....	18
■ Verifying_Feature_Availability.....	19
■ ValidatingXML_And_Excel.....	19
■ [TEARDOWN].....	20
■ FeatureFlag_Validation_Folder.....	20

■	Installing_Builds.....	20
■	Installation.....	20
■	Verifying_Feature_Availability.....	21
■	■ ValidatingXML_And_Excel.....	21
■	[TEARDOWN].....	23
■	FeatureFlag_Validation_Folder.....	23
■	Installing_Builds.....	23
■	Installation.....	23
■	Verifying_Feature_Availability.....	24
■	■ ValidatingXML_And_Excel.....	24
■	[TEARDOWN].....	25
■	FeatureFlag_Validation_Folder.....	25
■	Installing_Builds.....	25
■	Installation.....	25
■	Verifying_Feature_Availability.....	26
■	■ ValidatingXML_And_Excel.....	26
■	[TEARDOWN].....	27
■	FeatureFlag_Validation_Folder.....	27
■	Installing_Builds.....	28
■	Installation.....	28
■	Verifying_Feature_Availability.....	29
■	■ ValidatingXML_And_Excel.....	29
■	[TEARDOWN].....	30
■	FeatureFlag_Validation_Folder.....	30
■	Installing_Builds.....	30
■	Installation.....	30
■	Verifying_Feature_Availability.....	31
■	■ ValidatingXML_And_Excel.....	31
■	[TEARDOWN].....	32
■	FeatureFlag_Validation_Folder.....	32
■	Installing_Builds.....	33
■	Installation.....	33
■	Verifying_Feature_Availability.....	34
■	■ ValidatingXML_And_Excel.....	34
■	[TEARDOWN].....	35
■	FeatureFlag_Validation_Folder.....	35
■	Installing_Builds.....	35
■	Installation.....	35
■	Verifying_Feature_Availability.....	36
■	■ ValidatingXML_And_Excel.....	36
■	[TEARDOWN].....	37
■	FeatureFlag_Validation_Folder.....	37
■	Installing_Builds.....	37
■	Installation.....	37
■	Verifying_Feature_Availability.....	38
■	■ ValidatingXML_And_Excel.....	38
■	[TEARDOWN].....	40
■	FeatureFlag_Validation_Folder.....	40
■	Installing_Builds.....	40
■	Installation.....	40
■	Verifying_Feature_Availability.....	41
■	■ ValidatingXML_And_Excel.....	41
■	[TEARDOWN].....	42
■	FeatureFlag_Validation_Folder.....	42
■	Installing_Builds.....	42
■	Installation.....	42
■	Verifying_Feature_Availability.....	43
■	■ ValidatingXML_And_Excel.....	43

■ [TEARDOWN].....	45
■ FeatureFlag_Validation_Folder.....	45
■ Installing_Builds.....	45
■ Installation.....	45
■ Verifying_Feature_Availability.....	46
■ ValidatingXML_And_Excel.....	46
■ [TEARDOWN].....	47
■ FeatureFlag_Validation_Folder.....	47
■ Installing_Builds.....	47
■ Installation.....	47
■ Verifying_Feature_Availability.....	48
■ ValidatingXML_And_Excel.....	48
■ [TEARDOWN].....	49
■ FeatureFlag_Validation_Folder.....	49
■ Installing_Builds.....	50
■ Installation.....	50
■ Verifying_Feature_Availability.....	51
■ ValidatingXML_And_Excel.....	51
■ [TEARDOWN].....	52
■ FeatureFlag_Validation_Folder.....	52
■ Installing_Builds.....	52
■ Installation.....	52
■ Verifying_Feature_Availability.....	53
■ ValidatingXML_And_Excel.....	53
■ [TEARDOWN].....	54
■ FeatureFlag_Validation_Folder.....	54
■ Installing_Builds.....	55
■ Installation.....	55
■ Verifying_Feature_Availability.....	56
■ ValidatingXML_And_Excel.....	56
■ [TEARDOWN].....	57
■ FeatureFlag_Validation_Folder.....	57
■ Installing_Builds.....	57
■ Installation.....	57
■ Verifying_Feature_Availability.....	58
■ ValidatingXML_And_Excel.....	58
■ [TEARDOWN].....	59
■ FeatureFlag_Validation_Folder.....	59
■ Installing_Builds.....	59
■ Installation.....	59
■ Verifying_Feature_Availability.....	60
■ ValidatingXML_And_Excel.....	60
■ [TEARDOWN].....	62
■ FeatureFlag_Validation_Folder.....	62
■ Installing_Builds.....	62
■ Installation.....	62
■ Verifying_Feature_Availability.....	63
■ ValidatingXML_And_Excel.....	63
■ [TEARDOWN].....	64
■ FeatureFlag_Validation_Folder.....	64
■ Installing_Builds.....	64
■ Installation.....	64
■ Verifying_Feature_Availability.....	65
■ ValidatingXML_And_Excel.....	65
■ [TEARDOWN].....	67
■ FeatureFlag_Validation_Folder.....	67
■ Installing_Builds.....	67
■ Installation.....	67

■ Verifying_Feature_Availability.....	68
■ ValidatingXML_And_Excel.....	68
■ [TEARDOWN].....	69
■ FeatureFlag_Validation_Folder.....	69
■ Installing_Builds.....	69
■ Installation.....	69
■ Verifying_Feature_Availability.....	70
■ ValidatingXML_And_Excel.....	70
■ [TEARDOWN].....	72
■ FeatureFlag_Validation_Folder.....	72
■ Installing_Builds.....	72
■ Installation.....	72
■ Verifying_Feature_Availability.....	73
■ ValidatingXML_And_Excel.....	73
■ [TEARDOWN].....	74
■ FeatureFlag_Validation_Folder.....	74
■ Installing_Builds.....	74
■ Installation.....	74
■ Verifying_Feature_Availability.....	75
■ ValidatingXML_And_Excel.....	75
■ [TEARDOWN].....	76
■ FeatureFlag_Validation_Folder.....	76
■ Installing_Builds.....	77
■ Installation.....	77
■ Verifying_Feature_Availability.....	78
■ ValidatingXML_And_Excel.....	78
■ [TEARDOWN].....	79
■ FeatureFlag_Validation_Folder.....	79
■ Installing_Builds.....	79
■ Installation.....	79
■ Verifying_Feature_Availability.....	80
■ ValidatingXML_And_Excel.....	80
■ [TEARDOWN].....	81
■ FeatureFlag_Validation_Folder.....	81
■ Installing_Builds.....	82
■ Installation.....	82
■ Verifying_Feature_Availability.....	83
■ ValidatingXML_And_Excel.....	83
■ [TEARDOWN].....	84
■ FeatureFlag_Validation_Folder.....	84
■ Installing_Builds.....	84
■ Installation.....	84
■ Verifying_Feature_Availability.....	85
■ ValidatingXML_And_Excel.....	85
■ [TEARDOWN].....	86
■ FeatureFlag_Validation_Folder.....	86
■ Installing_Builds.....	86
■ Installation.....	86
■ Verifying_Feature_Availability.....	87
■ ValidatingXML_And_Excel.....	87
■ [TEARDOWN].....	89
■ FeatureFlag_Validation_Folder.....	89
■ Installing_Builds.....	89
■ Installation.....	89
■ Verifying_Feature_Availability.....	90
■ ValidatingXML_And_Excel.....	90
■ [TEARDOWN].....	91
■ FeatureFlag_Validation_Folder.....	91

■	Installing_Builds.....	91
■	Installation.....	91
■	Verifying_Feature_Availability.....	92
■	■ ValidatingXML_And_Excel.....	92
■	[TEARDOWN].....	94
■	FeatureFlag_Validation_Folder.....	94
■	Installing_Builds.....	94
■	Installation.....	94
■	Verifying_Feature_Availability.....	95
■	■ ValidatingXML_And_Excel.....	95
■	[TEARDOWN].....	96
■	FeatureFlag_Validation_Folder.....	96
■	Installing_Builds.....	96
■	Installation.....	96
■	Verifying_Feature_Availability.....	97
■	■ ValidatingXML_And_Excel.....	97
■	[TEARDOWN].....	98
■	FeatureFlag_Validation_Folder.....	98
■	Installing_Builds.....	99
■	Installation.....	99
■	Verifying_Feature_Availability.....	100
■	■ ValidatingXML_And_Excel.....	100
■	[TEARDOWN].....	101
■	FeatureFlag_Validation_Folder.....	101
■	Installing_Builds.....	101
■	Installation.....	101
■	Verifying_Feature_Availability.....	102
■	■ ValidatingXML_And_Excel.....	102
■	[TEARDOWN].....	103
■	FeatureFlag_Validation_Folder.....	103
■	Installing_Builds.....	104
■	Installation.....	104
■	Verifying_Feature_Availability.....	105
■	■ ValidatingXML_And_Excel.....	105
■	[TEARDOWN].....	106

	<b>FeatureFlag_Validation_Folder</b>	Rows: 41	1.7h	
	<b>FeatureFlag_Validation_Folder</b>	Data Row: 1	2.6m	

**Marketname:** United Kingdom

**BuildName:** ReSound Smart Fit 1.6.0.184

<b>Installing_Builds</b>				1.5m	
Installation				1.5m	
Time	Level	Category	Message		
00:00.042	Info	Data	Current variable values:  \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'United Kingdom'		
00:00.082	Info	Delay	Waiting for 10s.		
00:10.362	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.		
00:12.246	Info	Delay	Waiting for 3s.		
00:15.275	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.		
00:20.552	Info	Delay	Waiting for 2s.		
00:22.577	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.		
00:23.284	Info	Delay	Waiting for 2s.		
00:25.321	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.		
00:26.065	Info	Delay	Waiting for 2s.		
00:28.096	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgree' at Center.		
00:28.784	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.		
00:29.500	Info	Delay	Waiting for 3s.		
00:32.525	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.		
00:33.232	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.		
00:33.930	Info	Mouse	Mouse scroll Vertical by 600 units.		
00:34.274	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.		
00:35.216	Info	Delay	Waiting for 2s.		
00:37.253	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.		
00:37.970	Info	Delay	Waiting for 3s.		
00:40.991	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.		

00:41.703	Info	Delay	Waiting for 3s.
00:58.803	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
00:59.503	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
01:31.200	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
01:31.308	Success	Validation	Element for item 'ButtonFinish' does exist. 
01:31.340	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m ↑

### ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
01:32.038	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'United Kingdom', \$TxtKey = 'United Kingdom', \$TxtValue = 'United Kingdom', \$TxtMarket = 'United Kingdom'
01:32.834	Success	User	Pass :undoredo-master- True = ON 
01:32.857	Success	User	Pass :pediatrics-master- True = ON 
01:32.889	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
01:32.907	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
01:32.983	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
01:33.007	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 
01:33.023	Success	User	Pass :offline-firmware-update-master- True = ON 
01:33.039	Success	User	Pass :fitting-rules-master- True = ON 
01:33.056	Success	User	Pass :autorem-master- True = ON 
01:41.179	Info	Delay	Waiting for 10s.

01:51.217	Info	Delay	Waiting for 10s.
02:09.344	Info	Delay	Waiting for 10s. 
02:27.450	Info	Delay	Waiting for 6s. 
02:33.497	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms ↑

### 📁 FeatureFlag\_Validation\_Folder

Data Row: 2

2.5m ↑

**Marketname:** United States

**BuildName:** ReSound Smart Fit 1.6.0.184

## 🎬 Installing\_Builds

1.5m ↑

### 🎥 Installation

1.5m ↑

Time	Level	Category	Message
02:33.622	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'United States'
02:33.639	Info	Delay	Waiting for 10s.
02:43.722	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
02:44.530	Info	Delay	Waiting for 3s.
02:47.567	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
02:50.668	Info	Delay	Waiting for 2s.
02:52.695	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
02:53.381	Info	Delay	Waiting for 2s.
02:55.417	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.

02:56.136	Info	Delay	Waiting for 2s.
02:58.168	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
02:58.850	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
02:59.535	Info	Delay	Waiting for 3s.
03:02.564	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
03:03.267	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
03:03.965	Info	Mouse	Mouse scroll Vertical by 600 units.
03:04.300	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
03:05.234	Info	Delay	Waiting for 2s.
03:07.268	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
03:07.963	Info	Delay	Waiting for 3s.
03:10.996	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
03:11.700	Info	Delay	Waiting for 3s.
03:28.810	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
03:29.518	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
04:01.308	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
04:01.432	Success	Validation	Element for item 'ButtonFinish' does exist. ✓
04:01.479	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
04:02.186	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'United States', \$TxtKey = 'United States', \$TxtValue = 'United States', \$TxtMarket = 'United States'
04:03.297	Success	User	Pass :undoredo-master- True = ON ✓

04:03.324	Success	User	Pass :pediatrics-master- True = ON
04:03.355	Success	User	Pass :teleaudiology-master- True = ON
04:03.373	Success	User	Pass :teleaudiology-video-fsw- True = ON
04:03.405	Success	User	Pass :teleaudiology-fitting-fsw- True = ON
04:03.422	Failure	User	Fail :teleaudiology-tsgrestricted-fsw : FeatureFlag Value of Flag file is :true -and Excel File is :Off
04:03.439	Success	User	Pass :offline-firmware-update-master- True = ON
04:03.455	Success	User	Pass :fitting-rules-master- True = ON
04:03.472	Success	User	Pass :autorem-master- True = ON
04:11.653	Info	Delay	Waiting for 10s.
04:21.678	Info	Delay	Waiting for 10s.
04:39.804	Info	Delay	Waiting for 10s. 
04:57.955	Info	Delay	Waiting for 6s. 
05:04.002	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms ↑

### FeatureFlag\_Validation\_Folder

Data Row: 3

2.5m ↑

**Marketname:** Australia

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m

### Installation

1.5m

Time	Level	Category	Message
05:04.145	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Australia'
05:04.172	Info	Delay	Waiting for 10s.
05:14.243	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
05:15.082	Info	Delay	Waiting for 3s.
05:18.109	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
05:21.269	Info	Delay	Waiting for 2s.
05:23.301	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
05:24.003	Info	Delay	Waiting for 2s.
05:26.036	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
05:26.733	Info	Delay	Waiting for 2s.
05:28.765	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
05:29.483	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
05:30.201	Info	Delay	Waiting for 3s.
05:33.224	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
05:33.931	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
05:34.630	Info	Mouse	Mouse scroll Vertical by 600 units.
05:34.966	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
05:35.664	Info	Delay	Waiting for 2s.
05:37.696	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
05:38.398	Info	Delay	Waiting for 3s.
05:41.427	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
05:42.118	Info	Delay	Waiting for 3s.
05:59.208	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
05:59.905	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
06:31.683	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.

06:31.780	Success	Validation	Element for item 'ButtonFinish' does exist.
06:31.806	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m ↑

### ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
06:32.510	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Australia', \$TxtKey = 'Australia', \$TxtValue = 'Australia', \$TxtMarket = 'Australia'
06:33.286	Success	User	Pass :undoredo-master- True = ON
06:33.306	Success	User	Pass :pediatrics-master- True = ON
06:33.338	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
06:33.355	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
06:33.388	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
06:33.405	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
06:33.438	Success	User	Pass :offline-firmware-update-master- True = ON
06:33.455	Success	User	Pass :fitting-rules-master- True = ON
06:33.488	Success	User	Pass :autorem-master- True = ON
06:41.577	Info	Delay	Waiting for 10s.
06:51.622	Info	Delay	Waiting for 10s.
07:09.770	Info	Delay	Waiting for 10s. 

07:27.908	Info	Delay	Waiting for 6s. 
07:33.966	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder

Data Row: 4

2.5m 

**Marketname:** Austria

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m 

### Installation

1.5m 

Time	Level	Category	Message
07:34.103	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Austria'
07:34.134	Info	Delay	Waiting for 10s.
07:44.236	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
07:45.083	Info	Delay	Waiting for 3s.
07:48.107	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
07:51.184	Info	Delay	Waiting for 2s.
07:53.214	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
07:53.901	Info	Delay	Waiting for 2s.
07:55.937	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
07:56.646	Info	Delay	Waiting for 2s.
07:58.678	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
07:59.380	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
08:00.119	Info	Delay	Waiting for 3s.

08:03.149	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
08:03.846	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
08:04.581	Info	Mouse	Mouse scroll Vertical by 600 units.
08:04.915	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
08:05.613	Info	Delay	Waiting for 2s.
08:07.651	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
08:08.343	Info	Delay	Waiting for 3s.
08:11.374	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
08:12.067	Info	Delay	Waiting for 3s.
08:29.156	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
08:29.871	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
09:01.088	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
09:01.198 ✓	Success	Validation	Element for item 'ButtonFinish' does exist.
09:01.222	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
09:01.938	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Austria', \$TxtKey = 'Austria', \$TxtValue = 'Austria', \$TxtMarket = 'Austria'
09:03.047 ✓	Success	User	Pass :undoredo-master- True = ON
09:03.077 ✓	Success	User	Pass :pediatrics-master- True = ON
09:03.106 ✗	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
09:03.140 ✗	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON

09:03.182	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
09:03.221	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
09:03.237	Success	User	Pass :offline-firmware-update-master- True = ON
09:03.281	Success	User	Pass :fitting-rules-master- True = ON
09:03.321	Success	User	Pass :autorem-master- True = ON
09:11.468	Info	Delay	Waiting for 10s.
09:21.498	Info	Delay	Waiting for 10s.
09:39.638	Info	Delay	Waiting for 10s. 
09:57.751	Info	Delay	Waiting for 6s. 
10:03.779	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder

Data Row: 5

2.5m 

**Marketname:** Belgium

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m 

### Installation

1.5m 

Time	Level	Category	Message
10:03.922	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Belgium'

10:03.955	Info	Delay	Waiting for 10s.
10:14.069	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
10:14.896	Info	Delay	Waiting for 3s.
10:17.926	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
10:21.050	Info	Delay	Waiting for 2s.
10:23.082	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
10:23.769	Info	Delay	Waiting for 2s.
10:25.802	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
10:26.534	Info	Delay	Waiting for 2s.
10:28.565	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
10:29.263	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
10:29.970	Info	Delay	Waiting for 3s.
10:32.989	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
10:33.696	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
10:34.399	Info	Mouse	Mouse scroll Vertical by 600 units.
10:34.741	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
10:35.431	Info	Delay	Waiting for 2s.
10:37.464	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
10:38.160	Info	Delay	Waiting for 3s.
10:41.190	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
10:41.898	Info	Delay	Waiting for 3s.
10:58.981	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
10:59.684	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
11:31.260	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
11:31.368	Success	Validation	Element for item 'ButtonFinish' does exist. 
11:31.388	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

## ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
11:32.081	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Belgium', \$TxtKey = 'Belgium', \$TxtValue = 'Belgium', \$TxtMarket = 'Belgium'
11:32.835	Success	User	Pass :undoredo-master- True = ON ✓
11:32.856	Success	User	Pass :pediatrics-master- True = ON ✓
11:32.904	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON ✗
11:32.939	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON ✗
11:32.971	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON ✗
11:33.005	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF ✓
11:33.021	Success	User	Pass :offline-firmware-update-master- True = ON ✓
11:33.055	Success	User	Pass :fitting-rules-master- True = ON ✓
11:33.073	Success	User	Pass :autorem-master- True = ON ✓
11:41.385	Info	Delay	Waiting for 10s.
11:51.409	Info	Delay	Waiting for 10s.
12:09.591	Info	Delay	Waiting for 10s. 
12:27.718	Info	Delay	Waiting for 6s. 

12:33.780	Error	Module	The module has failed because one or more actions have failed. 
-----------	-------	--------	--

## TEARDOWN

2ms 

### FeatureFlag\_Validation\_Folder Data Row: 6

**Marketname:** Brazil

**BuildName:** ReSound Smart Fit 1.6.0.184

### Installing\_Builds

1.4m 

#### Installation

1.4m 

Time	Level	Category	Message
12:33.944	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Brazil'
12:33.972	Info	Delay	Waiting for 10s.
12:44.063	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
12:44.884	Info	Delay	Waiting for 3s.
12:47.912	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
12:50.917	Info	Delay	Waiting for 2s.
12:52.942	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
12:53.632	Info	Delay	Waiting for 2s.
12:55.660	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
12:56.364	Info	Delay	Waiting for 2s.
12:58.399	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
12:59.099	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
12:59.833	Info	Delay	Waiting for 3s.
13:02.860	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
13:03.578	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
13:04.296	Info	Mouse	Mouse scroll Vertical by 600 units.

13:04.628	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
13:05.314	Info	Delay	Waiting for 2s.
13:07.340	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
13:08.048	Info	Delay	Waiting for 3s.
13:11.072	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
13:11.783	Info	Delay	Waiting for 3s.
13:28.889	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
13:29.603	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
13:57.821	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
13:57.935	Success	Validation	Element for item 'ButtonFinish' does exist.
13:57.955	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ⬇

### 🎥 ValidatingXML\_And\_Excel

1m ⬇

Time	Level	Category	Message
13:58.649	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Brazil', \$TxtKey = 'Brazil', \$TxtValue = 'Brazil', \$TxtMarket = 'Brazil'
14:00.432	Success	User	Pass :undoredo-master- True = ON
14:00.463	Success	User	Pass :pediatrics-master- True = ON
14:00.488	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
14:00.521	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
14:00.539	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
14:00.577	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF

14:00.610	Success	User	Pass :offline-firmware-update-master- True = ON
14:00.638	Success	User	Pass :fitting-rules-master- True = ON
14:00.670	Success	User	Pass :autorem-master- True = ON
14:08.822	Info	Delay	Waiting for 10s.
14:18.860	Info	Delay	Waiting for 10s.
14:37.024	Info	Delay	Waiting for 10s. 
14:55.139	Info	Delay	Waiting for 6s. 
15:01.180	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms

### FeatureFlag\_Validation\_Folder

Data Row: 7

2.5m

**Marketname:** Bulgaria

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.4m

### Installation

1.4m

Time	Level	Category	Message
15:01.314	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Bulgaria'
15:01.338	Info	Delay	Waiting for 10s.
15:11.445	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
15:12.298	Info	Delay	Waiting for 3s.

15:15.324	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
15:18.467	Info	Delay	Waiting for 2s.
15:20.492	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
15:21.200	Info	Delay	Waiting for 2s.
15:23.235	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
15:23.950	Info	Delay	Waiting for 2s.
15:25.981	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
15:26.680	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
15:27.383	Info	Delay	Waiting for 3s.
15:30.415	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
15:31.096	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
15:31.813	Info	Mouse	Mouse scroll Vertical by 600 units.
15:32.142	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
15:32.848	Info	Delay	Waiting for 2s.
15:34.873	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
15:35.585	Info	Delay	Waiting for 3s.
15:38.610	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
15:39.316	Info	Delay	Waiting for 3s.
15:56.443	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
15:57.150	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
16:26.902	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
16:26.994	Success	Validation	Element for item 'ButtonFinish' does exist.
16:27.021	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
------	-------	----------	---------

16:27.734	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Bulgaria', \$TxtKey = 'Bulgaria', \$TxtValue = 'Bulgaria', \$TxtMarket = 'Bulgaria'
16:29.252	Success	User	Pass :undoredo-master- True = ON 
16:29.281	Success	User	Pass :pediatrics-master- True = ON 
16:29.314	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
16:29.339	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
16:29.372	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
16:29.405	Success	User	Pass :teleaudiology-tsrestricted-fsw- False = OFF 
16:29.437	Success	User	Pass :offline-firmware-update-master- True = ON 
16:29.470	Success	User	Pass :fitting-rules-master- True = ON 
16:29.504	Success	User	Pass :autorem-master- True = ON 
16:37.908	Info	Delay	Waiting for 10s.
16:47.949	Info	Delay	Waiting for 10s.
17:06.048	Info	Delay	Waiting for 10s. 
17:24.153	Info	Delay	Waiting for 6s. 
17:30.176	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms ↑

## 📁 FeatureFlag\_Validation\_Folder Data Row: 8

2.5m ↑

**Marketname:** Canada**BuildName:** ReSound Smart Fit 1.6.0.184

## 🎬 Installing\_Builds

1.4m ↑

## 🎥 Installation

1.4m ↑

Time	Level	Category	Message
17:30.307	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Canada'
17:30.337	Info	Delay	Waiting for 10s.
17:40.437	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
17:41.263	Info	Delay	Waiting for 3s.
17:44.289	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
17:47.317	Info	Delay	Waiting for 2s.
17:49.348	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
17:50.030	Info	Delay	Waiting for 2s.
17:52.063	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
17:52.782	Info	Delay	Waiting for 2s.
17:54.806	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
17:55.528	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
17:56.248	Info	Delay	Waiting for 3s.
17:59.271	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
17:59.983	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
18:00.679	Info	Mouse	Mouse scroll Vertical by 600 units.
18:01.026	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
18:01.729	Info	Delay	Waiting for 2s.
18:03.778	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
18:04.478	Info	Delay	Waiting for 3s.

18:07.506	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
18:08.215	Info	Delay	Waiting for 3s.
18:25.249	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
18:25.953	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
18:55.539	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
18:55.646 ✓	Success	Validation	Element for item 'ButtonFinish' does exist.
18:55.670	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.


## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
18:56.364	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Canada', \$TxtKey = 'Canada', \$TxtValue = 'Canada', \$TxtMarket = 'Canada'
18:57.178 ✓	Success	User	Pass :undoredo-master- True = ON
18:57.204 ✓	Success	User	Pass :pediatrics-master- True = ON
18:57.237 ✗	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
18:57.271 ✗	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
18:57.287 ✗	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
18:57.320 ✓	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
18:57.337 ✓	Success	User	Pass :offline-firmware-update-master- True = ON
18:57.370 ✓	Success	User	Pass :fitting-rules-master- True = ON
18:57.403 ✓	Success	User	Pass :autorem-master- True = ON

19:05.516	Info	Delay	Waiting for 10s.
19:15.547	Info	Delay	Waiting for 10s.
19:33.672	Info	Delay	Waiting for 10s. 
19:51.792	Info	Delay	Waiting for 6s. 
19:57.848	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder Data Row: 9

2.5m 

**Marketname:** China

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.4m 

### Installation

1.4m 

Time	Level	Category	Message
19:58.042	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'China'
19:58.072	Info	Delay	Waiting for 10s.
20:08.200	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
20:09.045	Info	Delay	Waiting for 3s.
20:12.080	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
20:15.233	Info	Delay	Waiting for 2s.
20:17.256	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
20:17.948	Info	Delay	Waiting for 2s.

20:19.977	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
20:20.703	Info	Delay	Waiting for 2s.
20:22.728	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
20:23.462	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
20:24.165	Info	Delay	Waiting for 3s.
20:27.199	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
20:27.882	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
20:28.576	Info	Mouse	Mouse scroll Vertical by 600 units.
20:28.913	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
20:29.612	Info	Delay	Waiting for 2s.
20:31.668	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
20:32.357	Info	Delay	Waiting for 3s.
20:35.393	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
20:36.101	Info	Delay	Waiting for 3s.
20:53.203	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
20:53.934	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
21:23.836	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
21:23.935	Success	Validation	Element for item 'ButtonFinish' does exist. ✓
21:23.954	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
21:24.667	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'China', \$TxtKey = 'China', \$TxtValue = 'China', \$TxtMarket = 'China'

21:25.849	Success	User	Pass :undoredo-master- True = ON
21:25.882	Success	User	Pass :pediatrics-master- True = ON
21:25.905	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
21:25.936	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
21:25.952	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
21:25.986	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
21:26.002	Success	User	Pass :offline-firmware-update-master- True = ON
21:26.035	Success	User	Pass :fitting-rules-master- True = ON
21:26.053	Success	User	Pass :autorem-master- True = ON
21:34.145	Info	Delay	Waiting for 10s.
21:44.180	Info	Delay	Waiting for 10s.
22:02.303	Info	Delay	Waiting for 10s. 
22:20.415	Info	Delay	Waiting for 6s. 
22:26.464	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms



FeatureFlag\_Validation\_Folder

Data Row: 10

2.5m



**Marketname:** Croatia

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m ↑

### Installation

1.5m ↑

Time	Level	Category	Message
22:26.614	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Croatia'
22:26.637	Info	Delay	Waiting for 10s.
22:36.735	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
22:37.541	Info	Delay	Waiting for 3s.
22:40.581	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
22:43.699	Info	Delay	Waiting for 2s.
22:45.725	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
22:46.411	Info	Delay	Waiting for 2s.
22:48.445	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
22:49.163	Info	Delay	Waiting for 2s.
22:51.194	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgree' at Center.
22:51.948	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
22:52.650	Info	Delay	Waiting for 3s.
22:55.682	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
22:56.376	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
22:57.077	Info	Mouse	Mouse scroll Vertical by 600 units.
22:57.414	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
22:58.111	Info	Delay	Waiting for 2s.
23:00.148	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
23:00.848	Info	Delay	Waiting for 3s.
23:03.873	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
23:04.564	Info	Delay	Waiting for 3s.
23:21.686	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.

23:22.399	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
23:52.834	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
23:52.947	Success	Validation	Element for item 'ButtonFinish' does exist.
23:52.970	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
23:53.693	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Croatia', \$TxtKey = 'Croatia', \$TxtValue = 'Croatia', \$TxtMarket = 'Croatia'
23:54.796	Success	User	Pass :undoredo-master- True = ON 
23:54.827	Success	User	Pass :pediatrics-master- True = ON 
23:54.865	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
23:54.888	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
23:54.936	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
23:54.973	Success	User	Pass :teleaudiology-tscrestricted-fsw- False = OFF 
23:55.005	Success	User	Pass :offline-firmware-update-master- True = ON 
23:55.036	Success	User	Pass :fitting-rules-master- True = ON 
23:55.070	Success	User	Pass :autorem-master- True = ON 
24:03.186	Info	Delay	Waiting for 10s.
24:13.209	Info	Delay	Waiting for 10s.

24:31.534	Info	Delay	Waiting for 10s. 
24:49.648	Info	Delay	Waiting for 6s. 
24:55.695	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

 FeatureFlag_Validation_Folder	Data Row: 11	2.5m 
<b>Marketname:</b> Czech Republic		
<b>BuildName:</b> ReSound Smart Fit 1.6.0.184		

 Installing_Builds	1.5m 		
 Installation			
Time	Level		
24:55.849	Info		
	Category		
	Message		
24:55.849	Info	Data	Current variable values:  \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Czech Republic'
24:55.869	Info	Delay	Waiting for 10s.
25:05.948	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
25:06.764	Info	Delay	Waiting for 3s.
25:09.787	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
25:12.830	Info	Delay	Waiting for 2s.
25:14.859	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
25:15.596	Info	Delay	Waiting for 2s.
25:17.626	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
25:18.343	Info	Delay	Waiting for 2s.

25:20.379	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
25:21.079	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
25:21.783	Info	Delay	Waiting for 3s.
25:24.817	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
25:25.513	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
25:26.224	Info	Mouse	Mouse scroll Vertical by 600 units.
25:26.564	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
25:27.242	Info	Delay	Waiting for 2s.
25:29.278	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
25:29.975	Info	Delay	Waiting for 3s.
25:33.005	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
25:33.713	Info	Delay	Waiting for 3s.
25:50.764	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
25:51.467	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
26:24.025	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
26:24.142	Success	Validation	Element for item 'ButtonFinish' does exist. 
26:24.169	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
26:24.850	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Czech Republic', \$TxtKey = 'Czech Republic', \$TxtValue = 'Czech Republic', \$TxtMarket = 'Czech Republic'
26:25.643	Success	User	Pass :undoredo-master- True = ON 

26:25.669	Success	User	Pass :pediatrics-master- True = ON
26:25.701	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
26:25.735	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
26:25.752	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
26:25.785	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
26:25.802	Success	User	Pass :offline-firmware-update-master- True = ON
26:25.835	Success	User	Pass :fitting-rules-master- True = ON
26:25.852	Success	User	Pass :autorem-master- True = ON
26:33.948	Info	Delay	Waiting for 10s.
26:43.978	Info	Delay	Waiting for 10s.
27:02.119	Info	Delay	Waiting for 10s. 
27:20.209	Info	Delay	Waiting for 6s. 
27:26.250	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms ↑

### FeatureFlag\_Validation\_Folder

Data Row: 12

2.5m ↑

**Marketname:** Denmark


**BuildName:** ReSound Smart Fit 1.6.0.184

Installing_Builds			
Installation			
Time	Level	Category	Message
27:26.488	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Denmark'
27:26.518	Info	Delay	Waiting for 10s.
27:36.597	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
27:37.410	Info	Delay	Waiting for 3s.
27:40.447	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
27:43.565	Info	Delay	Waiting for 2s.
27:45.594	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
27:46.294	Info	Delay	Waiting for 2s.
27:48.345	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
27:49.063	Info	Delay	Waiting for 2s.
27:51.090	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
27:51.780	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
27:52.501	Info	Delay	Waiting for 3s.
27:55.522	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
27:56.224	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
27:56.927	Info	Mouse	Mouse scroll Vertical by 600 units.
27:57.264	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
27:57.959	Info	Delay	Waiting for 2s.
28:00.016	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
28:00.694	Info	Delay	Waiting for 3s.
28:03.726	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
28:04.425	Info	Delay	Waiting for 3s.
28:21.515	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
28:22.215	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
28:52.760	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.

28:52.857	Success	Validation	Element for item 'ButtonFinish' does exist.
28:52.885	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m ↑

ValidatingXML_And_Excel			
Time	Level	Category	Message
28:53.610	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Denmark', \$TxtKey = 'Denmark', \$TxtValue = 'Denmark', \$TxtMarket = 'Denmark'
28:54.410	Success	User	Pass :undoredo-master- True = ON
28:54.444	Success	User	Pass :pediatrics-master- True = ON
28:54.483	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
28:54.506	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
28:54.535	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
28:54.569	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
28:54.602	Success	User	Pass :offline-firmware-update-master- True = ON
28:54.618	Success	User	Pass :fitting-rules-master- True = ON
28:54.652	Success	User	Pass :autorem-master- True = ON
29:02.737	Info	Delay	Waiting for 10s.
29:12.780	Info	Delay	Waiting for 10s.
29:30.959	Info	Delay	Waiting for 10s. 

29:49.061	Info	Delay	Waiting for 6s. 
29:55.085	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms 

 FeatureFlag_Validation_Folder	Data Row: 13	2.5m 
<b>Marketname:</b> Finland		
<b>BuildName:</b> ReSound Smart Fit 1.6.0.184		

▶ Installing_Builds			
🎥 Installation			
Time	Level	Category	Message
29:55.210	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Finland'
29:55.234	Info	Delay	Waiting for 10s.
30:05.329	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
30:06.162	Info	Delay	Waiting for 3s.
30:09.194	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
30:12.230	Info	Delay	Waiting for 2s.
30:14.257	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
30:14.962	Info	Delay	Waiting for 2s.
30:16.991	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
30:17.747	Info	Delay	Waiting for 2s.
30:19.783	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
30:20.511	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
30:21.213	Info	Delay	Waiting for 3s.

30:24.241	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
30:24.946	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
30:25.658	Info	Mouse	Mouse scroll Vertical by 600 units.
30:25.994	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
30:26.673	Info	Delay	Waiting for 2s.
30:28.717	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
30:29.426	Info	Delay	Waiting for 3s.
30:32.460	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
30:33.164	Info	Delay	Waiting for 3s.
30:50.231	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
30:50.918	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
31:21.435	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
31:21.545 ✓	Success	Validation	Element for item 'ButtonFinish' does exist.
31:21.568	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.


## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
31:22.270	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Finland', \$TxtKey = 'Finland', \$TxtValue = 'Finland', \$TxtMarket = 'Finland'
31:23.026 ✓	Success	User	Pass :undoredo-master- True = ON
31:23.056 ✓	Success	User	Pass :pediatrics-master- True = ON
31:23.085 ✗	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
31:23.118 ✗	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON

31:23.151	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
31:23.185	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
31:23.201	Success	User	Pass :offline-firmware-update-master- True = ON
31:23.235	Success	User	Pass :fitting-rules-master- True = ON
31:23.252	Success	User	Pass :autorem-master- True = ON
31:31.354	Info	Delay	Waiting for 10s.
31:41.397	Info	Delay	Waiting for 10s.
31:59.520	Info	Delay	Waiting for 10s. 
32:17.639	Info	Delay	Waiting for 6s. 
32:23.679	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder

Data Row: 14

2.5m 

**Marketname:** France

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.4m 

### Installation

1.4m 

Time	Level	Category	Message
32:23.802	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'France'

32:23.834	Info	Delay	Waiting for 10s.
32:33.914	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
32:34.793	Info	Delay	Waiting for 3s.
32:37.824	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
32:40.828	Info	Delay	Waiting for 2s.
32:42.858	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
32:43.562	Info	Delay	Waiting for 2s.
32:45.592	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
32:46.331	Info	Delay	Waiting for 2s.
32:48.353	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
32:49.060	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
32:49.746	Info	Delay	Waiting for 3s.
32:52.777	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
32:53.480	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
32:54.206	Info	Mouse	Mouse scroll Vertical by 600 units.
32:54.536	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
32:55.238	Info	Delay	Waiting for 2s.
32:57.276	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
32:57.975	Info	Delay	Waiting for 3s.
33:01.011	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
33:01.717	Info	Delay	Waiting for 3s.
33:18.783	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
33:19.497	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
33:49.181	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
33:49.281	Success	Validation	Element for item 'ButtonFinish' does exist.
33:49.314	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↗

## 🎥 ValidatingXML\_And\_Excel

1m ↗

Time	Level	Category	Message
33:50.018	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'France', \$TxtKey = 'France', \$TxtValue = 'France', \$TxtMarket = 'France'
33:50.993	Success	User	Pass :undoredo-master- True = ON 
33:51.019	Success	User	Pass :pediatrics-master- True = ON 
33:51.051	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
33:51.085	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
33:51.118	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
33:51.151	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 
33:51.168	Success	User	Pass :offline-firmware-update-master- True = ON 
33:51.201	Success	User	Pass :fitting-rules-master- True = ON 
33:51.234	Success	User	Pass :autorem-master- True = ON 
33:59.410	Info	Delay	Waiting for 10s.
34:09.445	Info	Delay	Waiting for 10s.
34:27.580	Info	Delay	Waiting for 10s. 
34:45.716	Info	Delay	Waiting for 6s. 

34:51.762	Error	Module	The module has failed because one or more actions have failed. 
-----------	-------	--------	--

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder Data Row: 15

2.5m 

**Marketname:** Germany

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m 

### Installation

1.5m 

Time	Level	Category	Message
34:51.902	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Germany'
34:51.943	Info	Delay	Waiting for 10s.
35:02.062	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
35:02.895	Info	Delay	Waiting for 3s.
35:05.930	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
35:09.046	Info	Delay	Waiting for 2s.
35:11.075	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
35:11.777	Info	Delay	Waiting for 2s.
35:13.803	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
35:14.543	Info	Delay	Waiting for 2s.
35:16.569	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
35:17.278	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
35:17.977	Info	Delay	Waiting for 3s.
35:21.007	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
35:21.740	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
35:22.441	Info	Mouse	Mouse scroll Vertical by 600 units.

35:22.795	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
35:23.476	Info	Delay	Waiting for 2s.
35:25.516	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
35:26.207	Info	Delay	Waiting for 3s.
35:29.242	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
35:29.982	Info	Delay	Waiting for 3s.
35:47.098	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
35:47.817	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
36:19.523	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
36:19.644	Success	Validation	Element for item 'ButtonFinish' does exist.
36:19.673	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ⬤

### 🎥 ValidatingXML\_And\_Excel

1m ⬤

Time	Level	Category	Message
36:20.367	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Germany', \$TxtKey = 'Germany', \$TxtValue = 'Germany', \$TxtMarket = 'Germany'
36:21.375	Success	User	Pass :undoredo-master- True = ON
36:21.410	Success	User	Pass :pediatrics-master- True = ON
36:21.434	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
36:21.468	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
36:21.501	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
36:21.533	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF

36:21.566	Success	User	Pass :offline-firmware-update-master- True = ON
36:21.600	Success	User	Pass :fitting-rules-master- True = ON
36:21.617	Success	User	Pass :autorem-master- True = ON
36:29.723	Info	Delay	Waiting for 10s.
36:39.763	Info	Delay	Waiting for 10s.
36:57.867	Info	Delay	Waiting for 10s. 
37:15.996	Info	Delay	Waiting for 6s. 
37:22.020	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms



 FeatureFlag_Validation_Folder	Data Row: 16	2.5m	
<b>Marketname:</b> Greece			
<b>BuildName:</b> ReSound Smart Fit 1.6.0.184			

## Installing\_Builds

1.5m



### Installation

1.5m



Time	Level	Category	Message
37:22.175	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Greece'
37:22.213	Info	Delay	Waiting for 10s.
37:32.294	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
37:33.126	Info	Delay	Waiting for 3s.

37:36.153	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
37:39.246	Info	Delay	Waiting for 2s.
37:41.273	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
37:41.994	Info	Delay	Waiting for 2s.
37:44.021	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
37:44.726	Info	Delay	Waiting for 2s.
37:46.759	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
37:47.459	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
37:48.143	Info	Delay	Waiting for 3s.
37:51.176	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
37:51.875	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
37:52.578	Info	Mouse	Mouse scroll Vertical by 600 units.
37:52.941	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
37:53.625	Info	Delay	Waiting for 2s.
37:55.654	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
37:56.355	Info	Delay	Waiting for 3s.
37:59.388	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
38:00.094	Info	Delay	Waiting for 3s.
38:17.139	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
38:17.833	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
38:49.466	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
38:49.559	Success	Validation	Element for item 'ButtonFinish' does exist.
38:49.584	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
------	-------	----------	---------

38:50.293	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Greece', \$TxtKey = 'Greece', \$TxtValue = 'Greece', \$TxtMarket = 'Greece'
38:51.082	Success	User	Pass :undoredo-master- True = ON 
38:51.113	Success	User	Pass :pediatrics-master- True = ON 
38:51.136	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
38:51.167	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
38:51.184	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
38:51.216	Success	User	Pass :teleaudiology-tsrestricted-fsw- False = OFF 
38:51.250	Success	User	Pass :offline-firmware-update-master- True = ON 
38:51.266	Success	User	Pass :fitting-rules-master- True = ON 
38:51.300	Success	User	Pass :autorem-master- True = ON 
38:59.400	Info	Delay	Waiting for 10s.
39:09.423	Info	Delay	Waiting for 10s.
39:27.581	Info	Delay	Waiting for 10s. 
39:45.752	Info	Delay	Waiting for 6s. 
39:51.795	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms ↑

## 📁 FeatureFlag\_Validation\_Folder Data Row: 17

2.5m ↑

**Marketname:** Hong Kong**BuildName:** ReSound Smart Fit 1.6.0.184

## 🎬 Installing\_Builds

1.5m ↑

## 🎥 Installation

1.5m ↑

Time	Level	Category	Message
39:52.026	Info	Data	Current variable values:  \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Hong Kong'
39:52.073	Info	Delay	Waiting for 10s.
40:02.159	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
40:03.011	Info	Delay	Waiting for 3s.
40:06.044	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
40:09.095	Info	Delay	Waiting for 2s.
40:11.121	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
40:11.847	Info	Delay	Waiting for 2s.
40:13.873	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
40:14.584	Info	Delay	Waiting for 2s.
40:16.632	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
40:17.340	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
40:18.032	Info	Delay	Waiting for 3s.
40:21.073	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
40:21.778	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
40:22.474	Info	Mouse	Mouse scroll Vertical by 600 units.
40:22.809	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
40:23.510	Info	Delay	Waiting for 2s.
40:25.557	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
40:26.273	Info	Delay	Waiting for 3s.

40:29.310	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
40:30.029	Info	Delay	Waiting for 3s.
40:47.167	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
40:47.865	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
41:19.415	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
41:19.506 ✓	Success	Validation	Element for item 'ButtonFinish' does exist.
41:19.533	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
41:20.243	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Hong Kong', \$TxtKey = 'Hong Kong', \$TxtValue = 'Hong Kong', \$TxtMarket = 'Hong Kong'
41:21.026 ✓	Success	User	Pass :undoredo-master- True = ON
41:21.051 ✓	Success	User	Pass :pediatrics-master- True = ON
41:21.084 ✗	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
41:21.116 ✗	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
41:21.134 ✗	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
41:21.167 ✓	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
41:21.183 ✓	Success	User	Pass :offline-firmware-update-master- True = ON
41:21.217 ✓	Success	User	Pass :fitting-rules-master- True = ON
41:21.233 ✓	Success	User	Pass :autorem-master- True = ON

41:29.479	Info	Delay	Waiting for 10s.
41:39.566	Info	Delay	Waiting for 10s.
41:57.703	Info	Delay	Waiting for 10s. 
42:15.811	Info	Delay	Waiting for 6s. 
42:21.840	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder Data Row: 18

2.5m 

**Marketname:** Hungary

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.4m 

### Installation

1.4m 

Time	Level	Category	Message
42:21.991	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Hungary'
42:22.017	Info	Delay	Waiting for 10s.
42:32.093	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
42:32.909	Info	Delay	Waiting for 3s.
42:35.944	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
42:38.996	Info	Delay	Waiting for 2s.
42:41.025	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
42:41.709	Info	Delay	Waiting for 2s.

42:43.741	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
42:44.477	Info	Delay	Waiting for 2s.
42:46.507	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
42:47.189	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
42:47.938	Info	Delay	Waiting for 3s.
42:50.969	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
42:51.708	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
42:52.420	Info	Mouse	Mouse scroll Vertical by 600 units.
42:52.776	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
42:53.494	Info	Delay	Waiting for 2s.
42:55.530	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
42:56.222	Info	Delay	Waiting for 3s.
42:59.249	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
42:59.976	Info	Delay	Waiting for 3s.
43:17.060	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
43:17.766	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
43:48.136	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
43:48.240	Success	Validation	Element for item 'ButtonFinish' does exist.
43:48.266	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
43:48.960	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Hungary', \$TxtKey = 'Hungary', \$TxtValue = 'Hungary', \$TxtMarket = 'Hungary'

43:49.980	Success	User	Pass :undoredo-master- True = ON
43:50.002	Success	User	Pass :pediatrics-master- True = ON
43:50.059	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
43:50.084	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
43:50.131	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
43:50.181	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
43:50.203	Success	User	Pass :offline-firmware-update-master- True = ON
43:50.233	Success	User	Pass :fitting-rules-master- True = ON
43:50.249	Success	User	Pass :autorem-master- True = ON
43:58.371	Info	Delay	Waiting for 10s.
44:08.410	Info	Delay	Waiting for 10s.
44:26.546	Info	Delay	Waiting for 10s. 
44:44.641	Info	Delay	Waiting for 6s. 
44:50.695	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms ↑



## FeatureFlag\_Validation\_Folder

Data Row: 19

2.5m ↑

**Marketname:** India

**BuildName:** ReSound Smart Fit 1.6.0.184

## 🎬 Installing\_Builds

1.4m ↑

### 🎥 Installation

1.4m ↑

Time	Level	Category	Message
44:50.842	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'India'
44:50.866	Info	Delay	Waiting for 10s.
45:00.938	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
45:01.756	Info	Delay	Waiting for 3s.
45:04.784	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
45:07.828	Info	Delay	Waiting for 2s.
45:09.860	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
45:10.543	Info	Delay	Waiting for 2s.
45:12.569	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
45:13.313	Info	Delay	Waiting for 2s.
45:15.339	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgree' at Center.
45:16.059	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
45:16.746	Info	Delay	Waiting for 3s.
45:19.770	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
45:20.488	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
45:21.192	Info	Mouse	Mouse scroll Vertical by 600 units.
45:21.536	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
45:22.241	Info	Delay	Waiting for 2s.
45:24.272	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
45:24.991	Info	Delay	Waiting for 3s.
45:28.026	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
45:28.729	Info	Delay	Waiting for 3s.
45:45.881	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.

45:46.597	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
46:14.447	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
46:14.546	Success	Validation	Element for item 'ButtonFinish' does exist.
46:14.566	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
46:15.267	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'India', \$TxtKey = 'India', \$TxtValue = 'India', \$TxtMarket = 'India'
46:17.338	Success	User	Pass :undoredo-master- True = ON 
46:17.376	Success	User	Pass :pediatrics-master- True = ON 
46:17.399	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
46:17.455	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
46:17.482	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
46:17.515	Success	User	Pass :teleaudiology-tscrestricted-fsw- False = OFF 
46:17.548	Success	User	Pass :offline-firmware-update-master- True = ON 
46:17.566	Success	User	Pass :fitting-rules-master- True = ON 
46:17.598	Success	User	Pass :autorem-master- True = ON 
46:25.699	Info	Delay	Waiting for 10s.
46:35.729	Info	Delay	Waiting for 10s.

46:53.838	Info	Delay	Waiting for 10s. 
47:11.945	Info	Delay	Waiting for 6s. 
47:17.987	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms 

### FeatureFlag\_Validation\_Folder Data Row: 20

2.5m 

**Marketname:** International

**BuildName:** ReSound Smart Fit 1.6.0.184

### Installing\_Builds

1.4m 

#### Installation

1.4m 

Time	Level	Category	Message
47:18.097	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'International'
47:18.115	Info	Delay	Waiting for 10s.
47:28.261	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
47:29.206	Info	Delay	Waiting for 3s.
47:32.237	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
47:35.259	Info	Delay	Waiting for 2s.
47:37.290	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
47:37.992	Info	Delay	Waiting for 2s.
47:40.024	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
47:40.744	Info	Delay	Waiting for 2s.

47:42.777	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
47:43.490	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
47:44.191	Info	Delay	Waiting for 3s.
47:47.225	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
47:47.938	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
47:48.619	Info	Mouse	Mouse scroll Vertical by 600 units.
47:48.987	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
47:49.673	Info	Delay	Waiting for 2s.
47:51.705	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
47:52.421	Info	Delay	Waiting for 3s.
47:55.452	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
47:56.179	Info	Delay	Waiting for 3s.
48:13.248	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
48:13.928	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
48:43.447	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
48:43.541	Success	Validation	Element for item 'ButtonFinish' does exist. 
48:43.565	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
48:44.273	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'International', \$TxtKey = 'International', \$TxtValue = 'International', \$TxtMarket = 'International'
48:45.707	Success	User	Pass :undoredo-master- True = ON 

48:45.733	Success	User	Pass :pediatrics-master- True = ON
48:45.765	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
48:45.799	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
48:45.832	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
48:45.865	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
48:45.898	Success	User	Pass :offline-firmware-update-master- True = ON
48:45.915	Success	User	Pass :fitting-rules-master- True = ON
48:45.949	Success	User	Pass :autorem-master- True = ON
48:54.061	Info	Delay	Waiting for 10s.
49:04.086	Info	Delay	Waiting for 10s.
49:22.203	Info	Delay	Waiting for 10s. 
49:40.327	Info	Delay	Waiting for 6s. 
49:46.354	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms ↑

 **FeatureFlag\_Validation\_Folder** Data Row: 21 2.5m ↑

**Marketname:** Iran

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m


### Installation

1.5m

Time	Level	Category	Message
49:46.499	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Iran'
49:46.532	Info	Delay	Waiting for 10s.
49:56.602	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
49:57.441	Info	Delay	Waiting for 3s.
50:00.472	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
50:03.544	Info	Delay	Waiting for 2s.
50:05.572	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
50:06.289	Info	Delay	Waiting for 2s.
50:08.327	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
50:09.029	Info	Delay	Waiting for 2s.
50:11.060	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
50:11.757	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
50:12.443	Info	Delay	Waiting for 3s.
50:15.487	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
50:16.191	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
50:16.873	Info	Mouse	Mouse scroll Vertical by 600 units.
50:17.206	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
50:17.905	Info	Delay	Waiting for 2s.
50:19.952	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
50:20.657	Info	Delay	Waiting for 3s.
50:23.686	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
50:24.409	Info	Delay	Waiting for 3s.
50:41.504	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
50:42.210	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
51:13.309	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.

51:13.409	Success	Validation	Element for item 'ButtonFinish' does exist.
51:13.431	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

51:14.133	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Iran', \$TxtKey = 'Iran', \$TxtValue = 'Iran', \$TxtMarket = 'Iran'
51:14.955	Success	User	Pass :undoredo-master- True = ON
51:14.982	Success	User	Pass :pediatrics-master- True = ON
51:15.015	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
51:15.047	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
51:15.066	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
51:15.098	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
51:15.115	Success	User	Pass :offline-firmware-update-master- True = ON
51:15.148	Success	User	Pass :fitting-rules-master- True = ON
51:15.165	Success	User	Pass :autorem-master- True = ON
51:23.307	Info	Delay	Waiting for 10s.
51:33.349	Info	Delay	Waiting for 10s.
51:51.510	Info	Delay	Waiting for 10s. 

52:09.608	Info	Delay	Waiting for 6s. 
52:15.646	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms 

### FeatureFlag\_Validation\_Folder Data Row: 22

2.5m 

**Marketname:** Italy

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m 

### Installation

1.5m 

Time	Level	Category	Message
52:15.777	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Italy'
52:15.798	Info	Delay	Waiting for 10s.
52:25.872	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
52:26.710	Info	Delay	Waiting for 3s.
52:29.732	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
52:32.727	Info	Delay	Waiting for 2s.
52:34.757	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
52:35.479	Info	Delay	Waiting for 2s.
52:37.511	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
52:38.223	Info	Delay	Waiting for 2s.
52:40.261	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
52:40.938	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
52:41.644	Info	Delay	Waiting for 3s.

52:44.670	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
52:45.388	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
52:46.091	Info	Mouse	Mouse scroll Vertical by 600 units.
52:46.415	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
52:47.123	Info	Delay	Waiting for 2s.
52:49.161	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
52:49.869	Info	Delay	Waiting for 3s.
52:52.901	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
52:53.611	Info	Delay	Waiting for 3s.
53:10.714	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
53:11.429	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
53:44.305	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
53:44.407	Success	Validation	 Element for item 'ButtonFinish' does exist.
53:44.431	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.


## Verifying\_Feature\_Availability

1m ↑

### ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
53:45.125	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Italy', \$TxtKey = 'Italy', \$TxtValue = 'Italy', \$TxtMarket = 'Italy'
53:45.960	Success	User	 Pass :undoredo-master- True = ON
53:45.982	Success	User	 Pass :pediatrics-master- True = ON
53:46.014	Failure	User	 Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
53:46.048	Failure	User	 Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON

53:46.066	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
53:46.097	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
53:46.114	Success	User	Pass :offline-firmware-update-master- True = ON
53:46.147	Success	User	Pass :fitting-rules-master- True = ON
53:46.241	Success	User	Pass :autorem-master- True = ON
53:54.334	Info	Delay	Waiting for 10s.
54:04.366	Info	Delay	Waiting for 10s.
54:22.471	Info	Delay	Waiting for 10s. 
54:40.622	Info	Delay	Waiting for 6s. 
54:46.663	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder

Data Row: 23

2.5m 

**Marketname:** Japan

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m 

### Installation

1.5m 

Time	Level	Category	Message
54:46.773	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Japan'

54:46.797	Info	Delay	Waiting for 10s.
54:56.894	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
54:57.726	Info	Delay	Waiting for 3s.
55:00.758	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
55:03.859	Info	Delay	Waiting for 2s.
55:05.892	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
55:06.631	Info	Delay	Waiting for 2s.
55:08.670	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
55:09.387	Info	Delay	Waiting for 2s.
55:11.427	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
55:12.139	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
55:12.825	Info	Delay	Waiting for 3s.
55:15.859	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
55:16.558	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
55:17.273	Info	Mouse	Mouse scroll Vertical by 600 units.
55:17.609	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
55:18.285	Info	Delay	Waiting for 2s.
55:20.314	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
55:21.040	Info	Delay	Waiting for 3s.
55:24.074	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
55:24.774	Info	Delay	Waiting for 3s.
55:41.842	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
55:42.526	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
56:15.509	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
56:15.616	Success	Validation	Element for item 'ButtonFinish' does exist.
56:15.647	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.


## ⌚ Verifying\_Feature\_Availability

1m ↗

## 🎥 ValidatingXML\_And\_Excel

1m ↗

Time	Level	Category	Message
56:16.341	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Japan', \$TxtKey = 'Japan', \$TxtValue = 'Japan', \$TxtMarket = 'Japan'
56:17.410	Success	User	Pass :undoredo-master- True = ON 
56:17.468	Success	User	Pass :pediatrics-master- True = ON 
56:17.499	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
56:17.530	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
56:17.564	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
56:17.597	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 
56:17.631	Success	User	Pass :offline-firmware-update-master- True = ON 
56:17.663	Success	User	Pass :fitting-rules-master- True = ON 
56:17.697	Success	User	Pass :autorem-master- True = ON 
56:26.000	Info	Delay	Waiting for 10s.
56:36.045	Info	Delay	Waiting for 10s.
56:54.131	Info	Delay	Waiting for 10s. 
57:12.242	Info	Delay	Waiting for 6s. 

57:18.264	Error	Module	The module has failed because one or more actions have failed. 
-----------	-------	--------	--

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder Data Row: 24

2.5m 

**Marketname:** Korea

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m 

### Installation

1.5m 

Time	Level	Category	Message
57:18.412	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Korea'
57:18.430	Info	Delay	Waiting for 10s.
57:28.530	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
57:29.356	Info	Delay	Waiting for 3s.
57:32.384	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
57:35.609	Info	Delay	Waiting for 2s.
57:37.632	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
57:38.340	Info	Delay	Waiting for 2s.
57:40.373	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
57:41.093	Info	Delay	Waiting for 2s.
57:43.123	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
57:43.867	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
57:44.573	Info	Delay	Waiting for 3s.
57:47.601	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
57:48.305	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
57:49.007	Info	Mouse	Mouse scroll Vertical by 600 units.

57:49.346	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
57:50.043	Info	Delay	Waiting for 2s.
57:52.085	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
57:52.770	Info	Delay	Waiting for 3s.
57:55.801	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
57:56.490	Info	Delay	Waiting for 3s.
58:13.593	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
58:14.324	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
58:46.977	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
58:47.087	Success	Validation	Element for item 'ButtonFinish' does exist.
58:47.114	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ⬇

### 🎥 ValidatingXML\_And\_Excel

1m ⬇

Time	Level	Category	Message
58:47.811	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Korea', \$TxtKey = 'Korea', \$TxtValue = 'Korea', \$TxtMarket = 'Korea'
58:48.639	Success	User	Pass :undoredo-master- True = ON
58:48.673	Success	User	Pass :pediatrics-master- True = ON
58:48.698	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
58:48.730	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
58:48.747	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON
58:48.781	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF

58:48.813	Success	User	Pass :offline-firmware-update-master- True = ON
58:48.846	Success	User	Pass :fitting-rules-master- True = ON
58:48.863	Success	User	Pass :autorem-master- True = ON
58:57.136	Info	Delay	Waiting for 10s.
59:07.176	Info	Delay	Waiting for 10s.
59:25.313	Info	Delay	Waiting for 10s. 
59:43.422	Info	Delay	Waiting for 6s. 
59:49.454	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms



### FeatureFlag\_Validation\_Folder

Data Row: 25

2.5m



**Marketname:** Netherlands

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m



### Installation

1.5m



Time	Level	Category	Message
59:49.598	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Netherlands'
59:49.630	Info	Delay	Waiting for 10s.
59:59.711	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.

60:00.544	Info	Delay	Waiting for 3s.
60:03.574	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
60:06.693	Info	Delay	Waiting for 2s.
60:08.721	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
60:09.428	Info	Delay	Waiting for 2s.
60:11.457	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
60:12.156	Info	Delay	Waiting for 2s.
60:14.196	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
60:14.886	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
60:15.573	Info	Delay	Waiting for 3s.
60:18.603	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
60:19.323	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
60:20.026	Info	Mouse	Mouse scroll Vertical by 600 units.
60:20.360	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
60:21.041	Info	Delay	Waiting for 2s.
60:23.095	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
60:23.789	Info	Delay	Waiting for 3s.
60:26.823	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
60:27.558	Info	Delay	Waiting for 3s.
60:44.669	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
60:45.375	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
61:18.509	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
61:18.612	Success	Validation	Element for item 'ButtonFinish' does exist.
61:18.630	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m ↑

### ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message

61:19.358	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Netherlands', \$TxtKey = 'Netherlands', \$TxtValue = 'Netherlands', \$TxtMarket = 'Netherlands'
61:20.422	Success	User	Pass :undoredo-master- True = ON 
61:20.448	Success	User	Pass :pediatrics-master- True = ON 
61:20.481	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
61:20.513	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
61:20.546	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
61:20.580	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 
61:20.614	Success	User	Pass :offline-firmware-update-master- True = ON 
61:20.646	Success	User	Pass :fitting-rules-master- True = ON 
61:20.679	Success	User	Pass :autorem-master- True = ON 
61:29.185	Info	Delay	Waiting for 10s.
61:39.223	Info	Delay	Waiting for 10s.
61:57.331	Info	Delay	Waiting for 10s. 
62:15.470	Info	Delay	Waiting for 6s. 

62:21.512	Error	Module	The module has failed because one or more actions have failed. 
-----------	-------	--------	--

## TEARDOWN

0ms ↑

### FeatureFlag\_Validation\_Folder Data Row: 26

2.5m ↑

**Marketname:** New Zealand

**BuildName:** ReSound Smart Fit 1.6.0.184

### Installing\_Builds

1.5m ↑

#### Installation

1.5m ↑

Time	Level	Category	Message
62:21.695	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'New Zealand'
62:21.729	Info	Delay	Waiting for 10s.
62:31.807	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
62:32.636	Info	Delay	Waiting for 3s.
62:35.674	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
62:38.725	Info	Delay	Waiting for 2s.
62:40.748	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
62:41.459	Info	Delay	Waiting for 2s.
62:43.480	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
62:44.226	Info	Delay	Waiting for 2s.
62:46.246	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
62:46.938	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
62:47.652	Info	Delay	Waiting for 3s.
62:50.696	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
62:51.404	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.

62:52.104	Info	Mouse	Mouse scroll Vertical by 600 units.
62:52.433	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
62:53.137	Info	Delay	Waiting for 2s.
62:55.171	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
62:55.871	Info	Delay	Waiting for 3s.
62:58.907	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
62:59.606	Info	Delay	Waiting for 3s.
63:16.669	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
63:17.359	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
63:48.266	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
63:48.401	Success	Validation	Element for item 'ButtonFinish' does exist. 
63:48.447	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
63:49.140	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'New Zealand', \$TxtKey = 'New Zealand', \$TxtValue = 'New Zealand', \$TxtMarket = 'New Zealand'
63:50.364	Success	User	Pass :undoredo-master- True = ON 
63:50.397	Success	User	Pass :pediatrics-master- True = ON 
63:50.430	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
63:50.463	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
63:50.480	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
63:50.512	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 

63:50.529	Success	User	Pass :offline-firmware-update-master- True = ON
63:50.638	Success	User	Pass :fitting-rules-master- True = ON
63:50.662	Success	User	Pass :autorem-master- True = ON
63:58.795	Info	Delay	Waiting for 10s.
64:08.815	Info	Delay	Waiting for 10s.
64:26.974	Info	Delay	Waiting for 10s. 
64:45.081	Info	Delay	Waiting for 6s. 
64:51.113	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms



### FeatureFlag\_Validation\_Folder

Data Row: 27

2.4m



**Marketname:** NLHL

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.4m



### Installation

1.4m



Time	Level	Category	Message
64:51.231	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'NLHL'
64:51.262	Info	Delay	Waiting for 10s.
65:01.333	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
65:02.173	Info	Delay	Waiting for 3s.

65:05.197	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
65:08.342	Info	Delay	Waiting for 2s.
65:10.374	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
65:11.058	Info	Delay	Waiting for 2s.
65:13.095	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
65:13.842	Info	Delay	Waiting for 2s.
65:15.879	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
65:16.634	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
65:17.339	Info	Delay	Waiting for 3s.
65:20.371	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
65:21.071	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
65:21.770	Info	Mouse	Mouse scroll Vertical by 600 units.
65:22.103	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
65:22.789	Info	Delay	Waiting for 2s.
65:24.816	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
65:25.518	Info	Delay	Waiting for 3s.
65:28.556	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
65:29.239	Info	Delay	Waiting for 3s.
65:46.354	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
65:47.041	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
66:14.980	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
66:15.091	Success	Validation	 Element for item 'ButtonFinish' does exist.
66:15.112	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message

66:15.793	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'NLHL', \$TxtKey = 'NLHL', \$TxtValue = 'NLHL', \$TxtMarket = 'NLHL'
66:17.020	Success	User	Pass :undoredo-master- True = ON 
66:17.054	Success	User	Pass :pediatrics-master- True = ON 
66:17.078	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
66:17.095	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
66:17.128	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
66:17.145	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 
66:17.178	Success	User	Pass :offline-firmware-update-master- True = ON 
66:17.195	Success	User	Pass :fitting-rules-master- True = ON 
66:17.228	Success	User	Pass :autorem-master- True = ON 
66:25.337	Info	Delay	Waiting for 10s.
66:35.374	Info	Delay	Waiting for 10s.
66:53.472	Info	Delay	Waiting for 10s. 
67:11.602	Info	Delay	Waiting for 6s. 
67:17.638	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms ↑

## 📁 FeatureFlag\_Validation\_Folder Data Row: 28

2.5m ↑

**Marketname:** Norway**BuildName:** ReSound Smart Fit 1.6.0.184

## 🎬 Installing\_Builds

1.5m ↑

## 🎥 Installation

1.5m ↑

Time	Level	Category	Message
67:17.834	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Norway'
67:17.879	Info	Delay	Waiting for 10s.
67:27.986	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
67:28.823	Info	Delay	Waiting for 3s.
67:31.855	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
67:34.857	Info	Delay	Waiting for 2s.
67:36.889	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
67:37.591	Info	Delay	Waiting for 2s.
67:39.623	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
67:40.338	Info	Delay	Waiting for 2s.
67:42.366	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
67:43.073	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
67:43.755	Info	Delay	Waiting for 3s.
67:46.788	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
67:47.503	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
67:48.203	Info	Mouse	Mouse scroll Vertical by 600 units.
67:48.558	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
67:49.285	Info	Delay	Waiting for 2s.
67:51.312	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
67:52.020	Info	Delay	Waiting for 3s.

67:55.045	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
67:55.737	Info	Delay	Waiting for 3s.
68:12.794	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
68:13.475	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
68:44.117	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
68:44.219	Success	Validation	Element for item 'ButtonFinish' does exist. 
68:44.244	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
68:44.945	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Norway', \$TxtKey = 'Norway', \$TxtValue = 'Norway', \$TxtMarket = 'Norway'
68:45.770	Success	User	Pass :undoredo-master- True = ON 
68:45.804	Success	User	Pass :pediatrics-master- True = ON 
68:45.828	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
68:45.861	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
68:45.879	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
68:45.911	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 
68:45.928	Success	User	Pass :offline-firmware-update-master- True = ON 
68:45.961	Success	User	Pass :fitting-rules-master- True = ON 
68:45.979	Success	User	Pass :autorem-master- True = ON 

68:54.084	Info	Delay	Waiting for 10s.
69:04.124	Info	Delay	Waiting for 10s.
69:22.633	Info	Delay	Waiting for 10s. 
69:40.756	Info	Delay	Waiting for 6s. 
69:46.791	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder Data Row: 29

2.5m 

**Marketname:** Poland

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m 

### Installation

1.5m 

Time	Level	Category	Message
69:47.038	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Poland'
69:47.063	Info	Delay	Waiting for 10s.
69:57.150	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
69:58.055	Info	Delay	Waiting for 3s.
70:01.082	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
70:04.123	Info	Delay	Waiting for 2s.
70:06.151	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
70:06.835	Info	Delay	Waiting for 2s.

70:08.875	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
70:09.624	Info	Delay	Waiting for 2s.
70:11.647	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
70:12.336	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
70:13.023	Info	Delay	Waiting for 3s.
70:16.055	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
70:16.755	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
70:17.473	Info	Mouse	Mouse scroll Vertical by 600 units.
70:17.811	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
70:18.523	Info	Delay	Waiting for 2s.
70:20.608	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
70:21.308	Info	Delay	Waiting for 3s.
70:24.331	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
70:25.023	Info	Delay	Waiting for 3s.
70:42.125	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
70:42.862	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
71:14.291	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
71:14.384	Success	Validation	Element for item 'ButtonFinish' does exist. 
71:14.411	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
71:15.097	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Poland', \$TxtKey = 'Poland', \$TxtValue = 'Poland', \$TxtMarket = 'Poland'

71:15.870	Success	User	Pass :undoredo-master- True = ON
71:15.896	Success	User	Pass :pediatrics-master- True = ON
71:15.929	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
71:15.985	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
71:16.013	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
71:16.053	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
71:16.078	Success	User	Pass :offline-firmware-update-master- True = ON
71:16.129	Success	User	Pass :fitting-rules-master- True = ON
71:16.161	Success	User	Pass :autorem-master- True = ON
71:24.249	Info	Delay	Waiting for 10s.
71:34.286	Info	Delay	Waiting for 10s.
71:52.440	Info	Delay	Waiting for 10s. 
72:10.549	Info	Delay	Waiting for 6s. 
72:16.586	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms ↑

FeatureFlag\_Validation\_Folder Data Row: 30

2.5m ↑

**Marketname:** Portugal

**BuildName:** ReSound Smart Fit 1.6.0.184

## 🎬 Installing\_Builds

1.4m ↑

### 🎥 Installation

1.4m ↑

Time	Level	Category	Message
72:16.699	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Portugal'
72:16.728	Info	Delay	Waiting for 10s.
72:26.809	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
72:27.705	Info	Delay	Waiting for 3s.
72:30.738	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
72:33.756	Info	Delay	Waiting for 2s.
72:35.783	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
72:36.488	Info	Delay	Waiting for 2s.
72:38.517	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
72:39.224	Info	Delay	Waiting for 2s.
72:41.256	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgree' at Center.
72:41.938	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
72:42.637	Info	Delay	Waiting for 3s.
72:45.670	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
72:46.367	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
72:47.067	Info	Mouse	Mouse scroll Vertical by 600 units.
72:47.404	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
72:48.086	Info	Delay	Waiting for 2s.
72:50.119	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
72:50.820	Info	Delay	Waiting for 3s.
72:53.848	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
72:54.574	Info	Delay	Waiting for 3s.
73:11.623	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.

73:12.323	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
73:41.712	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
73:41.823 ✓	Success	Validation	Element for item 'ButtonFinish' does exist.
73:41.844	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↴

### 🎥 ValidatingXML\_And\_Excel

1m ↴

Time	Level	Category	Message
73:42.543	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Portugal', \$TxtKey = 'Portugal', \$TxtValue = 'Portugal', \$TxtMarket = 'Portugal'
73:43.325 ✓	Success	User	Pass :undoredo-master- True = ON
73:43.345 ✓	Success	User	Pass :pediatrics-master- True = ON
73:43.378 ✗	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
73:43.435 ✗	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
73:43.463 ✗	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
73:43.494 ✓	Success	User	Pass :teleaudiology-tscrestricted-fsw- False = OFF
73:43.543 ✓	Success	User	Pass :offline-firmware-update-master- True = ON
73:43.580 ✓	Success	User	Pass :fitting-rules-master- True = ON
73:43.611 ✓	Success	User	Pass :autorem-master- True = ON
73:51.728	Info	Delay	Waiting for 10s.
74:01.775	Info	Delay	Waiting for 10s.

74:19.919	Info	Delay	Waiting for 10s. 
74:38.037	Info	Delay	Waiting for 6s. 
74:44.063	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

 FeatureFlag_Validation_Folder	Data Row: 31	2.5m 
<b>Marketname:</b> ReSound Branded Standard PE		
<b>BuildName:</b> ReSound Smart Fit 1.6.0.184		

 Installing_Builds	1.4m 																																												
 Installation	1.4m 																																												
<table border="1"> <thead> <tr> <th>Time</th> <th>Level</th> <th>Category</th> <th>Message</th> </tr> </thead> <tbody> <tr> <td>74:44.242</td> <td>Info</td> <td>Data</td> <td>Current variable values:  \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'ReSound Branded Standard PE'</td> </tr> <tr> <td>74:44.260</td> <td>Info</td> <td>Delay</td> <td>Waiting for 10s.</td> </tr> <tr> <td>74:54.349</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.</td> </tr> <tr> <td>74:55.170</td> <td>Info</td> <td>Delay</td> <td>Waiting for 3s.</td> </tr> <tr> <td>74:58.202</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.</td> </tr> <tr> <td>75:01.255</td> <td>Info</td> <td>Delay</td> <td>Waiting for 2s.</td> </tr> <tr> <td>75:03.332</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.</td> </tr> <tr> <td>75:04.038</td> <td>Info</td> <td>Delay</td> <td>Waiting for 2s.</td> </tr> <tr> <td>75:06.064</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.</td> </tr> <tr> <td>75:06.772</td> <td>Info</td> <td>Delay</td> <td>Waiting for 2s.</td> </tr> </tbody> </table>		Time	Level	Category	Message	74:44.242	Info	Data	Current variable values:  \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'ReSound Branded Standard PE'	74:44.260	Info	Delay	Waiting for 10s.	74:54.349	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.	74:55.170	Info	Delay	Waiting for 3s.	74:58.202	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.	75:01.255	Info	Delay	Waiting for 2s.	75:03.332	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.	75:04.038	Info	Delay	Waiting for 2s.	75:06.064	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.	75:06.772	Info	Delay	Waiting for 2s.
Time	Level	Category	Message																																										
74:44.242	Info	Data	Current variable values:  \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'ReSound Branded Standard PE'																																										
74:44.260	Info	Delay	Waiting for 10s.																																										
74:54.349	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.																																										
74:55.170	Info	Delay	Waiting for 3s.																																										
74:58.202	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.																																										
75:01.255	Info	Delay	Waiting for 2s.																																										
75:03.332	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.																																										
75:04.038	Info	Delay	Waiting for 2s.																																										
75:06.064	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.																																										
75:06.772	Info	Delay	Waiting for 2s.																																										

75:08.815	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
75:09.516	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
75:10.204	Info	Delay	Waiting for 3s.
75:13.261	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
75:13.988	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
75:14.705	Info	Mouse	Mouse scroll Vertical by 600 units.
75:15.045	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
75:15.737	Info	Delay	Waiting for 2s.
75:17.797	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
75:18.516	Info	Delay	Waiting for 3s.
75:21.555	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
75:22.238	Info	Delay	Waiting for 3s.
75:39.325	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
75:40.043	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
76:09.154	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
76:09.258	Success	Validation	Element for item 'ButtonFinish' does exist. 
76:09.277	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
76:09.957	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'ReSound Branded Standard PE', \$TxtKey = 'ReSound Branded Standard PE', \$TxtValue = 'ReSound Branded Standard PE', \$TxtMarket = 'ReSound Branded Standard PE'
76:10.803	Success	User	Pass :undoredo-master- True = ON 

76:10.829	Success	User	Pass :pediatrics-master- True = ON
76:10.860	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
76:10.877	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
76:10.910	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
76:10.929	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
76:10.961	Success	User	Pass :offline-firmware-update-master- True = ON
76:10.993	Success	User	Pass :fitting-rules-master- True = ON
76:11.028	Success	User	Pass :autorem-master- True = ON
76:19.158	Info	Delay	Waiting for 10s.
76:29.182	Info	Delay	Waiting for 10s.
76:47.282	Info	Delay	Waiting for 10s. 
77:05.370	Info	Delay	Waiting for 6s. 
77:11.399	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms ↑

### FeatureFlag\_Validation\_Folder

Data Row: 32

2.5m ↑

**Marketname:** ReSound Standard PE

**BuildName:** ReSound Smart Fit 1.6.0.184

Installing_Builds			
Installation			
Time	Level	Category	Message
77:11.547	Info	Data	Current variable values:  \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'ReSound Standard PE'
77:11.577	Info	Delay	Waiting for 10s.
77:21.663	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
77:22.485	Info	Delay	Waiting for 3s.
77:25.519	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
77:28.556	Info	Delay	Waiting for 2s.
77:30.588	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
77:31.274	Info	Delay	Waiting for 2s.
77:33.302	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
77:34.007	Info	Delay	Waiting for 2s.
77:36.047	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
77:36.750	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
77:37.455	Info	Delay	Waiting for 3s.
77:40.490	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
77:41.185	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
77:41.884	Info	Mouse	Mouse scroll Vertical by 600 units.
77:42.212	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
77:42.903	Info	Delay	Waiting for 2s.
77:44.932	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
77:45.654	Info	Delay	Waiting for 3s.
77:48.677	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
77:49.387	Info	Delay	Waiting for 3s.
78:06.434	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
78:07.157	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
78:37.150	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.

78:37.253	Success	Validation	Element for item 'ButtonFinish' does exist.
78:37.277	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m ↑

### ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
78:37.989	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'ReSound Standard PE', \$TxtKey = 'ReSound Standard PE', \$TxtValue = 'ReSound Standard PE', \$TxtMarket = 'ReSound Standard PE'
78:38.985	Success	User	Pass :undoredo-master- True = ON
78:39.014	Success	User	Pass :pediatrics-master- True = ON
78:39.057	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
78:39.078	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
78:39.118	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
78:39.145	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
78:39.178	Success	User	Pass :offline-firmware-update-master- True = ON
78:39.210	Success	User	Pass :fitting-rules-master- True = ON
78:39.244	Success	User	Pass :autorem-master- True = ON
78:47.392	Info	Delay	Waiting for 10s.
78:57.420	Info	Delay	Waiting for 10s.
79:15.530	Info	Delay	Waiting for 10s. 

79:33.636	Info	Delay	Waiting for 6s. 
79:39.684	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

 FeatureFlag_Validation_Folder	Data Row: 33	2.5m 
<b>Marketname:</b> Romania		
<b>BuildName:</b> ReSound Smart Fit 1.6.0.184		

 Installing_Builds	1.5m 																																																								
 Installation																																																									
<table border="1"> <thead> <tr> <th>Time</th> <th>Level</th> <th>Category</th> <th>Message</th> </tr> </thead> <tbody> <tr> <td>79:39.806</td> <td>Info</td> <td>Data</td> <td>Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Romania'</td> </tr> <tr> <td>79:39.827</td> <td>Info</td> <td>Delay</td> <td>Waiting for 10s.</td> </tr> <tr> <td>79:49.913</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.</td> </tr> <tr> <td>79:50.818</td> <td>Info</td> <td>Delay</td> <td>Waiting for 3s.</td> </tr> <tr> <td>79:53.848</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.</td> </tr> <tr> <td>79:56.905</td> <td>Info</td> <td>Delay</td> <td>Waiting for 2s.</td> </tr> <tr> <td>79:58.936</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.</td> </tr> <tr> <td>79:59.638</td> <td>Info</td> <td>Delay</td> <td>Waiting for 2s.</td> </tr> <tr> <td>80:01.665</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.</td> </tr> <tr> <td>80:02.350</td> <td>Info</td> <td>Delay</td> <td>Waiting for 2s.</td> </tr> <tr> <td>80:04.391</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.</td> </tr> <tr> <td>80:05.103</td> <td>Info</td> <td>Mouse</td> <td>Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.</td> </tr> <tr> <td>80:05.788</td> <td>Info</td> <td>Delay</td> <td>Waiting for 3s.</td> </tr> </tbody> </table>		Time	Level	Category	Message	79:39.806	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Romania'	79:39.827	Info	Delay	Waiting for 10s.	79:49.913	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.	79:50.818	Info	Delay	Waiting for 3s.	79:53.848	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.	79:56.905	Info	Delay	Waiting for 2s.	79:58.936	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.	79:59.638	Info	Delay	Waiting for 2s.	80:01.665	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.	80:02.350	Info	Delay	Waiting for 2s.	80:04.391	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.	80:05.103	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.	80:05.788	Info	Delay	Waiting for 3s.
Time	Level	Category	Message																																																						
79:39.806	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Romania'																																																						
79:39.827	Info	Delay	Waiting for 10s.																																																						
79:49.913	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.																																																						
79:50.818	Info	Delay	Waiting for 3s.																																																						
79:53.848	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.																																																						
79:56.905	Info	Delay	Waiting for 2s.																																																						
79:58.936	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.																																																						
79:59.638	Info	Delay	Waiting for 2s.																																																						
80:01.665	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.																																																						
80:02.350	Info	Delay	Waiting for 2s.																																																						
80:04.391	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.																																																						
80:05.103	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.																																																						
80:05.788	Info	Delay	Waiting for 3s.																																																						

80:08.818	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
80:09.517	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
80:10.215	Info	Mouse	Mouse scroll Vertical by 600 units.
80:10.544	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
80:11.488	Info	Delay	Waiting for 2s.
80:13.515	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
80:14.220	Info	Delay	Waiting for 3s.
80:17.254	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
80:17.956	Info	Delay	Waiting for 3s.
80:35.084	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
80:35.772	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
81:06.977	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
81:07.085 ✓	Success	Validation	Element for item 'ButtonFinish' does exist.
81:07.110	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.


## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
81:07.816	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Romania', \$TxtKey = 'Romania', \$TxtValue = 'Romania', \$TxtMarket = 'Romania'
81:08.594 ✓	Success	User	Pass :undoredo-master- True = ON
81:08.628 ✓	Success	User	Pass :pediatrics-master- True = ON
81:08.660 ✗	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
81:08.676 ✗	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON

81:08.709	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
81:08.726	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
81:08.760	Success	User	Pass :offline-firmware-update-master- True = ON
81:08.792	Success	User	Pass :fitting-rules-master- True = ON
81:08.826	Success	User	Pass :autorem-master- True = ON
81:16.932	Info	Delay	Waiting for 10s.
81:26.972	Info	Delay	Waiting for 10s.
81:45.125	Info	Delay	Waiting for 10s. 
82:03.263	Info	Delay	Waiting for 6s. 
82:09.300	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms 

### FeatureFlag\_Validation\_Folder

Data Row: 34

2.6m 

**Marketname:** Russia

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m 

### Installation

1.5m 

Time	Level	Category	Message
82:09.453	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Russia'

82:09.476	Info	Delay	Waiting for 10s.
82:19.711	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
82:20.609	Info	Delay	Waiting for 3s.
82:23.654	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
82:26.804	Info	Delay	Waiting for 2s.
82:28.838	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
82:29.538	Info	Delay	Waiting for 2s.
82:31.564	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
82:32.286	Info	Delay	Waiting for 2s.
82:34.320	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
82:35.018	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
82:35.702	Info	Delay	Waiting for 3s.
82:38.732	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
82:39.435	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
82:40.148	Info	Mouse	Mouse scroll Vertical by 600 units.
82:40.486	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
82:41.398	Info	Delay	Waiting for 2s.
82:43.459	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
82:44.184	Info	Delay	Waiting for 3s.
82:47.222	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
82:47.936	Info	Delay	Waiting for 3s.
83:04.983	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
83:05.713	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
83:40.211	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
83:40.359	Success	Validation	Element for item 'ButtonFinish' does exist.
83:40.376	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m ↗

### ValidatingXML\_And\_Excel

1m ↗

Time	Level	Category	Message
83:41.069	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Russia', \$TxtKey = 'Russia', \$TxtValue = 'Russia', \$TxtMarket = 'Russia'
83:41.873	Success	User	Pass :undoredo-master- True = ON 
83:41.894	Success	User	Pass :pediatrics-master- True = ON 
83:41.926	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
83:41.960	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
83:41.992	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
83:42.025	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 
83:42.061	Success	User	Pass :offline-firmware-update-master- True = ON 
83:42.093	Success	User	Pass :fitting-rules-master- True = ON 
83:42.109	Success	User	Pass :autorem-master- True = ON 
83:50.210	Info	Delay	Waiting for 10s.
84:00.257	Info	Delay	Waiting for 10s.
84:18.378	Info	Delay	Waiting for 10s. 
84:36.522	Info	Delay	Waiting for 6s. 

84:42.554	Error	Module	The module has failed because one or more actions have failed. 
-----------	-------	--------	--

## TEARDOWN

0ms 

### FeatureFlag\_Validation\_Folder Data Row: 35

2.5m 

**Marketname:** South Africa

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.4m 

### Installation

1.4m 

Time	Level	Category	Message
84:42.689	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'South Africa'
84:42.709	Info	Delay	Waiting for 10s.
84:52.809	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
84:53.650	Info	Delay	Waiting for 3s.
84:56.711	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
84:59.737	Info	Delay	Waiting for 2s.
85:01.761	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
85:02.467	Info	Delay	Waiting for 2s.
85:04.502	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
85:05.203	Info	Delay	Waiting for 2s.
85:07.243	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
85:07.968	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
85:08.689	Info	Delay	Waiting for 3s.
85:11.739	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
85:12.431	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.

85:13.150	Info	Mouse	Mouse scroll Vertical by 600 units.
85:13.484	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
85:14.401	Info	Delay	Waiting for 2s.
85:16.452	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
85:17.167	Info	Delay	Waiting for 3s.
85:20.195	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
85:20.905	Info	Delay	Waiting for 3s.
85:38.014	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
85:38.708	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
86:07.102	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
86:07.199	Success	Validation	Element for item 'ButtonFinish' does exist. ✓
86:07.226	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
86:07.926	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'South Africa', \$TxtKey = 'South Africa', \$TxtValue = 'South Africa', \$TxtMarket = 'South Africa'
86:09.223	Success	User	Pass :undoredo-master- True = ON ✓
86:09.243	Success	User	Pass :pediatrics-master- True = ON ✓
86:09.275	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON ✗
86:09.308	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON ✗
86:09.325	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON ✗
86:09.359	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF ✓

86:09.375	Success	User	Pass :offline-firmware-update-master- True = ON
86:09.409	Success	User	Pass :fitting-rules-master- True = ON
86:09.425	Success	User	Pass :autorem-master- True = ON
86:17.549	Info	Delay	Waiting for 10s.
86:27.588	Info	Delay	Waiting for 10s.
86:45.714	Info	Delay	Waiting for 10s. 
87:03.847	Info	Delay	Waiting for 6s. 
87:09.883	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms



### FeatureFlag\_Validation\_Folder Data Row: 36

2.6m



**Marketname:** Spain

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m



### Installation

1.5m



Time	Level	Category	Message
87:10.051	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Spain'
87:10.075	Info	Delay	Waiting for 10s.
87:20.139	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
87:20.984	Info	Delay	Waiting for 3s.

87:24.035	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
87:27.122	Info	Delay	Waiting for 2s.
87:29.145	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
87:29.851	Info	Delay	Waiting for 2s.
87:31.885	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
87:32.586	Info	Delay	Waiting for 2s.
87:34.619	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
87:35.313	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
87:36.022	Info	Delay	Waiting for 3s.
87:39.076	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
87:39.788	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
87:40.486	Info	Mouse	Mouse scroll Vertical by 600 units.
87:40.830	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
87:41.772	Info	Delay	Waiting for 2s.
87:43.801	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
87:44.481	Info	Delay	Waiting for 3s.
87:47.516	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
87:48.221	Info	Delay	Waiting for 3s.
88:05.264	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
88:05.971	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
88:41.119	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
88:41.223	Success	Validation	Element for item 'ButtonFinish' does exist.
88:41.242	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
------	-------	----------	---------

88:41.956	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Spain', \$TxtKey = 'Spain', \$TxtValue = 'Spain', \$TxtMarket = 'Spain'
88:43.019	Success	User	Pass :undoredo-master- True = ON 
88:43.059	Success	User	Pass :pediatrics-master- True = ON 
88:43.092	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
88:43.125	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
88:43.158	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
88:43.191	Success	User	Pass :teleaudiology-tsrestricted-fsw- False = OFF 
88:43.225	Success	User	Pass :offline-firmware-update-master- True = ON 
88:43.258	Success	User	Pass :fitting-rules-master- True = ON 
88:43.292	Success	User	Pass :autorem-master- True = ON 
88:51.704	Info	Delay	Waiting for 10s.
89:01.737	Info	Delay	Waiting for 10s.
89:20.038	Info	Delay	Waiting for 10s. 
89:38.143	Info	Delay	Waiting for 6s. 
89:44.218	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms ↑

## 📁 FeatureFlag\_Validation\_Folder Data Row: 37

2.6m ↑

**Marketname:** Sweden**BuildName:** ReSound Smart Fit 1.6.0.184

## 🎬 Installing\_Builds

1.5m ↑

## 🎥 Installation

1.5m ↑

Time	Level	Category	Message
89:44.365	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Sweden'
89:44.392	Info	Delay	Waiting for 10s.
89:54.476	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
89:55.498	Info	Delay	Waiting for 3s.
89:58.535	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
90:01.769	Info	Delay	Waiting for 2s.
90:03.802	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
90:04.501	Info	Delay	Waiting for 2s.
90:06.527	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
90:07.268	Info	Delay	Waiting for 2s.
90:09.297	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
90:09.983	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
90:10.685	Info	Delay	Waiting for 3s.
90:13.711	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
90:14.415	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
90:15.117	Info	Mouse	Mouse scroll Vertical by 600 units.
90:15.452	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
90:16.414	Info	Delay	Waiting for 2s.
90:18.451	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
90:19.179	Info	Delay	Waiting for 3s.

90:22.217	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
90:22.918	Info	Delay	Waiting for 3s.
90:40.014	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
90:40.717	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
91:16.009	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
91:16.124	Success	Validation	Element for item 'ButtonFinish' does exist. 
91:16.142	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
91:16.838	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Sweden', \$TxtKey = 'Sweden', \$TxtValue = 'Sweden', \$TxtMarket = 'Sweden'
91:17.952	Success	User	Pass :undoredo-master- True = ON 
91:17.977	Success	User	Pass :pediatrics-master- True = ON 
91:18.019	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
91:18.043	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
91:18.075	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
91:18.108	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF 
91:18.141	Success	User	Pass :offline-firmware-update-master- True = ON 
91:18.161	Success	User	Pass :fitting-rules-master- True = ON 
91:18.191	Success	User	Pass :autorem-master- True = ON 

91:26.515	Info	Delay	Waiting for 10s.
91:36.554	Info	Delay	Waiting for 10s.
91:54.705	Info	Delay	Waiting for 10s. 
92:12.846	Info	Delay	Waiting for 6s. 
92:18.882	Error	Module	The module has failed because one or more actions have failed.  ✖

## TEARDOWN

1ms



## FeatureFlag\_Validation\_Folder

Data Row: 38

2.6m



**Marketname:** Switzerland

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.5m



### Installation

1.5m



Time	Level	Category	Message
------	-------	----------	---------

92:19.046	Info	Data	Current variable values:
-----------	------	------	--------------------------

\$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Switzerland'
--

92:19.083	Info	Delay	Waiting for 10s.
-----------	------	-------	------------------

92:29.244	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
-----------	------	-------	---

92:30.081	Info	Delay	Waiting for 3s.
-----------	------	-------	-----------------

92:33.113	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
-----------	------	-------	--

92:36.170	Info	Delay	Waiting for 2s.
-----------	------	-------	-----------------

92:38.202	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
-----------	------	-------	--

92:38.899	Info	Delay	Waiting for 2s.
-----------	------	-------	-----------------

92:40.935	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
92:41.635	Info	Delay	Waiting for 2s.
92:43.662	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
92:44.364	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
92:45.067	Info	Delay	Waiting for 3s.
92:48.091	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
92:48.786	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
92:49.537	Info	Mouse	Mouse scroll Vertical by 600 units.
92:49.873	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
92:50.802	Info	Delay	Waiting for 2s.
92:52.825	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
92:53.566	Info	Delay	Waiting for 3s.
92:56.592	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
92:57.319	Info	Delay	Waiting for 3s.
93:14.391	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
93:15.107	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
93:49.888	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
93:50.025 ✓	Success	Validation	Element for item 'ButtonFinish' does exist.
93:50.057	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## ⌚ Verifying\_Feature\_Availability

1m ↑

### 🎥 ValidatingXML\_And\_Excel

1m ↑

Time	Level	Category	Message
93:50.754	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Switzerland', \$TxtKey = 'Switzerland', \$TxtValue = 'Switzerland', \$TxtMarket = 'Switzerland'

93:51.581	Success	User	Pass :undoredo-master- True = ON
93:51.609	Success	User	Pass :pediatrics-master- True = ON
93:51.640	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
93:51.689	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
93:51.726	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
93:51.758	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
93:51.790	Success	User	Pass :offline-firmware-update-master- True = ON
93:51.824	Success	User	Pass :fitting-rules-master- True = ON
93:51.840	Success	User	Pass :autorem-master- True = ON
94:00.035	Info	Delay	Waiting for 10s.
94:10.060	Info	Delay	Waiting for 10s.
94:28.214	Info	Delay	Waiting for 10s. 
94:46.326	Info	Delay	Waiting for 6s. 
94:52.368	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

1ms ↑



FeatureFlag\_Validation\_Folder

Data Row: 39

2.5m



**Marketname:** Taiwan

**BuildName:** ReSound Smart Fit 1.6.0.184

## 🎬 Installing\_Builds

1.5m ↑

### 🎥 Installation

1.5m ↑

Time	Level	Category	Message
94:52.483	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Taiwan'
94:52.526	Info	Delay	Waiting for 10s.
95:02.646	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
95:03.484	Info	Delay	Waiting for 3s.
95:06.518	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
95:09.635	Info	Delay	Waiting for 2s.
95:11.661	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
95:12.365	Info	Delay	Waiting for 2s.
95:14.394	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
95:15.134	Info	Delay	Waiting for 2s.
95:17.160	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgree' at Center.
95:17.868	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
95:18.587	Info	Delay	Waiting for 3s.
95:21.614	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
95:22.317	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
95:23.054	Info	Mouse	Mouse scroll Vertical by 600 units.
95:23.383	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
95:24.315	Info	Delay	Waiting for 2s.
95:26.352	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
95:27.047	Info	Delay	Waiting for 3s.
95:30.082	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
95:30.782	Info	Delay	Waiting for 3s.
95:47.842	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.

95:48.536	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
96:21.089	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
96:21.184	Success	Validation	Element for item 'ButtonFinish' does exist. 
96:21.207	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
96:21.901	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Taiwan', \$TxtKey = 'Taiwan', \$TxtValue = 'Taiwan', \$TxtMarket = 'Taiwan'
96:22.698	Success	User	Pass :undoredo-master- True = ON 
96:22.724	Success	User	Pass :pediatrics-master- True = ON 
96:22.776	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON 
96:22.807	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
96:22.840	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON 
96:22.874	Success	User	Pass :teleaudiology-tscrestricted-fsw- False = OFF 
96:22.894	Success	User	Pass :offline-firmware-update-master- True = ON 
96:22.923	Success	User	Pass :fitting-rules-master- True = ON 
96:22.940	Success	User	Pass :autorem-master- True = ON 
96:31.063	Info	Delay	Waiting for 10s.
96:41.103	Info	Delay	Waiting for 10s.

96:59.232	Info	Delay	Waiting for 10s. 
97:17.379	Info	Delay	Waiting for 6s. 
97:23.409	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms 

 FeatureFlag_Validation_Folder	Data Row: 40	2.5m 
<b>Marketname:</b> Thailand		
<b>BuildName:</b> ReSound Smart Fit 1.6.0.184		

## Installing\_Builds

1.5m 

Time	Level	Category	Message
97:23.522	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Thailand'
97:23.540	Info	Delay	Waiting for 10s.
97:33.642	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
97:34.534	Info	Delay	Waiting for 3s.
97:37.563	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
97:40.630	Info	Delay	Waiting for 2s.
97:42.665	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
97:43.351	Info	Delay	Waiting for 2s.
97:45.422	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
97:46.118	Info	Delay	Waiting for 2s.

97:48.149	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreem' at Center.
97:48.845	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
97:49.570	Info	Delay	Waiting for 3s.
97:52.600	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
97:53.300	Info	Mouse	Mouse Left Click item 'ResoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
97:54.000	Info	Mouse	Mouse scroll Vertical by 600 units.
97:54.333	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
97:55.264	Info	Delay	Waiting for 2s.
97:57.299	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
97:57.999	Info	Delay	Waiting for 3s.
98:01.032	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
98:01.730	Info	Delay	Waiting for 3s.
98:18.813	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
98:19.535	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
98:50.715	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.
98:50.851	Success	Validation	Element for item 'ButtonFinish' does exist. 
98:50.887	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m 

### ValidatingXML\_And\_Excel

1m 

Time	Level	Category	Message
98:51.590	Info	Data	Current variable values:  \$XML_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Thailand', \$TxtKey = 'Thailand', \$TxtValue = 'Thailand', \$TxtMarket = 'Thailand'
98:52.453	Success	User	Pass :undoredo-master- True = ON 

98:52.475	Success	User	Pass :pediatrics-master- True = ON
98:52.566	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
98:52.599	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
98:52.624	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
98:52.672	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
98:52.707	Success	User	Pass :offline-firmware-update-master- True = ON
98:52.740	Success	User	Pass :fitting-rules-master- True = ON
98:52.773	Success	User	Pass :autorem-master- True = ON
99:00.986	Info	Delay	Waiting for 10s.
99:11.007	Info	Delay	Waiting for 10s.
99:29.134	Info	Delay	Waiting for 10s. 
99:47.243	Info	Delay	Waiting for 6s. 
99:53.294	Error	Module	The module has failed because one or more actions have failed. 

## TEARDOWN

0ms ↑

### FeatureFlag\_Validation\_Folder

Data Row: 41

2.6m ↑

**Marketname:** Turkey

**BuildName:** ReSound Smart Fit 1.6.0.184

## Installing\_Builds

1.6m ↑

### Installation

1.6m ↑

Time	Level	Category	Message
99:53.408	Info	Data	Current variable values: \$FSWBrand = 'ReSound Smart Fit 1.6.0.184', \$TxtMkt = 'Turkey'
99:53.445	Info	Delay	Waiting for 10s.
100:03.572	Info	Mouse	Mouse Left Click item 'SmartFit15InstallShieldWizard.ButtonOK' at Center.
100:04.380	Info	Delay	Waiting for 3s.
100:07.408	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
100:10.368	Info	Delay	Waiting for 2s.
100:12.400	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
100:13.118	Info	Delay	Waiting for 2s.
100:15.140	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
100:15.849	Info	Delay	Waiting for 2s.
100:17.876	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.IAcceptTheTermsInTheLicenseAgreement' at Center.
100:18.579	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
100:19.283	Info	Delay	Waiting for 3s.
100:22.315	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.CheckBoxStandalone' at Center.
100:23.011	Info	Mouse	Mouse Left Click item 'ReSoundSmartFitProgramsAndFeature.ComboBox17451' at Center.
100:23.716	Info	Mouse	Mouse scroll Vertical by 600 units.
100:24.069	Info	Mouse	Mouse Left Click item 'List1000.Australia' at Center.
100:24.962	Info	Delay	Waiting for 2s.
100:26.993	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
100:27.695	Info	Delay	Waiting for 3s.
100:30.732	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonNext' at Center.
100:31.449	Info	Delay	Waiting for 3s.
100:48.564	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonInstall' at Center.
100:49.285	Info	Wait	Waiting 5s for the attribute 'Visible' to equal the specified value 'True'. Associated repository item: 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'
101:25.720	Info	Validation	Validating Exists on item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish'.

101:25.818	Success	Validation	Element for item 'ButtonFinish' does exist.
101:25.840	Info	Mouse	Mouse Left Click item 'ReSoundSmartFit15InstallShieldWi.ButtonFinish' at Center.

## Verifying\_Feature\_Availability

1m ↑

ValidatingXML_And_Excel			
Time	Level	Category	Message
101:26.576	Info	Data	Current variable values:  \$XMI_FlagKey_Buildname = 'ReSound Smart Fit 1.6.0.184', \$XML_FeatureFlag_Values_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_FlagKeyMethod_Buildname = 'ReSound Smart Fit 1.6.0.184', \$Excel_Brand_Buildname = 'ReSound Smart Fit 1.6.0.184', \$DeleteFilesBuildname = 'ReSound Smart Fit 1.6.0.184', \$UninstallBuildname = 'ReSound Smart Fit 1.6.0.184', \$XML_flagKey_Marketname = 'Turkey', \$TxtKey = 'Turkey', \$TxtValue = 'Turkey', \$TxtMarket = 'Turkey'
101:27.365	Success	User	Pass :undoredo-master- True = ON
101:27.408	Success	User	Pass :pediatrics-master- True = ON
101:27.441	Failure	User	Fail :teleaudiology-master : FeatureFlag Value of Flag file is :false - and Excel File is :ON
101:27.473	Failure	User	Fail :teleaudiology-video-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
101:27.506	Failure	User	Fail :teleaudiology-fitting-fsw : FeatureFlag Value of Flag file is :false -and Excel File is :ON
101:27.539	Success	User	Pass :teleaudiology-tsgrestricted-fsw- False = OFF
101:27.558	Success	User	Pass :offline-firmware-update-master- True = ON
101:27.589	Success	User	Pass :fitting-rules-master- True = ON
101:27.607	Success	User	Pass :autorem-master- True = ON
101:35.724	Info	Delay	Waiting for 10s.
101:45.762	Info	Delay	Waiting for 10s.
102:03.868	Info	Delay	Waiting for 10s. 

102:22.013	Info	Delay	Waiting for 6s. 
102:28.055	Error	Module	The module has failed because one or more actions have failed. 

TEARDOWN

1ms

