

Πολυτεχνική Σχολή Τμήμα Μηχανικών Η/Υ & Πληροφορικής

ΕΡΓΑΣΤΗΡΙΟ ΜΙΚΡΟΕΠΕΞΕΡΓΑΣΤΩΝ

ΟΜΑΔΑ Β1 - ΕΡΓΑΣΤΗΡΙΑΚΗ ΑΣΚΗΣΗ 2


Στοιχεία Φοιτητών:

Αλευράς Ηλίας <u>up1069667@upnet.gr</u> 1069667

Σάββας Στυλιανού <u>up1069661@upnet.gr</u> 1069661

Κανονική λειτουργία

Διάγραμμα Ροής:



Κώδικας

```
#include <avr/io.h>
#include <util/delay.h>
#include <avr/interrupt.h>
#define T1 10
#define T2 10
int zero = 0;
int p;
int z;
int k;
int t;
int y;
int main(void){
       //PIN is output
       PORTD.DIR |= 0b00000001; //PIN0_bm right
       //PIN is output
       PORTD.DIR |= 0b00000010; //PIN1_bm straight
       //PIN is output
       PORTD.DIR |= 0b00000100; //PIN2_bm left
       //LED is off
       PORTD.OUT |= 0b00000001; //PIN0 bm
       //LED is off
       PORTD.OUT |= 0b00000010; //PIN1_bm
       //LED is off
       PORTD.OUT |= 0b00000100; //PIN2_bm
       CLOCK_init();
       //interrupt
       PORTF.PIN5CTRL |= PORT_PULLUPEN_bm | PORT_ISC_BOTHEDGES_gc;
       //TIMER freerunning mode
       /* Load the Compare or Capture register with the timeout value*/
       TCB0.CCMP |= T1;
       /* Enable Capture or Timeout interrupt */
```

```
TCBO.CTRLB |= TCB CNTMODE INT gc;
       //TIMER single convertion
       /* Load the Compare or Capture register with the timeout value*/
       TCB1.CCMP = T2;
       /* Configure TCB in Periodic Timeout mode */
       TCB1.CTRLB = TCB_CNTMODE_INT_gc;
       /* Enable Capture or Timeout interrupt */
       TCB1.INTCTRL = TCB_CAPT_bm;
       //TIMER strofis
       /* Load the Compare or Capture register with the timeout value*/
       TCB2.CCMP = T2;
       /* Configure TCB in Periodic Timeout mode */
       TCB2.CTRLB = TCB_CNTMODE_INT_gc;
       /* Enable Capture or Timeout interrupt */
       TCB2.INTCTRL = TCB CAPT bm;
       PORTD.DIR |= PIN1_bm; //PIN is output
       //initialize the ADC for Free-Running mode
       ADCO.CTRLA |= ADC_RESSEL_10BIT_gc; //10-bit resolution
       ADCO.CTRLA |= ADC_FREERUN_bm; //Free-Running mode enabled
       ADCO.CTRLA |= ADC ENABLE bm; //Enable ADC
       ADCO.MUXPOS |= ADC_MUXPOS_AIN7_gc; //The bit //Enable Debug Mode
       ADCO.DBGCTRL |= ADC DBGRUN bm; //Window Comparator Mode
       ADCO.WINLT |= 10; //Set threshold
       ADCO.INTCTRL |= ADC WCMP bm; //Enable Interrupts for WCM
       ADCO.CTRLE |= ADC WINCMO bm; //Interrupt when RESULT < WINLT
       sei();
       y=0;
       while(y<4){//to robot tha kanei 4 strofes kai tha stamatisi</pre>
              p=0;
              t=1;
              //energopiisi mprostinou esthitira
              straight on();
              ADCO.CTRLA &= ~ADC FREERUN bm; //Free-Running mode disabled
              ADCO.COMMAND |= ADC_STCONV_bm; //Start Conversion
              //energopiisi timer
              TCB1.CTRLA |= TCB_CLKSEL_CLKDIV1_gc;
              TCB1.CTRLA |= TCB_ENABLE_bm;
              while(p==0){//perimene timer
              if(t==0){ // mpeni mono otan energopiithi i isr tou adc
                     TCB2.CTRLA |= TCB_CLKSEL_CLKDIV1_gc; //ksekina to t2
                     TCB2.CTRLA |= TCB_ENABLE_bm;
                     while (k==0){ //perimene timer strofis t2
                     left_off();
                     straight_on();
                     y++; //metritis strofon
              }
       }
}
void right_on(){
```

TCB0.INTCTRL |= TCB CAPT bm;

```
//on
       PORTD.OUTCLR= 0b00000001; //PIN0 bm
void right_off(){
       //LED is off
       PORTD.OUT |= 0b00000001; //PIN0_bm
}
void straight_on(){
       //on
       PORTD.OUTCLR= 0b00000010; //PIN1_bm
void straight_off(){
       //LED is off
       PORTD.OUT |= 0b00000010; //PIN1_bm
}
void left_on(){
       //on
       PORTD.OUTCLR= 0b00000100; //PIN2 bm
}
void left_off(){
       //LED is off
       PORTD.OUT |= 0b00000100; //PIN2_bm
}
void all on(){
       PORTD.OUTCLR= 0b00000001; //PIN0 bm
       PORTD.OUTCLR= 0b00000010; //PIN1 bm
       PORTD.OUTCLR= 0b00000100; //PIN2 bm
}
void all off(){
       //LED is off
       PORTD.OUT |= 0b00000001; //PIN0 bm
       //LED is off
       PORTD.OUT |= 0b00000010; //PIN1_bm
       //LED is off
       PORTD.OUT |= 0b00000100; //PIN2_bm
}
void CLOCK_init (void)
{
       /* Enable writing to protected register */
       CPU_CCP = CCP_IOREG_gc;
       /* Enable Prescaler and set Prescaler Division to 64 */
       CLKCTRL.MCLKCTRLB = CLKCTRL PDIV 64X gc | CLKCTRL PEN bm;
       /* Enable writing to protected register */
       CPU_CCP = CCP_IOREG_gc;
       /* Select 32KHz Internal Ultra Low Power Oscillator (OSCULP32K) */
       CLKCTRL.MCLKCTRLA = CLKCTRL_CLKSEL_OSCULP32K_gc;
       /* Wait for system oscillator changing to finish */
       while (CLKCTRL.MCLKSTATUS & CLKCTRL_SOSC_bm)
              ;
       }
}
```


```
ISR(TCB0 INT vect){
       TCBO.INTFLAGS |= TCB CAPT bm; /* Clear the interrupt flag */
       TCBO.CTRLA &= ~TCB ENABLE bm;
       z=1;
ISR(TCB1 INT vect){
       TCB1.INTFLAGS |= TCB_CAPT_bm; /* Clear the interrupt flag */
       TCB1.CTRLA &= ~TCB_ENABLE_bm;
       p=1;
ISR(TCB2 INT vect){
       TCB2.INTFLAGS |= TCB CAPT bm; /* Clear the interrupt flag */
       TCB2.CTRLA &= ~TCB ENABLE bm;
       k=1;
}
ISR(PORTF PORT vect){
       //clear the interrupt flag
       int z = PORTF.INTFLAGS;
       PORTF.INTFLAGS=z;
}
ISR(ADC0 WCOMP vect){
       int intflags = ADCO.INTFLAGS;
       ADCO.INTFLAGS = intflags;
       t=0; // gia na mpi stin if tis strofis
       straight off();
       left on();
}
```

Περιγραφή

Στο πρόγραμμα μας χρησιμοποιούμε 2 χρονίστες, τον tcb1 ο οποίος μετρά και μέχρι να δεχτεί τιμή ο μπροστινός αισθητήρας και tcb2 ο οποίος μετρά μέχρι να γίνει η στροφή. Επίσης χρησιμοποιούμε ένα adc ο οποίος είναι συνεχώς σε single conversion γιατί χρησιμοποιούμε μόνο τον μπροστινό αισθητήρα. Αρχικά η λειτουργίες του προγράμματος μας εμπεριέχονται μέσα σε μια while που μετρά μέχρι 4 όσες είναι δηλαδή και οι στροφές οπού θα κάνει. Ξεκινούμε με το LED της ευθείας αναμμένο και ξεκινούμε τον adc. Στην συνέχεια ξεκινούμε και τον timer οπού περιμένει τον adc να πάρει τιμή. Εάν ο adc πάρει τιμή RESULT < WINLT τότε εισέρχεται μέσα στην if οπού γίνεται η στροφή. Στην if ενεργοποιείται το LED τις αριστερής στροφής και ο timer του. Αφού τελειώσει ο timer το LED γίνεται οff και προσθέτουμε 1 στην μεταβλητή στροφών γ.

Δυο αμβλείες γωνίες

Διάγραμμα Ροής:



Κώδικας

```
#include <avr/io.h>
#include <util/delay.h>
#include <avr/interrupt.h>
#define T1 10
#define T2 10
int zero = 0;
int p;//gia na stamatisi i while
int z;//gia na stamatisi i while
int y=0;//metritis strofon
int x;//dixni pou na gini strofi aristera i deksia
int t;
int k;
int main(void){
       //PIN is output
       PORTD.DIR |= 0b00000001; //PIN0_bm right
       //PIN is output
       PORTD.DIR |= 0b00000010; //PIN1_bm straight
       //PIN is output
```

```
PORTD.DIR |= 0b00000100; //PIN2_bm left
//LED is off
PORTD.OUT |= 0b00000001; //PIN0 bm
//LED is off
PORTD.OUT |= 0b00000010; //PIN1_bm
//LED is off
PORTD.OUT |= 0b00000100; //PIN2_bm
CLOCK_init();
//interrupt
PORTF.PIN5CTRL |= PORT_PULLUPEN_bm | PORT_ISC_BOTHEDGES_gc;
//TIMER freerunning mode
/* Load the Compare or Capture register with the timeout value*/
TCB0.CCMP |= T1;
/* Enable Capture or Timeout interrupt */
TCB0.INTCTRL |= TCB CAPT bm;
TCBO.CTRLB |= TCB CNTMODE INT gc;
//TIMER single convertion
/* Load the Compare or Capture register with the timeout value*/
TCB1.CCMP = T2;
/* Configure TCB in Periodic Timeout mode */
TCB1.CTRLB = TCB CNTMODE_INT_gc;
/* Enable Capture or Timeout interrupt */
TCB1.INTCTRL = TCB CAPT bm;
//TIMER strofis
/* Load the Compare or Capture register with the timeout value*/
TCB2.CCMP = T2:
/* Configure TCB in Periodic Timeout mode */
TCB2.CTRLB = TCB CNTMODE INT gc;
/* Enable Capture or Timeout interrupt */
TCB2.INTCTRL = TCB CAPT bm;
PORTD.DIR |= PIN1 bm; //PIN is output
//initialize the ADC for Free-Running mode
ADCO.CTRLA |= ADC_RESSEL_10BIT_gc; //10-bit resolution
ADCO.CTRLA = ADC_FREERUN_bm; //Free-Running mode enabled
ADCO.CTRLA |= ADC_ENABLE_bm; //Enable ADC
ADCO.MUXPOS |= ADC_MUXPOS_AIN7_gc; //The bit //Enable Debug Mode
ADCO.DBGCTRL |= ADC_DBGRUN_bm; //Window Comparator Mode
ADCO.WINLT |= 10; //Set threshold
ADCO.INTCTRL |= ADC_WCMP_bm; //Enable Interrupts for WCM
sei();
y=0;
while(y<4){ //metritis strofon</pre>
       p=t=z=k=0;//arxikopiisi timon
       //deksia strofi
       //deksia esthitiras
       straight_on();
      ADCO.CTRLE = 0x02; //Interrupt when RESULT > WINLT
      ADCO.CTRLA |= ADC_FREERUN_bm; //Free-Running mode enabled
      ADCO.COMMAND |= ADC STCONV bm; //Start Conversion
      TCBO.CTRLA |= TCB_CLKSEL_CLKDIV1_gc ; //timer dekia esthitira
      TCBO.CTRLA |= TCB_ENABLE_bm;
      while(z==0){ //perimer timer
       }
```

```
ADCO.CTRLA &= ~ADC ENABLE bm; //stop conversion
                     right_on();
                     TCB2.CTRLA |= TCB_CLKSEL_CLKDIV1_gc ; //ksekina timer strofis
TCB2.CTRLA |= TCB_ENABLE_bm;
                     while(k==0){//perimene timer strofis
                     }
                     right_off();
                     y--; //metritis strofis
              }
              straight_on();
              ADCO.CTRLA &= ~ADC_ENABLE_bm; //stop conversion
              ADCO.CTRLA |= ADC_ENABLE_bm; //start conversion
              t=0;
              k=0;
              //aristeri strofi
              //mprosta esthitiras
              ADCO.CTRLA &= ~ADC FREERUN bm; //Free-Running mode disabled
              ADCO.CTRLE = 0x01; //Interrupt when RESULT < WINLT
              ADCO.COMMAND |= ADC_STCONV_bm; //Start Conversion
              TCB1.CTRLA |= TCB_CLKSEL_CLKDIV1_gc; //ksekina timer mprosta esthitira
              TCB1.CTRLA |= TCB ENABLE bm;
              while(p==0){ //perimene timer
              if(t==1){ //mpeni mesa otan energopiithi to interrupt tis adc
                     left on();
                     TCB2.CTRLA |= TCB CLKSEL CLKDIV1 gc; //ksekina timer strofis
                     TCB2.CTRLA |= TCB ENABLE bm;
                     while(k==0){ //perimene timer
                     left_off();
                     y++;
              }
       }
}
void
      right_on(){
       //on
       PORTD.OUTCLR= 0b00000001; //PIN0 bm
void right_off(){
       //LED is off
       PORTD.OUT |= 0b00000001; //PIN0 bm
}
void straight_on(){
       PORTD.OUTCLR= 0b00000010; //PIN1_bm
void straight_off(){
       //LED is off
```

if(t==1){//mpeni mes stin if mono ean exei gini interrupt apo ton adc

```
PORTD.OUT |= 0b00000010; //PIN1 bm
}
void left_on(){
       //on
       PORTD.OUTCLR= 0b00000100; //PIN2_bm
void left_off(){
       //LED is off
       PORTD.OUT |= 0b00000100; //PIN2_bm
}
void all_on(){
       //on
       PORTD.OUTCLR= 0b00000001; //PIN0_bm
       //on
       PORTD.OUTCLR= 0b00000010; //PIN1 bm
       //on
       PORTD.OUTCLR= 0b00000100; //PIN2_bm
}
void all_off(){
       //LED is off
       PORTD.OUT |= 0b00000001; //PINO_bm
       //LED is off
       PORTD.OUT |= 0b00000010; //PIN1 bm
       //LED is off
       PORTD.OUT |= 0b00000100; //PIN2 bm
}
void CLOCK init (void)
{
       /* Enable writing to protected register */
       CPU CCP = CCP IOREG gc;
       /* Enable Prescaler and set Prescaler Division to 64 */
       CLKCTRL.MCLKCTRLB = CLKCTRL PDIV 64X gc | CLKCTRL PEN bm;
       /* Enable writing to protected register */
       CPU CCP = CCP_IOREG_gc;
       /* Select 32KHz Internal Ultra Low Power Oscillator (OSCULP32K) */
       CLKCTRL.MCLKCTRLA = CLKCTRL_CLKSEL_OSCULP32K_gc;
       /* Wait for system oscillator changing to finish */
       while (CLKCTRL.MCLKSTATUS & CLKCTRL_SOSC_bm)
       {
       }
}
ISR(TCB0 INT vect){
       TCB0.INTFLAGS |= TCB_CAPT_bm; /* Clear the interrupt flag */
       TCBO.CTRLA &= ~TCB ENABLE bm;
       z=1;
ISR(TCB1_INT_vect){
       TCB1.INTFLAGS |= TCB_CAPT_bm; /* Clear the interrupt flag */
       TCB1.CTRLA &= ~TCB_ENABLE_bm;
       p=1;
ISR(TCB2_INT_vect){
```

```
TCB2.INTFLAGS |= TCB_CAPT_bm; /* Clear the interrupt flag */
TCB2.CTRLA &= ~TCB_ENABLE_bm;
k=1;
}


ISR(ADC0_WCOMP_vect){
   int intflags = ADC0.INTFLAGS;
   ADC0.INTFLAGS = intflags;
   straight_off();
   t=1; //gia na mpi stin if tis strofis
   ADC0.CTRLA &= ~ADC_ENABLE_bm; //stop conversion
}
```

<u>Περιγραφή</u>

Στο πρόγραμμα μας χρησιμοποιούμε 3 χρονίστες, τον tcb0 ο οποίος μετρά μέχρι να δεχτεί τιμή ο δεξιά αισθητήρας, τον tcb1 ο οποίος μετρά μέχρι να δεχτεί τιμή ο μπροστινός αισθητήρας και tcb2 ο οποίος μετρά μέχρι να γίνει η στροφή. Επίσης χρησιμοποιούμε ένα adc ο οποίος δουλεύει ενάλλαξα single conversion και free running mode ανάλογα με τον πιο αισθητήρα θέλουμε να ελέγξουμε. Δηλώνουμε όλους τους χρονιστες, τον adc και όλα τα flags. Το πρόγραμμα που εκτελείται βρίσκεται σε μια while η οποία μετρά μέχρι το 4. Αρχικά αρχικοποιουμε τα flags p t z k με 0, ανάβουμε το LED για ευθεία κίνηση και ξεκινούμε τον δεξιό αισθητήρα adc σε free running mode με interrupt να γίνεται όταν RESULT > WINLT. Ακόλουθος ξεκινούμε τον tcb0 και περιμένουμε στην while μέχρι να τελειώσει. Αφού τελειώσει η while του tcb0 και έχει συμβεί interrupt από τον adc το πρόγραμμα θα εισέλθει στην if(t==1){ οπου είναι ο κώδικας για να στρίψει δεξιά και θα αφαιρέσει 1 από την μεταβλητή γ, εάν δεν συμβεί interrupt θα συνέχιση ευθεία. Στην συνέχεια απενεργοποιούμε τον adc για να σταματήσει το conversion και τον ξανά ενεργοποιούμε, αρχικοποιουμε τα flags και αλλάζουμε τον adc να κάνει interrupt όταν RESULT < WINLT και να τρέχει σε single conversion mode. Ακόλουθος ξεκινούμε τον tcb1 και τον περιμένουμε να τελειώσει. Παράλληλα περιμένουμε να γίνει interrupt από τον adc. Όταν τελειώσει ο tcb1 εάν έχει γίνει interrupt από τον adc τότε θα εισέλθουμε στο if οπού γίνεται η αριστερή στροφή και θα προσθέσουμε αλλιώς συνεχίζει ευθεία.

Ανάποδη λειτουργία

Διάγραμμα Ροής:



Κώδικας

```
#include <avr/io.h>
#include <util/delay.h>
#include <avr/interrupt.h>
#define T1 10
#define T2 10
int zero = 0;
int p;//gia na stamatisi i while
int z;//gia na stamatisi i while
int y=0;//metritis strofon
int x;//dixni pou na gini strofi aristera i deksia
int t;
int k;
int strofes=0;
int main(void){
       //PIN is output
       PORTD.DIR |= 0b00000001; //PIN0 bm right
       //PIN is output
       PORTD.DIR |= 0b00000010; //PIN1 bm straight
       //PIN is output
       PORTD.DIR |= 0b00000100; //PIN2 bm left
       //LED is off
       PORTD.OUT |= 0b00000001; //PINO_bm
       //LED is off
       PORTD.OUT |= 0b00000010; //PIN1_bm
       //LED is off
       PORTD.OUT |= 0b00000100; //PIN2 bm
       CLOCK init();
       //interrupt
       PORTF. PIN5CTRL |= PORT PULLUPEN bm | PORT ISC BOTHEDGES gc;
       //TIMER freerunning mode
       /* Load the Compare or Capture register with the timeout value*/
       TCB0.CCMP |= T1;
       /* Enable Capture or Timeout interrupt */
       TCB0.INTCTRL |= TCB CAPT bm;
       TCBO.CTRLB |= TCB_CNTMODE_INT_gc;
       //TIMER single convertion
       /* Load the Compare or Capture register with the timeout value*/
       TCB1.CCMP = T2;
       /* Configure TCB in Periodic Timeout mode */
       TCB1.CTRLB = TCB_CNTMODE_INT_gc;
       /* Enable Capture or Timeout interrupt */
       TCB1.INTCTRL = TCB_CAPT_bm;
       //TIMER strofis
       /* Load the Compare or Capture register with the timeout value*/
       TCB2.CCMP = T2;
       /* Configure TCB in Periodic Timeout mode */
       TCB2.CTRLB = TCB_CNTMODE_INT_gc;
       /* Enable Capture or Timeout interrupt */
       TCB2.INTCTRL = TCB_CAPT_bm;
       PORTD.DIR |= PIN1_bm; //PIN is output
       //initialize the ADC for Free-Running mode
       ADCO.CTRLA |= ADC_RESSEL_10BIT_gc; //10-bit resolution
```

```
ADCO.CTRLA |= ADC FREERUN bm; //Free-Running mode enabled
      ADCO.CTRLA |= ADC ENABLE bm; //Enable ADC
      ADCO.MUXPOS |= ADC MUXPOS AIN7 gc; //The bit //Enable Debug Mode
      ADCO.DBGCTRL |= ADC_DBGRUN_bm; //Window Comparator Mode
      ADCO.WINLT |= 10; //Set threshold
      ADCO.INTCTRL | = ADC_WCMP_bm; //Enable Interrupts for WCM
      sei();
      y=0;
      while(y<4){ // to programma tha trexi mexri na gini to y 4 dld ftasi eki pou
ksekinise
             if(x==0){ // KANONIKI LITOURGIA to x einai 0 otan den exei energopiithi
to interrupt sto portf
                    p=t=z=k=0; //arxikopiisi timon
                    //deksia strofi
                    straight_on();
                    //deksios esthitiras
                    ADCO.CTRLA |= ADC ENABLE bm; //start conversion
                    ADCO.CTRLE = 0x02; //Interrupt when RESULT > WINLT
                    ADCO.CTRLA |= ADC FREERUN bm; //Free-Running mode enabled
                    ADCO.COMMAND |= ADC_STCONV_bm; //Start Conversion
                    TCBO.CTRLA |= TCB CLKSEL CLKDIV1 gc; //timer aristerou esthitia
                    TCBO.CTRLA |= TCB ENABLE bm;
                    while(z==0){ //perimene timer
                     if(t==1){ //ean exi gini interupt apo to adc to t tha gini 1 kai
tha stripsi deksia
                           ADCO.CTRLA &= ~ADC ENABLE bm; //stop conversion
                           right on();
                           TCB2.CTRLA |= TCB CLKSEL CLKDIV1 gc; //timer strofis
                           TCB2.CTRLA |= TCB_ENABLE_bm;
                           while(k==0){ //perimene timer strofis
                           }
                           right_off();
                           y--; //kathe fora pou strifi deksia aferoume 1 apo to y
                           strofes++;
                    straight_on();
                    ADCO.CTRLA &= ~ADC_ENABLE_bm; //stop conversion
                    ADCO.CTRLA |= ADC_ENABLE_bm; //start conversion
                    p=t=z=k=0; //arxikopiisi timon
                    //aristeri strofi
                    //mprosta esthitiras
                    ADCO.CTRLA &= ~ADC_FREERUN_bm; //Free-Running mode disabled
                    ADCO.CTRLE = 0x01; //Interrupt when RESULT < WINLT
                    ADCO.COMMAND |= ADC STCONV bm; //Start Conversion
                    TCB1.CTRLA |= TCB_CLKSEL_CLKDIV1_gc; //ksekina to timer tou
mprosta esthitira
                    TCB1.CTRLA |= TCB_ENABLE bm;
                    while(p==0){ //perimene timer mprosta esthitira
                     if(t==1){ //ean exi gini interrupt apo ton adc tha gini to t 1
kai tha stripsi aristera
```

```
left on();
                            TCB2.CTRLA |= TCB CLKSEL CLKDIV1 gc; //ksekina timer
strofis
                            TCB2.CTRLA |= TCB ENABLE bm;
                            while(k==0){ //perimene timer strofis
                            left_off();
                            y++;
                            strofes++;
                     }
              }else if(x==1){ //ANAPODI LITOURGIA mpeni sto if mono ean exi
energopiithi to portf
             TCB2.CTRLA |= TCB CLKSEL CLKDIV1 gc; //ksekina timer gia ola ta fota
anixta
             TCB2.CTRLA |= TCB ENABLE bm;
             while(k==0){ //perimene timer
              }
             all off();
             while(strofes>0){ //otan oi strofes einai mikroteres i ises tou 0 exei
ftasi stin arxiki tou thesi
                     p=t=z=k=0; //arxikopiisi timon
                    ADCO.CTRLA &= ~ADC ENABLE bm; //stop conversion
                    //deksia strofi
                     //mprosta esthitiras
                    ADCO.CTRLA |= ADC ENABLE bm; //start conversion
                    ADCO.CTRLA &= ~ADC FREERUN bm; //Free-Running mode disabled
                    ADCO.CTRLE = 0x01; //Interrupt when RESULT < WINLT
                    ADCO.COMMAND |= ADC STCONV bm; //Start Conversion
                    TCB1.CTRLA |= TCB CLKSEL CLKDIV1 gc; //ksekina timer
                     TCB1.CTRLA |= TCB ENABLE bm;
                    while(p==0){//perimene timer
                     if(t==1){ // mpeni ean exei energopiithi interrupt apo ton adc
                            right_on();
                            TCB2.CTRLA |= TCB_CLKSEL_CLKDIV1_gc ; //ksekina timer
                            TCB2.CTRLA = TCB_ENABLE_bm;
                            while(k==0){
                            right off();
                            strofes--;
                    ADCO.CTRLA &= ~ADC_ENABLE_bm; //stop conversion
                     p=t=z=k=0; //arxikopiisi timon
                     //aristeri strofi
                     straight_on();
                     ADCO.CTRLA |= ADC_ENABLE_bm; //start conversion
                    ADCO.CTRLE = 0x02; //Interrupt when RESULT > WINLT
                    ADCO.CTRLA |= ADC_FREERUN_bm; //Free-Running mode enabled
                    ADCO.COMMAND |= ADC_STCONV_bm; //Start Conversion
```

```
TCBO.CTRLA |= TCB CLKSEL CLKDIV1 gc; //ksekina timer
                     TCBO.CTRLA |= TCB ENABLE bm;
                     while(z==0){ //perimene timer
                     if(t==1){ //mpeni mono ean exei energopiithi to timer apo ton adc
                            ADCO.CTRLA &= ~ADC_ENABLE_bm; //stop conversion
                            left_on();
                            TCB2.CTRLA |= TCB_CLKSEL_CLKDIV1_gc; //ksekina timer
                            TCB2.CTRLA |= TCB_ENABLE_bm;
                            while(k==0){
                            left_off();
                            strofes--;
                     straight_on();
              }
       }
       }
}
void
      right_on(){
       //on
       PORTD.OUTCLR= 0b00000001; //PIN0 bm
}
void right_off(){
       //LED is off
       PORTD.OUT |= 0b00000001; //PIN0 bm
}
void straight_on(){
       PORTD.OUTCLR= 0b00000010; //PIN1_bm
void straight_off(){
       //LED is off
       PORTD.OUT |= 0b00000010; //PIN1_bm
}
void left_on(){
       //on
       PORTD.OUTCLR= 0b00000100; //PIN2 bm
void left_off(){
       //LED is off
       PORTD.OUT |= 0b00000100; //PIN2 bm
}
void all_on(){
       PORTD.OUTCLR= 0b00000001; //PIN0_bm
       PORTD.OUTCLR= 0b00000010; //PIN1_bm
       //on
```

```
PORTD.OUTCLR= 0b00000100; //PIN2 bm
}
void all_off(){
       //LED is off
       PORTD.OUT |= 0b00000001; //PINO_bm
       //LED is off
       PORTD.OUT |= 0b00000010; //PIN1_bm
       //LED is off
       PORTD.OUT |= 0b00000100; //PIN2_bm
}
void CLOCK_init (void)
{
       /* Enable writing to protected register */
       CPU_CCP = CCP_IOREG_gc;
       /* Enable Prescaler and set Prescaler Division to 64 */
       CLKCTRL.MCLKCTRLB = CLKCTRL_PDIV_64X_gc | CLKCTRL_PEN_bm;
       /* Enable writing to protected register */
       CPU CCP = CCP_IOREG_gc;
       /* Select 32KHz Internal Ultra Low Power Oscillator (OSCULP32K) */
       CLKCTRL.MCLKCTRLA = CLKCTRL_CLKSEL_OSCULP32K_gc;
       /* Wait for system oscillator changing to finish */
       while (CLKCTRL.MCLKSTATUS & CLKCTRL_SOSC_bm)
       }
}
ISR(TCB0 INT vect){
       TCBO.INTFLAGS |= TCB CAPT bm; /* Clear the interrupt flag */
       TCBO.CTRLA &= ~TCB ENABLE bm;
       z=1;
ISR(TCB1 INT vect){
       TCB1.INTFLAGS |= TCB_CAPT_bm; /* Clear the interrupt flag */
       TCB1.CTRLA &= ~TCB_ENABLE_bm;
       p=1;
ISR(TCB2_INT_vect){
       TCB2.INTFLAGS |= TCB_CAPT_bm; /* Clear the interrupt flag */
       TCB2.CTRLA &= ~TCB_ENABLE_bm;
       k=1;
ISR(PORTF PORT vect){
       //clear the interrupt flag
       int z = PORTF.INTFLAGS;
       PORTF.INTFLAGS=z;
       all_on();
       x=1; //gia na mpi sto if tis anapodis litourgias
       k=0;
       ADCO.CTRLA &= ~ADC_ENABLE_bm; //stop conversion
}
ISR(ADC0_WCOMP_vect){
       int intflags = ADCO.INTFLAGS;
       ADCO.INTFLAGS = intflags;
       straight_off();
```

```
t=1; //gia na mpi sto if tis strofis
ADCO.CTRLA &= ~ADC_ENABLE_bm; //stop conversion
}
```

Περιγραφή

Η ανάποδη λειτουργία ενεργοποιείται από interrupt στο PORTF. Η κανονική λειτουργία βρίσκεται στο if(x==0){ και η ανάποδη στο }else if(x==1){. Όταν γίνει 1 η μεταβλητή x από το interrupt στο PORTF τότε ενεργοποιείται. Επίσης κρατάμε μια μεταβλητή με όνομα strofes οπού στην κανονική λειτουργία κάθε φορά που κάνουμε μια στροφή προσθέτουμε 1 σε αυτή ώστε στην ανάποδη να γνωρίζουμε πόσες στροφές θα κάνουμε.