TECHNICAL INSPECTION REPORT — VALVE PRV-102

Equipment ID: PRV-102 | **Location:** Substation Unit 4 | **Inspector:** Senior Engineer

Inspection Findings:
Visual inspection of Pressure Relief Valve PRV-102 indicated active pressure reading at 168.4 PSI. Gasket seal shows moderate thermal degradation and surface oxidation around flange bolts. Vibration sensor recorded 5.8 mm/s velocity.

Recommendation:
Refer to SOP-IND-402 Section 4.2 for overhaul threshold verification. Generate an emergency maintenance approval note and excel risk matrix.