

Harmonic Sum waveform in part 2:




Part C:

RTL viewer:



floor-plan:



Timing:

TimeQuest Timing Analyzer Summary

Quartus II Version Version 13.0.1 Build 232 06/12/2013 Service Pack 1 SJ Web Edition

Revision Name CA4

Device Family Cyclone II

Device Name EP2C5AF256A7

Timing Models Final

Delay Model Combined Rise/Fall Delays Unavailable

Flow Summary

Flow Status Successful - Fri Dec 20 06:10:28 2024

Quartus II 64-Bit Version 13.0.1 Build 232 06/12/2013 SP 1 SJ Web Edition

Revision Name CA4
Top-level Entity Name CA4
Family Cyclone II
Device EP2C5AF256A7

Timing Models Final

Total logic elements 68 / 4,608 (1 %)Total combinational functions 50 / 4,608 (1 %)Dedicated logic registers 47 / 4,608 (1 %)

Total registers 47

Total pins 25 / 158 (16 %)

Total virtual pins 0

Total memory bits 0 / 119,808 (0 %)

Embedded Multiplier 9-bit elements 0 / 26 (0 %)Total PLLs 0 / 2 (0 %)