

Hardware Assessment Report

Ankya Advisors

Scan Date: May 29, 2026 at 06:50 AM



Estimated Lifespan: 2-3 years

System Information

Hostname: DESKTOP-CSIQ964

OS: Microsoft Windows 11 Pro 11

CPU: Intel(R) Core(TM) i5-8365U CPU @ 1.60GHz

RAM: 23.75 GB

Overall System Health: 62/100 (Grade B)

Estimated Remaining Lifespan: 2-3 years

Critical Issues Detected:

- CPU: C (55/100) — Plan replacement within 1 year
- GPU: C (56/100) — Plan replacement within 1 year

Component Health Summary

Component	Score	Grade	Status
Intel(R) Core(TM) i5-8365U CPU @ 1.	55	C	Plan replacement within 1 year
23.75 GB (2 modules)	84	A	No action needed
INTEL SSDPEKKF512G7	63	B	No action needed
Intel(R) UHD Graphics 620	56	C	Plan replacement within 1 year
LENOVO 20N3S4WQ00	77	B	No action needed
Internal Battery	63	B	No action needed

CPU — Intel(R) Core(TM) i5-8365U CPU @ 1.60GHz

Grade C (55/100)

Part/Serial: BFEBFBFF000806EC Status: ■ MONITOR

→ Reapply thermal paste to reduce operating temperatures

→ Clean CPU heatsink and fan to prevent thermal throttling

RAM — 23.75 GB (2 modules)

Grade A (84/100)

Part/Serial: M471A2G44AM0-CTD Status: ■ OK

→ Run MemTest86 to verify memory stability and rule out bad sectors

→ Ensure RAM is configured in dual-channel mode for optimal bandwidth

Storage — INTEL SSDPEKKF512G7

Grade B (63/100)

Part/Serial: 0000_0000_0100_0000_E4D2_5C3F_1227_... Status: ■ OK

→ Enable TRIM support in the operating system for optimal endurance

→ Avoid filling the SSD beyond 80% capacity to extend lifespan

GPU — Intel(R) UHD Graphics 620

Grade C (56/100)

Part/Serial: Intel(R) UHD Graphics Family Status: ■ MONITOR

→ Integrated GPU is soldered to the CPU/motherboard — cannot be upgraded separately

→ To improve GPU performance, a motherboard + CPU replacement is required

Motherboard — LENOVO 20N3S4WQ00

Grade B (77/100)

Part/Serial: L1HF98R023V Status: ■ OK

→ Update BIOS firmware to the latest version for compatibility fixes

→ Visually inspect capacitors for bulging or leaking (sign of failure)

Battery — Internal Battery




Grade B (63/100)

Part/Serial: N/A Status: ■ OK

→ Calibrate the battery every 3 months by fully charging and discharging

→ Keep charge levels between 20-80% for daily use to extend cycle life

Overall Benchmark Score: 0/100



Category	Status	Bottlenecks
Web Development	Fully Supported	None
Desktop Development	Minimum Requirements Only	Recommended 6 CPU cores (has 4)
Mobile Development	Minimum Requirements Only	Recommended 6 CPU cores (has 4); Recommended 2048MB VRAM ...
Databases	Fully Supported	None
Virtualization	Minimum Requirements Only	Recommended 32GB RAM (has 23.75GB); Recommended 8 CPU cor...
AI & Data Science	Not Supported	Recommended 32GB RAM (has 23.75GB); Recommended 8 CPU cor...
CAD & Engineering	Not Supported	Recommended 32GB RAM (has 23.75GB); Recommended 8 CPU cor...
Game Development	Not Supported	Recommended 32GB RAM (has 23.75GB); Recommended 8 CPU cor...
Video Editing	Not Supported	Recommended 32GB RAM (has 23.75GB); Recommended 8 CPU cor...
Basic Office & Browsing	Fully Supported	None

Total Recommendations: 12

- [HIGH] System
Recommended 32GB RAM (has 23.75GB)
- [HIGH] System
Recommended 8 CPU cores (has 4)
- [HIGH] System
Needs 4096MB VRAM (has 1024.0MB)
- [HIGH] System
Needs 2048MB VRAM (has 1024.0MB)

Total Estimated Upgrade Cost

Rs. 18,000 INR (~\$200 USD)

Prices as of 2026-04-07 | Sources: Amazon.in, MDComputers, PrimeABGB

Priority	Component	Current	Recommended Upgrade	■ INR	\$ USD
MONITOR	CPU	Intel(R) Core(TM) i5-8	Intel i5 (12th/13th Gen)	Rs. 18,000	\$200
			TOTAL	Rs. 18,000	\$200

Upgrade Justification

- CPU: Upgrade from 4-core/1896.0MHz to modern mid-range CPU
Source: MDComputers (<https://mdcomputers.in/processors?brand=intel&tier=i5>)

* Prices are approximate and may vary. Consult your vendor for exact quotes. Currency rate: 1 USD = ■92.0