

Hardware Assessment Report

Gen Mot Coils

Scan Date: May 28, 2026 at 07:09 AM



Estimated Lifespan: 1-2 years

System Information

Hostname: HR

OS: Microsoft Windows 11 Pro 11

CPU: Intel(R) Core(TM) i3-10100 CPU @ 3.60GHz

RAM: 7.75 GB

Overall System Health: 51/100 (Grade C)

Estimated Remaining Lifespan: 1-2 years

Critical Issues Detected:

- GPU: C (44/100) — Plan replacement within 1 year
- Storage: C (48/100) — Plan replacement within 1 year
- Motherboard: C (50/100) — Plan replacement within 1 year

Component Health Summary

Component	Score	Grade	Status
Intel(R) Core(TM) i3-10100 CPU @ 3.	61	B	No action needed
7.75 GB (2 modules)	77	B	No action needed
ST1000DM010-2EP102	48	C	Plan replacement within 1 year
Intel(R) UHD Graphics 630	44	C	Plan replacement within 1 year
Dell Inc. 0X9X1W	50	C	Plan replacement within 1 year

Grade B (61/100)

Part/Serial: BFEBFBFF000A0653

Status: ■ OK

- Reapply thermal paste to reduce operating temperatures
- Clean CPU heatsink and fan to prevent thermal throttling

Grade B (77/100)

Part/Serial: 4ATF51264AZ-3G2J1

Status: ■ OK

- Run MemTest86 to verify memory stability and rule out bad sectors
- Ensure RAM is configured in dual-channel mode for optimal bandwidth

Grade C (48/100)

Part/Serial: ZN1OL9TB

Status: ■ MONITOR

- Defragment the drive regularly to maintain read/write performance
- Monitor S.M.A.R.T. values weekly to detect early signs of failure

Grade C (44/100)

Part/Serial: Intel(R) UHD Graphics Family

Status: ■ MONITOR

- Integrated GPU is soldered to the CPU/motherboard — cannot be upgraded separately
- To improve GPU performance, a motherboard + CPU replacement is required




Grade C (50/100)

Part/Serial: /H2PF1G3/CNFCW0015F02JC/

Status: ■ MONITOR

- Update BIOS firmware to the latest version for compatibility fixes
- Visually inspect capacitors for bulging or leaking (sign of failure)

Overall Benchmark Score: 0/100



Category	Status	Bottlenecks
Web Development	Minimum Requirements Only	Recommended 8GB RAM (has 7.75GB)
Desktop Development	Not Supported	Needs 8GB RAM (has 7.75GB); Recommended 6 CPU cores (has 4)
Mobile Development	Not Supported	Needs 8GB RAM (has 7.75GB); Recommended 6 CPU cores (has ...
Databases	Minimum Requirements Only	Recommended 16GB RAM (has 7.75GB)
Virtualization	Not Supported	Needs 8GB RAM (has 7.75GB); Recommended 8 CPU cores (has 4)
AI & Data Science	Not Supported	Needs 8GB RAM (has 7.75GB); Recommended 8 CPU cores (has ...
CAD & Engineering	Not Supported	Needs 8GB RAM (has 7.75GB); Recommended 8 CPU cores (has ...
Game Development	Not Supported	Needs 8GB RAM (has 7.75GB); Recommended 8 CPU cores (has ...
Video Editing	Not Supported	Needs 8GB RAM (has 7.75GB); Recommended 8 CPU cores (has ...
Basic Office & Browsing	Minimum Requirements Only	Recommended 8GB RAM (has 7.75GB)

Total Recommendations: 19

- [HIGH] System
Needs 8GB RAM (has 7.75GB)
- [HIGH] System
Recommended 6 CPU cores (has 4)
- [HIGH] System
Recommended 2048MB VRAM (has 1024.0MB)
- [HIGH] System
Recommended 8 CPU cores (has 4)
- [HIGH] System
Needs 4096MB VRAM (has 1024.0MB)
- [HIGH] System
Needs 2048MB VRAM (has 1024.0MB)

Total Estimated Upgrade Cost

Rs. 9,700 INR (~\$106 USD)

Prices as of 2026-04-07 | Sources: Amazon.in, MDComputers, PrimeABGB

Priority	Component	Current	Recommended Upgrade	■ INR	\$ USD
OK	RAM	7.75GB DDR4	DDR4 8GB 2666MHz	Rs. 2,200	\$26
✓ GOOD	Storage	931.51GB HDD (ST1000DM	1TB SATA SSD	Rs. 7,500	\$80
			TOTAL	Rs. 9,700	\$106

Upgrade Justification

- RAM: Upgrade from 7.75GB to 8GB DDR4
Source: Amazon.in (<https://www.amazon.in/s?k=ddr4+8gb+ram>)
- Storage: Replace 931.51GB HDD with 1TB SATA SSD (3-5x speed boost)
Source: Amazon.in (<https://www.amazon.in/s?k=1tb+ssd>)

* Prices are approximate and may vary. Consult your vendor for exact quotes. Currency rate: 1 USD = ■92.0