

Hardware Assessment Report

Gen Mot Coils

Scan Date: May 27, 2026 at 08:03 AM



Estimated Lifespan: 1-2 years

System Information

Hostname: MAHESHak

OS: Microsoft Windows 10 Home Single Language 10

CPU: Intel(R) Core(TM) i3-6100T CPU @ 3.20GHz

RAM: 7.86 GB

Overall System Health: 41/100 (Grade C)

Estimated Remaining Lifespan: 1-2 years

Critical Issues Detected:

- GPU: D (32/100) — Replace soon, degraded performance
- Motherboard: D (33/100) — Replace soon, degraded performance
- Storage: C (48/100) — Plan replacement within 1 year

Component Health Summary

Component	Score	Grade	Status
Intel(R) Core(TM) i3-6100T CPU @ 3.	55	C	Plan replacement within 1 year
7.86 GB (2 modules)	67	B	No action needed
WDC WD10EZEX-60WN4A0	48	C	Plan replacement within 1 year
Intel(R) HD Graphics 530	32	D	Replace soon, degraded performance
HP 81B4	33	D	Replace soon, degraded performance

CPU — Intel(R) Core(TM) i3-6100T CPU @ 3.20GHz

Grade C (55/100)

Part/Serial: BFEBFBFF000506E3 Status: ■ MONITOR

→ Reapply thermal paste to reduce operating temperatures

→ Clean CPU heatsink and fan to prevent thermal throttling

RAM — 7.86 GB (2 modules)

Grade B (67/100)

Part/Serial: HMA451U6AFR8N-TF Status: ■ OK

→ Run MemTest86 to verify memory stability and rule out bad sectors

→ Ensure RAM is configured in dual-channel mode for optimal bandwidth

Storage — WDC WD10EZEX-60WN4A0

Grade C (48/100)

Part/Serial: WD-WCC6Y0KNVZD7 Status: ■ MONITOR

→ Defragment the drive regularly to maintain read/write performance

→ Monitor S.M.A.R.T. values weekly to detect early signs of failure

GPU — Intel(R) HD Graphics 530

Grade D (32/100)

Part/Serial: Intel(R) HD Graphics Family Status: ■ REPLACE_SOON

→ Integrated GPU is soldered to the CPU/motherboard — cannot be upgraded separately

→ To improve GPU performance, a motherboard + CPU replacement is required

Motherboard — HP 81B4




Grade D (33/100)

Part/Serial: PFPSK0DWJ40BO8 Status: ■ REPLACE_SOON

→ Update BIOS firmware to the latest version for compatibility fixes

→ Visually inspect capacitors for bulging or leaking (sign of failure)

Overall Benchmark Score: 0/100



Category	Status	Bottlenecks
Web Development	Minimum Requirements Only	Recommended 8GB RAM (has 7.86GB); Recommended 4 CPU cores...
Desktop Development	Not Supported	Needs 8GB RAM (has 7.86GB); Needs 4 CPU cores (has 2)
Mobile Development	Not Supported	Needs 8GB RAM (has 7.86GB); Needs 4 CPU cores (has 2); Re...
Databases	Minimum Requirements Only	Recommended 16GB RAM (has 7.86GB); Recommended 4 CPU core...
Virtualization	Not Supported	Needs 8GB RAM (has 7.86GB); Needs 4 CPU cores (has 2)
AI & Data Science	Not Supported	Needs 8GB RAM (has 7.86GB); Needs 4 CPU cores (has 2); Ne...
CAD & Engineering	Not Supported	Needs 8GB RAM (has 7.86GB); Needs 4 CPU cores (has 2); Ne...
Game Development	Not Supported	Needs 8GB RAM (has 7.86GB); Needs 4 CPU cores (has 2); Ne...
Video Editing	Not Supported	Needs 8GB RAM (has 7.86GB); Needs 4 CPU cores (has 2); Ne...
Basic Office & Browsing	Minimum Requirements Only	Recommended 8GB RAM (has 7.86GB); Recommended 4 CPU cores...

Total Recommendations: 21

- [MEDIUM] GPU
Replace soon, degraded performance — INTEGRATED GPU: Motherboard + CPU replacement required. Alternatively, add a discrete PC
- [MEDIUM] Motherboard
Replace soon, degraded performance
- [HIGH] System
Needs 8GB RAM (has 7.86GB)
- [HIGH] System
Needs 4 CPU cores (has 2)
- [HIGH] System
Recommended 2048MB VRAM (has 1024.0MB)
- [HIGH] System
Needs 4096MB VRAM (has 1024.0MB)
- [HIGH] System
Needs 2048MB VRAM (has 1024.0MB)

Total Estimated Upgrade Cost

Rs. 33,700 INR (~\$376 USD)

Prices as of 2026-04-07 | Sources: Amazon.in, MDComputers, PrimeABGB

Priority	Component	Current	Recommended Upgrade	■ INR	\$ USD
OK	RAM	7.86GB DDR4	DDR4 8GB 2666MHz	Rs. 2,200	\$26
✓ GOOD	Storage	931.51GB HDD (WDC WD10	1TB SATA SSD	Rs. 7,500	\$80
MONITOR	CPU	Intel(R) Core(TM) i3-6	Intel i5 (12th/13th Gen)	Rs. 18,000	\$200
REPLACE_SOON	Motherboard	HP 81B4 (BIOS: 9.8yr o	H610/A520 Budget Motherbo	Rs. 6,000	\$70
			TOTAL	Rs. 33,700	\$376

Upgrade Justification

- RAM: Upgrade from 7.86GB to 8GB DDR4
Source: Amazon.in (<https://www.amazon.in/s?k=ddr4+8gb+ram>)
- Storage: Replace 931.51GB HDD with 1TB SATA SSD (3-5x speed boost)
Source: Amazon.in (<https://www.amazon.in/s?k=1tb+ssd>)
- CPU: Upgrade from 2-core/3192.0MHz to modern mid-range CPU
Source: MDComputers (<https://mdcomputers.in/processors?brand=intel&tier=i5>)
- Motherboard: BIOS is 9.8 years old — motherboard nearing end of life
Source: MDComputers (<https://mdcomputers.in/motherboards?chipset=h610>)

* Prices are approximate and may vary. Consult your vendor for exact quotes. Currency rate: 1 USD = ■92.0