

Hardware Assessment Report

Jaya rani

Scan Date: June 12, 2026 at 04:14 AM



Estimated Lifespan: 6-12 months

System Information

Hostname: JCS-Office-02

OS: Microsoft Windows 10 Pro 10

CPU: Intel(R) Core(TM) i3-9100F CPU @ 3.60GHz

RAM: 3.95 GB

Overall System Health: 35/100 (Grade D)

Estimated Remaining Lifespan: 6-12 months

Critical Issues Detected:

- GPU: F (18/100) — Immediate replacement required
- Motherboard: D (38/100) — Replace soon, degraded performance
- Storage: C (50/100) — Plan replacement within 1 year

Component Health Summary

Component	Score	Grade	Status
Intel(R) Core(TM) i3-9100F CPU @ 3.	61	B	No action needed
3.95 GB (1 modules)	64	B	No action needed
ST1000DM010-2EP102	50	C	Plan replacement within 1 year
NVIDIA GeForce GT 710	18	F	Immediate replacement required
ASUSTeK COMPUTER INC. PRIME H310M-C	38	D	Replace soon, degraded performance

CPU — Intel(R) Core(TM) i3-9100F CPU @ 3.60GHz

Grade B (61/100)

Part/Serial: BFEBFBFF000906EBStatus: ■ OK

→ Reapply thermal paste to reduce operating temperatures

→ Clean CPU heatsink and fan to prevent thermal throttling

RAM — 3.95 GB (1 modules)

Grade B (64/100)

Part/Serial: 0Status: ■ OK

→ Run MemTest86 to verify memory stability and rule out bad sectors

→ Ensure RAM is configured in dual-channel mode for optimal bandwidth

Storage — ST1000DM010-2EP102

Grade C (50/100)

Part/Serial: W9AFQTNNStatus: ■ MONITOR

→ Defragment the drive regularly to maintain read/write performance

→ Monitor S.M.A.R.T. values weekly to detect early signs of failure

GPU — NVIDIA GeForce GT 710

Grade F (18/100)

Part/Serial: GeForce GT 710Status: ■ REPLACE_NOW

→ Update GPU drivers to the latest stable version

→ Clean GPU fans and heatsink to prevent thermal throttling

Motherboard — ASUSTeK COMPUTER INC. PRIME H310M-CS R2.




Grade D (38/100)

Part/Serial: 190550414601625Status: ■ REPLACE_SOON

→ Update BIOS firmware to the latest version for compatibility fixes

→ Visually inspect capacitors for bulging or leaking (sign of failure)

Overall Benchmark Score: 0/100



Category	Status	Bottlenecks
Web Development	Not Supported	Needs 4GB RAM (has 3.95GB)
Desktop Development	Not Supported	Needs 8GB RAM (has 3.95GB); Recommended 6 CPU cores (has 4)
Mobile Development	Not Supported	Needs 8GB RAM (has 3.95GB); Recommended 6 CPU cores (has ...
Databases	Not Supported	Needs 4GB RAM (has 3.95GB)
Virtualization	Not Supported	Needs 8GB RAM (has 3.95GB); Recommended 8 CPU cores (has 4)
AI & Data Science	Not Supported	Needs 8GB RAM (has 3.95GB); Recommended 8 CPU cores (has ...
CAD & Engineering	Not Supported	Needs 8GB RAM (has 3.95GB); Recommended 8 CPU cores (has ...
Game Development	Not Supported	Needs 8GB RAM (has 3.95GB); Recommended 8 CPU cores (has ...
Video Editing	Not Supported	Needs 8GB RAM (has 3.95GB); Recommended 8 CPU cores (has ...
Basic Office & Browsing	Not Supported	Needs 4GB RAM (has 3.95GB)

Total Recommendations: 24

- [HIGH] GPU
Immediate replacement required
- [MEDIUM] Motherboard
Replace soon, degraded performance
- [HIGH] System
Needs 4GB RAM (has 3.95GB)
- [HIGH] System
Needs 8GB RAM (has 3.95GB)
- [HIGH] System
Recommended 6 CPU cores (has 4)
- [HIGH] System
Requires dedicated GPU with 512MB VRAM
- [HIGH] System
Recommended 8 CPU cores (has 4)
- [HIGH] System
Requires dedicated GPU with 4096MB VRAM
- [HIGH] System
Requires dedicated GPU with 2048MB VRAM

Total Estimated Upgrade Cost

Rs. 15,700 INR (~\$176 USD)

Prices as of 2026-04-07 | Sources: Amazon.in, MDComputers, PrimeABGB

Priority	Component	Current	Recommended Upgrade	■ INR	\$ USD
OK	RAM	3.95GB DDR4	DDR4 8GB 2666MHz	Rs. 2,200	\$26
✓ GOOD	Storage	931.51GB HDD (ST1000DM	1TB SATA SSD	Rs. 7,500	\$80
REPLACE_SOON	Motherboard	ASUSTeK COMPUTER INC.	H610/A520 Budget Motherbo	Rs. 6,000	\$70
			TOTAL	Rs. 15,700	\$176

Upgrade Justification

- RAM: Upgrade from 3.95GB to 8GB DDR4
Source: Amazon.in (<https://www.amazon.in/s?k=ddr4+8gb+ram>)
- Storage: Replace 931.51GB HDD with 1TB SATA SSD (3-5x speed boost)
Source: Amazon.in (<https://www.amazon.in/s?k=1tb+ssd>)
- Motherboard: BIOS is 7.2 years old — motherboard nearing end of life
Source: MDComputers (<https://mdcomputers.in/motherboards?chipset=h610>)

* Prices are approximate and may vary. Consult your vendor for exact quotes. Currency rate: 1 USD = ■92.0