ROMHEX14 CALIBRATION PACKAGE CERTIFICATE

Stage 1 Remap + EGR OFF + IMMO Bypass | Stage 1 + EGR OFF + IMMO Bypass (Chabi Tellovin)

03_STAGE1_EGR_IMMO_OFF

1. VEHICLE PROFILE

Motor Chanchin

MODEL	VIN	ECU TYPE	BOSCH SW
Mahindra Pik-Up BS4 4WD	MA1ZC4TBKK1A11163	Bosch EDC17C55	1037560611

2. CALIBRATION TARGETS

Thahrui & Map Hlutna

Metric	Factory Value	Package Target	Net Gain
Engine Power	70 HP @ 3,200 RPM	**95 HP**	+25 HP (+35%)
Engine Torque	200 Nm @ 1,800	**260 Nm**	+60 Nm (+30%)
Fuel Limit (IQ)	43.54 mg/hub	**53.5 mg/hub**	+10.0 mg/hub
Boost Target	2,200 mbar	**2320 mbar**	+120 mbar
Rail Pressure	1,550 bar	**1600 bar**	+50 bar

3. DTC & SECURITY MATRIX

Fault Code & Security Thliarna

Code / Identifier	Subsystem	Address	Status
P0401	EGR Flow Insufficient	0x10E7D2	DEACTIVATED (00 00)
P0405	EGR Sensor A Low Input	0x10E7D4	DEACTIVATED (00 00)
P0513	Incorrect Immobilizer Key	0x10E834	DEACTIVATED (00 00)
P0633	Immobilizer Key Not Programmed	0x10E886	DEACTIVATED (00 00)
EEPROM Security	Key Tokens (0x1378 & 0x1478)	EEPROM: 0x1378/1478	BYPASS (00 00)
Lock Penalty	Lockout Timer Countdown	EEPROM: 0x130E/140E	0x00 (CLEARED)

4. BINARY FILES & INTEGRITY

File Hlutna & Checksum

Type	Filename	SHA-256 Hash
Flash (2 MB)	Mahindra_PikUp_BS4_Stage1_EGR_IMMO_OFF_Flash.bin	`827B46E4E2A532B97766B6E8E4BBF393F1F635692F62EF79E409539BFBECD5EE`
EEPROM (64 KB)	Mahindra_PikUp_BS4_IMMO_OFF_EEPROM.bin	`09CD990A3C39462FD31A0E37B671A0892FF3AB6F6D88528338611522FF9F9550`

5. INSTRUCTIONS & ADVISORY

Hriattur Pawimawh Te

CHECKSUM PROTOCOL: Bosch EDC17C55 requires Bench Flasher auto-checksum calculation on write (PCMFlash Mod 71 / Foxflash / KT200 / KTAG automatically correct CRC32 on load).
IMMO OFF ADVISORY (MIZO): Flash zawhah steering column bula Immobilizer Box connector kha phawi (unplug) hmak tur a ni. Starter a vir loh chuan starter relay terminal 50 kha direct rawh.