ROMHEX14 CALIBRATION PACKAGE CERTIFICATE

Factory Stock Power + IMMO Bypass | Stock Power + Chabi (IMMO) Bypass Ringawt

04_STOCK_IMMO_OFF_ONLY

1. VEHICLE PROFILE

Motor Chanchin

MODEL	VIN	ECU TYPE	BOSCH SW
Mahindra Pik-Up BS4 4WD	MA1ZC4TBKK1A11163	Bosch EDC17C55	1037560611

2. CALIBRATION TARGETS

Thahrui & Map Hlutna

Metric	Factory Value	Package Target	Net Gain
Engine Power	70 HP @ 3,200 RPM	**70 HP**	Stock Baseline
Engine Torque	200 Nm @ 1,800	**200 Nm**	Stock Baseline
Fuel Limit (IQ)	43.54 mg/hub	**43.54 mg/hub**	Stock Baseline
Boost Target	2,200 mbar	**2200 mbar**	Stock Baseline
Rail Pressure	1,550 bar	**1550 bar**	Stock Baseline

3. DTC & SECURITY MATRIX

Fault Code & Security Thliarna

Code / Identifier	Subsystem	Address	Status
P0513	Incorrect Immobilizer Key	0x10E834	**DEACTIVATED (00 00)**
P0633	Immobilizer Key Not Programmed	0x10E886	**DEACTIVATED (00 00)**
EEPROM Security	Key Tokens (0x1378 & 0x1478)	EEPROM: 0x1378/1478	**BYPASS (00 00)**
Lock Penalty	Lockout Timer Countdown	EEPROM: 0x130E/140E	**0x00 (CLEARED)**

4. BINARY FILES & INTEGRITY

File Hlutna & Checksum

Type	Filename	SHA-256 Hash
Flash (2 MB)	Mahindra_PikUp_BS4_Stock_IMMO_OFF_Only_Flash.bin	`CEA0D0ED87846EF41B4109074F2D5BF1E84D2FE577089822AB82CCCB670A57D3`
EEPROM (64 KB)	Mahindra_PikUp_BS4_IMMO_OFF_EEPROM.bin	`09CD990A3C39462FD31A0E37B671A0892FF3AB6F6D88528338611522FF9F9550`

5. INSTRUCTIONS & ADVISORY

Hriattur Pawimawh Te

CHECKSUM PROTOCOL: Bosch EDC17C55 requires Bench Flasher auto-checksum calculation on write (PCMFlash Mod 71 / Foxflash / KT200 / KTAG automatically correct CRC32 on load).
IMMO OFF ADVISORY (MIZO): Flash zawhah steering column bula Immobilizer Box connector kha phawi (unplug) hmak tur a ni. Starter a vir loh chuan starter relay terminal 50 kha direct rawh.