

MD Decomposition stiffens the SAW



DFT Stiff α' enters the unallowed range



Decomposition → stiffer δ-ferrite ($C' \uparrow$) → higher SAW frequency → non-destructive sign of embrittlement