

PulseSync Medical - Cardiac Device Services

Patient: Mark Smith	Patient ID: PSM491002	Date: 15-02-2026
Document: Interrogation Report (Urgent – Critical Status)		

Device & Lead Overview

Manufacturer / Model	PulseSync DuoRate DR-220
Implant Date	21-06-2025
Mode	DDD 60–130 bpm
Battery Status	Critical — service recommended; ERI/near-EOL indicated
Atrial Lead	P-wave 3.0 mV; Threshold 0.7 V @ 0.4 ms; Impedance 540 Ω
Ventricular Lead	R-wave 9.6 mV; Threshold 0.8 V @ 0.4 ms; Impedance 610 Ω

Event Summary

Atrial High Rate Episodes	0
Ventricular High Rate Episodes	0
Mode Switches	1 brief episode (< 10 seconds)
Pacing Percent (A / V)	A: 28% V: 96%

Remote Monitoring & Transmission Status

Recent remote transmissions are **delayed** and **intermittent**. Connectivity issues with missed scheduled uploads over the last 14 days. Attempt manual transmission; if unsuccessful, arrange in-clinic device check immediately.

Programming Changes

No programming changes performed today due to battery status (critical). Outputs and sensing remain safe; proceed to generator assessment.

Assessment & Plan

Battery / Hardware	Device flagged as Critical (ERI/near-EOL). Expedite in-clinic evaluation; discuss generator replacement timing.
Remote Monitoring	Resolve connectivity; attempt manual transmission before leaving clinic. Verify home monitor power and placement.
Follow-up	Urgent device clinic appointment within 1–2 weeks or sooner if symptoms occur (syncope, dizziness, palpitations).