

	ETHIOPIAN AIRLINES ENTERPRISE FLIGHT OPERATIONS TRAINING BULLETIN	BULLETIN
		Ref: FT/BUL/004/2025
	Date: December 18, 2025	
To: All Pilots		

Subject: Mandatory VOR Availability During RNP AR Operations

When conducting an RNP AR approach, flight crew must ensure that the associated VOR is operational before commencing the approach.

IMPORTANT REQUIREMENT

The availability of the associated VOR is mandatory for RNP AR operations. In the event of an FMC failure, or if RNP AR capability is lost or downgraded, the missed approach procedure cannot be flown using RNP AR guidance.

MISSED APPROACH CONTINGENCY

If RNP AR capability is lost or an FMC failure occurs during the approach, the published missed approach procedure shall be flown using the associated VOR.

In case the VOR is unserviceable, prior ATC clearance must be obtained confirming that radar vectors will be provided to safely execute the missed approach.

FLIGHT CREW ACTIONS

Before commencing an RNP AR approach, flight crew shall:

Confirm that the required VOR is serviceable and available.


Review and clearly understand the published missed approach procedure.

Ensure that ATC contingency arrangements, including the provision of radar vectors, are clearly understood if the VOR becomes unavailable.

Strict adherence to this requirement is mandatory to ensure safe and compliant RNP AR operations.

Regards,




Flight Training & Standards